

**OWNER:** AEROLINEAS EJECUTIVAS, S.A. DE C.V.  
**ADDRESS:** AEROPUERTO INTERNACIONAL DE  
TOLUCA  
TOLUCA 50200  
**PHONE:** +52-722-279-1600  
**FAX:** +52-722-279-1656

**OPERATOR:** AEROLINEAS EJECUTIVAS, S.A. DE C.V.  
**ADDRESS:** CALLE 2 LOTES 14-18  
TOLUCA 50200  
**PHONE:** +52-722+279-1618  
**FAX:**

**ANALYST:** PATRICK EMERSON  
**EMAIL:** PEMERSON@CESCOM.CAMPSYSTEMS.CO  
M  
1-866-581-2267 (OFFICE)  
316-462-2442 (FAX)  
WWW.CAMPSYSTEMS.COM  
800-787-9749 (EFAX-CARDS)  
631-980-4222 (EFAX-CARDS)  
PLEASE RECORD CHANGES TO ADDRESS, LAST  
ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO  
CAMP.

**AIRCRAFT SERIAL/REGNO:** 750-0204/XA-KYE      **MODEL:** CITATION X (MSG)      **MANUFACTURER:** CESSNA AIRCRAFT COMPANY - WICHITA

DATES	LAST ACTUALS	CURRENT ACTUAL
CERTIFICATION DATE: 12-DEC-2002	7814 A/C HRS as of 21-AUG-2015	A/C HRS as of ___/___/___
	3680 AFL as of 21-AUG-2015	AFL as of ___/___/___
	4383 APH as of 29-JUL-2015	APH as of ___/___/___
	4951 APS as of 29-JUL-2015	APS as of ___/___/___

**APU SERIAL/PART:** P327/3800576-1      **MODEL:** GTCP36-150(CX)      **MANUFACTURER:** HONEYWELL

INSTALLED ON 12-SEP-2009	LAST ACTUALS	CURRENT ACTUAL
0 APU HRS	4383 APU HRS as of 29-JUL-2015	APU HRS as of ___/___/___
0 APUS	4951 APUS as of 29-JUL-2015	APUS as of ___/___/___

**ENGINE NO. 1 SERIAL/PART:** 330439/23074408      **MODEL:** AE3007C/C1      **MANUFACTURER:** ROLLS ROYCE

INSTALLED ON 04-JUN-2008	LAST ACTUALS	CURRENT ACTUAL
4371 ENG. HRS      4505 A/C HRS	7679.9 ENG. HRS as of 21-AUG-2015	ENG. HRS as of ___/___/___
ENC	3608 ENC as of 21-AUG-2015	ENC as of ___/___/___

**ENGINE NO. 2 SERIAL/PART:** 330426/23074408      **MODEL:** AE3007C/C1      **MANUFACTURER:** ROLLS ROYCE

INSTALLED ON 28-APR-2011	LAST ACTUALS	CURRENT ACTUAL
5837.5 ENG. HRS      6413.9 A/C HRS	7237.5 ENG. HRS as of 21-AUG-2015	ENG. HRS as of ___/___/___
2693 ENC	3429 ENC as of 21-AUG-2015	ENC as of ___/___/___



# AD/SI Status Report

CITATION X (MSG) S/N 750-0204 (XA-KYE): 7814HRS, 3680 AFL as of 21-Aug-2015

**AIRFRAME**  
**SI with Compliance or Due**  
**Report Date: 22-Sep-2015**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
<b>AIRFRAME - SB - 750-0204/XA-KYE</b>							
ASL ASL750-25-09	REFRESHMENT CENTER HEATED DRAIN HOSE ELECTRICAL CONNECTOR DISCONNECTION, ALERT SERVICE LETTER					MANDATORY	NOT APPLICABLE - ALERT SERVICE LETTER ASL750-25-09 IS NOT APPLICABLE DUE THAT SERVICE BULLETIN SB750-25-24 WAS NOT INSTALLED ON THIS AIRCRAFT. SERVICE BULLETIN SB750-25-24 REVISION 1 WAS COMPLIED WITH BY WICHITA CITATION SERVICE CENTER ON 01/04/2007. WORK ORDER NUMBER 2-57019 MTR ID NUMBER 318829. REVISION 1 WAS THE CORRECTION ACTION FOR THE ALERT SERVICE LETTER.
14-MAY-2004		MOS HRS/MSC AFL	A/R (s)	19-FEB-2014 7633.2 3575			
	<b>Note:</b>	NOT APPLICABLE-EQUIPMENT NOT INSTALLED					
ASL ASL750-27-16	ROLL DISCONNECT SYSTEM INSPECTION AND AILERON/ROLL FEEL BUNGEE INSTALLATION, ALERT SERVICE LETTER					MANDATORY	COMPLIED WITH
06-AUG-2004		MOS HRS/MSC AFL	A/R	28-OCT-2004 1674			
ASL ASL750-27-18	ELEVATOR PCU HOSE ASSSEMBLY INSPECTION, ALERT SERVICE LETTER					MANDATORY	COMPLIED WITH
03-OCT-2005		MOS HRS/MSC AFL	A/R	21-OCT-2005 2446			
ASL ASL750-27-18 R1	ELEVATOR PCU HOSE ASSSEMBLY INSPECTION, ALERT SERVICE LETTER					MANDATORY	COMPLIED WITH
26-OCT-2005		MOS HRS/MSC AFL	A/R	13-JAN-2006 2662			
ASL ASL750-27-21	FLIGHT CONTROLS-ELEVATOR INBOARD-HINGE BRACKET INSPECTION, ALERT SERVICE LETTER					MANDATORY	COMPLIED WITH
13-OCT-2006		MOS HRS/MSC AFL	A/R	20-OCT-2006 3315			
ASL ASL750-29-09	HYDRAULIC TUBE/AIR DUCT INTERFERENCE INSPECTION, ALERT SERVICE LETTER					MANDATORY	COMPLIED WITH
09-FEB-2005		MOS HRS/MSC AFL	A/R	14-MAR-2005 1973			
ASL ASL750-29-22	RUDDER STANDBY SYSTEM RETURN LINE CHAFING INSPECTION, ALERT SERVICE LETTER					MANDATORY	COMPLIED WITH
10-MAR-2010		MOS HRS/MSC AFL	A/R	06-APR-2010 5720			
ASL ASL750-29-22 R1	RUDDER STANDBY SYSTEM RETURN LINE CHAFING INSPECTION, ALERT SERVICE LETTER					MANDATORY	COMPLIED WITH - PREVIOUSLY PREVIOUSLY COMPLIED WITH ORIGINAL BULLETIN ASL750-29-22
10-MAY-2010		MOS HRS/MSC AFL	A/R				



# AD/SI Status Report

CITATION X (MSG) S/N 750-0204 (XA-KYE): 7814HRS, 3680 AFL as of 21-Aug-2015

**AIRFRAME**  
**SI with Compliance or Due**  
**Report Date: 22-Sep-2015**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ASL ASL750-30-04	HORIZONTAL STABILIZER ANTI-ICE INSPECTION, ALERT SERVICE LETTER					MANDATORY	COMPLIED WITH
27-JAN-2004		MOS		11-FEB-2004			
		HRS/MSC	A/R	934			
		AFL					
ASL ASL750-32-19	MAIN LANDING GEAR TRAILING LINK, ALERT SERVICE LETTER					MANDATORY	COMPLIED WITH
27-AUG-2004		MOS		28-OCT-2004			
		HRS/MSC	A/R	1674			
		AFL		740			
ASL ASL750-32-22	LEFT MAIN GEAR TRAILING LINK ENHANCED INSPECTION, ALERT SERVICE LETTER					MANDATORY	COMPLIED WITH
03-NOV-2005		MOS		19-MAR-2006			
		HRS/MSC	A/R	2800			
		AFL		1253			
ASL ASL750-32-22	RIGHT MAIN GEAR TRAILING LINK ENHANCED INSPECTION, ALERT SERVICE LETTER					MANDATORY	COMPLIED WITH
03-NOV-2005		MOS		05-NOV-2005			
		HRS/MSC	A/R	2513			
		AFL		1131			
ASL ASL750-34-12	TRANSMITAL OF HONEYWELL TECHNICAL NEWSLETTER A23-3850-001, ALERT SERVICE LETTER					MANDATORY	COMPLIED WITH
17-FEB-2003		MOS		10-MAR-2003			
		HRS/MSC	A/R	156			
		AFL					
ASL ASL750-49-09 R2	APU FUEL LINE INSPECTION, ALERT SERVICE LETTER					MANDATORY	COMPLIED WITH
10-MAR-2005		MOS		26-JUL-2006			
		HRS/MSC	A/R	3108			
		AFL					
FAA 2005-09-01	APU FUEL LINE INSPECTION					MANDATORY	COMPLIED WITH
10-MAY-2005		MOS		04-JAN-2007			
		HRS/MSC	A/R	3428			
		AFL					
ASL ASL750-53-05	FUSELAGE - CANTED BULKHEAD INSPECTION, ALERT SERVICE LETTER					MANDATORY	COMPLIED WITH
03-MAR-2006		MOS		25-MAR-2006			
		HRS/MSC	A/R	2817			
		AFL					
SB 750-05-02	TIME LIMITS/MAINTENANCE CHECKS- RETROFIT FROM CALENDER SCHEDULE MAINTENANCE PROGRAM TO MSG-3 SCHEDULE MAINTENANCE PROGRAM, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - UNIT 750-0204 INCORPORATED SB750-05-02 WITHOUT BEING REMOVED FROM SERVICE. FROM THIS DATE FORWARD, THE CITATION X MSG-3 MAINTENANCE PLAN APPLIES TO UNIT 750-0204. FOR QUESTIONS, CONTACT THE REPAIR FACILITY LISTED BELOW OR CESSNA MAINTENANCE ENGINEERING DEPARTMENT AT +1 316-517-7564
		MOS		10-JAN-2014			
		HRS/MSC	A/R	7602.7			
		AFL		3551			
SB 750-11-16	PLACARDS & MARKINGS - BAGGAGE WEIGHT AND LOADING PLACARD, SERVICE BULLETIN					MANDATORY	COMPLIED WITH
01-DEC-2004		MOS		24-FEB-2005			
		HRS/MSC	A/R	1903			
		AFL					

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks \*-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



# AD/SI Status Report

CITATION X (MSG) S/N 750-0204 (XA-KYE): 7814HRS, 3680 AFL as of 21-Aug-2015

**AIRFRAME**  
**SI with Compliance or Due**  
**Report Date: 22-Sep-2015**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 750-21-23	CABIN DUCT ASSEMBLY IMPROVEMENT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
		MOS		18-JAN-2006			
	01-MAR-2005	HRS/MSC	A/R	2664			
		AFL					
SB 750-21-25	AIR CONDITIONING - ACM LOW LIMIT SET-POINT IMPROVEMENT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
		MOS		09-MAY-2008			
	13-FEB-2007	HRS/MSC	A/R	4470			
		AFL					
SB 750-21-28	AIR CONDITIONING - SERVICE AIR IMPROVEMENT FOR THE BAGGAGE COMPARTMENT DOOR, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - ACCOMPLISHED SB750-21-28, DATED JUNE 12, 2009, SERVICE AIR IMPROVEMENT FOR THE BAGGAGE COMPARTMENT DOOR
		MOS		14-JAN-2011			
	12-JUN-2009	HRS/MSC	A/R (s)	6199.7			
		AFL		2845			
SB 750-23-12 R1	RNZ-850 NAV RADIO UPGRADE, SERVICE BULLETIN					MANDATORY	COMPLIED WITH
		MOS		22-MAR-2005			
	20-OCT-2003	HRS/MSC	-	1975			
		AFL					
SB 750-23-16	MODIFICATION OF THE HONEYWELL AV-850 AUDIO WIRING, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
		MOS		21-MAY-2009			
	08-DEC-2006	HRS/MSC	A/R	5123			
		AFL					
SB 750-24-11 R1	APU DC GENERATOR BEARING FAIL INDICATION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
		MOS		22-DEC-2004			
	05-APR-2004	HRS/MSC	A/R				
		AFL		975			
		APH					
SB 750-24-11 R1	LEFT DC GENERATOR BEARING FAIL INDICATION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
		MOS		22-MAR-2005			
	05-APR-2004	HRS/MSC	-	1975			
		AFL					
SB 750-24-11 R1	RIGHT DC GENERATOR BEARING FAIL INDICATION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
		MOS		22-MAR-2005			
	05-APR-2004	HRS/MSC	A/R	1975			
		AFL					
SB 750-24-24	ELECTRICAL POWER - SPLIT BUS START CONTROL LOGIC MODULE IMPROVEMENT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
		MOS		11-MAR-2008			
	22-DEC-2004	HRS/MSC	A/R	4325			
		AFL					
SB 750-24-24 R1	SPLIT BUS START CONTROL LOGIC MODULE IMPROVEMENT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - SERVICE BULLETIN ON HOLD.
		MOS		04-JAN-2007			
	01-AUG-2005	HRS/MSC	A/R	3428			
		AFL					



# AD/SI Status Report

CITATION X (MSG) S/N 750-0204 (XA-KYE): 7814HRS, 3680 AFL as of 21-Aug-2015

**AIRFRAME**  
**SI with Compliance or Due**  
**Report Date: 22-Sep-2015**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 750-24-24 R3	ELECTRICAL POWER - SPLIT BUS START CONTROL LOGIC MODULE IMPROVEMENT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
12-SEP-2007		MOS		11-MAR-2008			
		HRS/MSC	A/R	4325			
		AFL					
SB 750-24-30	APU GENERATOR CONTROL UNIT (GCU) IMPROVEMENT, SERVICE BULLETIN					MANDATORY	COMPLIED WITH - SERVICE BULLETIN SB750-24-30 IS NOT APPLICABLE TO THIS AIRCRAFT DUE TO SERIAL NUMBER EFFECTIVITY CALL OUT IN THE SERVICE BULLETIN.
05-DEC-2011		MOS		13-FEB-2012			
		HRS/MSC	A/R	6856.9			
		AFL		3188			
FAA 2012-18-16	REPLACEMENT OF AUXILIARY POWER UNIT (APU) GENERATOR CONTROL UNIT (GCU).					MANDATORY	NOT APPLICABLE - AD2012-18-16 IS NOT APPLICABLE TO THIS AIRCRAFT SERIAL NUMBER 750-0204 DUE TO THE APPLICABILITY SERIAL NUMBERS SATED IN THE AD
24-OCT-2012		MOS		11-OCT-2012			
		HRS/MSC	-	7040.9			
		AFL		3303			
SB 750-24-31	EMERGENCY BATTERY WIRING MODIFICATION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - ACCOMPLISHED SB750-24-31, DATED APRIL 27, 2010, EMERGENCY BATTERY WIRING MODIFICATION
27-APR-2010		MOS		14-JAN-2011			
		HRS/MSC	A/R	6199.7			
		AFL		2845			
SB 750-24-32	ENGINE GENERATOR CONTROL UNIT (GCU) IMPROVEMENT, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - SERVICE BULLETIN SB750-24-32 IS NOT APPLICABLE TO THIS AIRCRAFT DUE TO SERIAL NUMBER EFFECTIVITY STATED IN THE SERVICE BULLETIN.
01-AUG-2012		MOS		23-AUG-2012			
		HRS/MSC	-	7005.3			
		AFL		3284			
SB 750-25-23	EQUIPMENT/FURNISHINGS - SEXTANT EMERGENCY LOCATOR TRANSMITTER CONTROL PANEL IMPROVEMENT, SERVICE BULLETIN					DISCRETIONARY	COMPLIED WITH
15-APR-2003		MOS		02-JUL-2008			
		HRS/MSC	A/R	4559			
		AFL					
SB 750-25-24 R1	RIGHT HAND FORWARD REFRESHMENT CENTER DRAIN LINE MODIFICATION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
01-APR-2005		MOS		04-JAN-2007			
		HRS/MSC	A/R	3428			
		AFL					
SB 750-25-38	EQUIPMENT/FURNISHINGS - DRAIN TIP HEATER REMOVAL, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - ACCOMPLISHED OPTIONAL SERVICE BULLETIN SB750-25-38
25-OCT-2011		MOS		01-MAY-2013			
		HRS/MSC	A/R	7262.3			
		AFL		3402			



# AD/SI Status Report

CITATION X (MSG) S/N 750-0204 (XA-KYE): 7814HRS, 3680 AFL as of 21-Aug-2015

**AIRFRAME**  
**SI with Compliance or Due**  
**Report Date: 22-Sep-2015**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 750-26-04	FIRE PROTECTION- TRANSMITTAL OF PACIFIC SCIENTIFIC SERVICE BULLETIN 26-03-35071497, INSPECTION AND REPLACEMENT OF TEMPERATURE COMPENSATED PRESSURE SWITCH, SERVICE BULLETIN					MANDATORY	COMPLIED WITH
11-APR-2003		MOS HRS/MSC AFL	A/R	27-MAY-2003 346			
SB 750-26-05	APU FIRE BOTTLE WIRE IDENTIFICATION SLEEVE INSTALLATION, SERVICE BULLETIN					MANDATORY	COMPLIED WITH
24-NOV-2004		MOS HRS/MSC AFL	-	23-FEB-2005 1903			
SB 750-27-38 R1	ROLL SPOILER MIXER BOX ASSEMBLY ROLL PIN INSPECTION/REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
10-JUL-2003		MOS HRS/MSC AFL	-	22-MAR-2005 1975			
SB 750-27-50	FLIGHT CONTROLS- ELEVATOR CONTROL CABLE RUB BLOCK REPLACEMENT, SERVICE BULLETIN					DISCRETIONARY	COMPLIED WITH
10-FEB-2003		MOS HRS/MSC AFL	A/R	31-MAR-2003 210			
SB 750-27-55 R1	FLIGHT CONTROLS - PITCH ROLL DISCONNECT IMPROVEMENT, SERVICE BULLETIN					MANDATORY	COMPLIED WITH
08-MAY-2006		MOS HRS/MSC AFL	A/R	20-JUL-2006 3098			
SB 750-27-56	AILERON ROLL FEEL AND CENTERING BELLCRANK REPLACEMENT, SERVICE BULLETIN					MANDATORY	COMPLIED WITH
17-JAN-2006		MOS HRS/MSC AFL	-	10-JUN-2006 2997			
SB 750-27-60	FLIGHT CONTROLS - WIRE MODIFICATION TO THE FLAP SYSTEM HIGH SPEED RELAY WIRE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
20-FEB-2007		MOS HRS/MSC AFL	A/R	18-SEP-2007 3914			



# AD/SI Status Report

CITATION X (MSG) S/N 750-0204 (XA-KYE): 7814HRS, 3680 AFL as of 21-Aug-2015

**AIRFRAME**  
**SI with Compliance or Due**  
**Report Date: 22-Sep-2015**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 750-27-62 R3	FLIGHT CONTROLS - HORIZONTAL STABILIZER AND ELEVATOR HINGE IMPROVEMENT (COMPLIANCE OF SB 750-27-62 REMOVES INSPECTION DOCUMENT 33 REQUIREMENTS AS PER 750 CHAPTER 5) SERVICE BULLETIN, SERVICE BULLETIN					MANDATORY	COMPLIED WITH - ACCOMPLISHED SB750-27-62 REV 3, DATED AUGUST 21, 2009, HORIZONTAL STABILIZER HINGE IMPROVEMENT AND ELEVATOR REPLACEMENT
21-AUG-2009		MOS HRS/MSC AFL	A/R	14-JAN-2011 6199.7 2845			
FAA 2006-23-05	INSPECT FOR CRACKS IN ELEVATOR INBOARD-HINGE BRACKETS					SUPERSEDED	COMPLIED WITH
		MOS HRS/MSC AFL	A/R	10-NOV-2006 3381			
FAA 2010-20-10	GENERAL VISUAL INSPECTION FOR CRACKING OF THE INBOARD-HINGE BRACKETS OF THE LEFT AND RIGHT ELEVATOR					MANDATORY	COMPLIED WITH - ACCOMPLISHED AD2010-20-10 EFFECTIVE NOV 1/2010 BY MEANS OF ACCOMPLISHING SB750-27-62 REV 3 NO FURTHER ACTION REQUIRED. THIS AD2010-20-10 WAS COMPLIED WITH BY WICHITA CITATION SERVICE CENTER ON JAN 14 2011 WORK ORDER # 2-78826. WICHITA SIGN OFF THE SB750-27-62 REV 3 BUT DID NOT SIGN OFF THE AD2010-20-10.
		MOS HRS/MSC AFL	A/R	14-JAN-2011 6199.7 2845			
SB 750-27-66	FLIGHT CONTROLS - FLAP/SLAT SELECTOR SCREW IMPROVEMENT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - ACCOMPLISHED SB750-27-66 IAW BULLETIN'S INSTRUCTIONS
22-DEC-2011		MOS HRS/MSC AFL	-	06-JAN-2012 6838.3 3175			
SB 750-29-11 R1	POWER TRANSFER UNIT INSTALLATION IMPROVEMENT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
21-JUN-2002		MOS HRS/MSC AFL	A/R	12-DEC-2002 13 0			
SB 750-29-14	HYDRAULIC POWER - ENGINE PYLON HYDRAULIC TUBE IMPROVEMENT, SERVICE BULLETIN					MANDATORY	COMPLIED WITH - ACCOMPLISHED SB750-29-14, DATED APRIL 25, 2011, ENGINE PYLON HYDRAULIC TUBE IMPROVEMENT.
25-APR-2011		MOS HRS/MSC AFL	-	28-JUN-2011 6563.2 3005			
SB 750-30-06	WING LEADING EDGE BLEED AIR TUBE IMPROVEMENT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
09-AUG-2002		MOS HRS/MSC AFL	A/R	12-DEC-2002 13 0			
SB 750-31-04	INDICATING/RECORDING SYSTEMS - PAC OVERTEMP EICAS MESSAGE LATCH IMPROVEMENT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
06-MAY-2003		MOS HRS/MSC AFL	A/R	07-MAR-2004 1044			



# AD/SI Status Report

CITATION X (MSG) S/N 750-0204 (XA-KYE): 7814HRS, 3680 AFL as of 21-Aug-2015

**AIRFRAME**  
**SI with Compliance or Due**  
**Report Date: 22-Sep-2015**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 750-32-44 R2	MAIN LANDING GEAR TRAILING LINK AND OLEO ASSEMBLY WASHER INSTALLATION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
01-MAR-2004		MOS		22-MAR-2005			
		HRS/MSC	A/R	1975			
		AFL					
SB 750-32-45 R1	NOSE LANDING GEAR EXTEND HOSE REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
01-AUG-2003		MOS		07-MAR-2004			
		HRS/MSC	A/R	1044			
		AFL					
SB 750-32-46	LANDING GEAR- MAIN LANDING GEAR BRAKE HOSE INSTALLATION IMPROVEMENT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
11-MAY-2004		MOS		18-JAN-2006			
		HRS/MSC	A/R	2664			
		AFL					
SB 750-32-51	LANDING GEAR - BRAKE TUBE REPLACEMENT					DISCRETIONARY	
22-SEP-2011		MOS					
		HRS/MSC	-				
		AFL					
SB 750-32-47	LANDING GEAR - LANDING GEAR CONTROL MANIFOLD REPLACEMENT, SERVICE BULLETIN					MANDATORY	COMPLIED WITH
08-JUN-2006		MOS		11-JAN-2007			
		HRS/MSC	A/R	3438			
		AFL					
SB 750-32-51	LANDING GEAR - BRAKE TUBE REPLACEMENT, SERVICE BULLETIN					DISCRETIONARY	
22-SEP-2011		MOS					
		HRS/MSC	-				
		AFL					
SB 750-32-46	LANDING GEAR- MAIN LANDING GEAR BRAKE HOSE INSTALLATION IMPROVEMENT					RECOMMENDED	COMPLIED WITH
11-MAY-2004		MOS		18-JAN-2006			
		HRS/MSC	A/R	2664			
		AFL					
SB 750-32-52	LANDING GEAR - LANDING GEAR RETRACT WIRING MODIFICATION, SERVICE BULLETIN					MANDATORY	COMPLIED WITH
27-NOV-2007		MOS		04-JUN-2008			
		HRS/MSC	A/R	4505			
		AFL					
SB 750-32-53	LANDING GEAR - PARKING BRAKE CABLE IMPROVEMENT, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH
16-MAR-2007		MOS		22-DEC-2009			
		HRS/MSC	A/R	5549			
		AFL					
SB 750-32-56	GAGE INSTALLATION IMPROVEMENT FOR THE EMERGENCY GEAR EXTENSION BOTTLE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - ACCOMPLISHED SB750-32-56, DATED JANUARY 22, 2010, GAGE INSTALLATION IMPROVEMENT FOR THE EMERGENCY GEAR EXTENSION BOTTLE
22-JAN-2010		MOS		14-JAN-2011			
		HRS/MSC	A/R (s)	6199.7			
		AFL		2845			





# AD/SI Status Report

CITATION X (MSG) S/N 750-0204 (XA-KYE): 7814HRS, 3680 AFL as of 21-Aug-2015

**AIRFRAME**  
**SI with Compliance or Due**  
**Report Date: 22-Sep-2015**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 750-32-59	LANDING GEAR - MAIN LANDING GEAR SIDE BRACE FITTING INSPECTION, SERVICE BULLETIN					MANDATORY	COMPLIED WITH - COMPLIED WITH SB750-32-59 MAIN LANDING GEAR SIDE BRACE FITTING INSPECTION.
03-JAN-2011		MOS HRS/MSC AFL	A/R	10-JAN-2014 7602.7 3551			
SB 750-32-61	NOSE LANDING GEAR ISOLATOR-PIN REPLACEMENT, SERVICE BULLETIN					MANDATORY	COMPLIED WITH - PER TEAM X - ALL REQUIREMENTS OF SB750-32-61 WERE PREVIOUSLY ACCOMPLISHED ON 9/24/2012 AT 7029.9 ACFT TT, 3298 TLNDGS WHEN ISOLATION PIN AND HARDWARE WAS REPLACED WITH NEW ITEMS - REF NGSC WO # 15696 AND MTR # 2063222.
17-OCT-2013		MOS HRS/MSC AFL	-	18-NOV-2013 7558.3 3527			
SL CIL-32-02 R1	NOSE LANDING GEAR ISOLATOR-PIN INSPECTION					MANDATORY	NOT APPLICABLE - THIS CIL IS NOLONGER APPLICABLE DUE TO SB750-32-61 BEING ACCOMPLISHED.
17-OCT-2013		DAYS HRS/MSC AFL	-	18-NOV-2013 7558.3 3527			
SB 750-33-21 R1	LED NAVIGATION LIGHT IMPROVEMENT, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - VERIFIED TO BE N/A BY PREVIOUS ACCOMPLISHMENT OF SB750-33-21 ( REF NGSC WO # 10850 ).
12-OCT-2004		MOS HRS/MSC AFL	A/R	11-OCT-2011 6749.9 3115			
SB 750-33-22 R2	LIGHTS - CHART LIGHT MODIFICATION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - ACCOMPLISHED SB750-33-22 REV 2, DATED OCT 22/2007; LIGHTS - CHART LIGHT MODIFICATION.
22-OCT-2007		MOS HRS/MSC AFL	A/R (s)	13-MAR-2014 7651.3 3586			
SB 750-33-23	PSU LIGHTING WIRING MODIFICATION, SERVICE BULLETIN					MANDATORY	COMPLIED WITH
13-AUG-2004		MOS HRS/MSC AFL	A/R	22-MAR-2005 1975			
SB 750-33-28 R1	LIGHT EMITTING DIODE (LED) EMERGENCY OVER WING LIGHT INSTALLATION, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH
25-MAR-2008		MOS HRS/MSC AFL	A/R	07-JUL-2008 4560			
SB 750-33-31	LIGHTS - BONDING IMPROVEMENT FOR THE OVER WING EMERGENCY LIGHT, SERVICE BULLETIN					MANDATORY	COMPLIED WITH
26-MAR-2008		MOS HRS/MSC AFL	A/R	07-JUL-2008 4560			



# AD/SI Status Report

CITATION X (MSG) S/N 750-0204 (XA-KYE): 7814HRS, 3680 AFL as of 21-Aug-2015

**AIRFRAME**  
**SI with Compliance or Due**  
**Report Date: 22-Sep-2015**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 750-34-40 R1	NAVIGATION - ENHANCED GROUND PROXIMITY WARNING SYSTEM (EGPWS) SCN 219 SOFTWARE UPGRADE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH
18-APR-2006		MOS		04-JAN-2007			
		HRS/MSC	A/R	3428			
		AFL					
SB 750-34-41	HONEYWELL ENHANCED SURVEILLANCE TRANSPONDER UPGRADE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH
04-MAY-2006		MOS		04-JAN-2007			
		HRS/MSC	A/R	3428			
		AFL					
SB 750-34-42	NAVIGATION - HONEYWELL PRIMUS 2000 PHASE 7 WITH FMS SOFTWARE NZ 6.0, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
31-MAR-2008		MOS		04-JUN-2008			
		HRS/MSC	A/R	4505			
		AFL					
SB 750-34-46	MODIFICATION OF AVIONICS BAY VENTILATION, SERVICE BULLETIN					DISCRETIONARY	COMPLIED WITH
02-NOV-2006		MOS		08-OCT-2007			
		HRS/MSC	A/R	3988			
		AFL					
SB 750-34-51 R1	TAKE OFF AND LANDING DATABASE LIMITATION-PLACARD INSTALLATION, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - NOT APPLICABLE BY COMPONENT SERIAL NUMBER.
18-FEB-2010		MOS		22-APR-2010			
		HRS/MSC	A/R	5720			
		AFL					
SB 750-34-53	TCAS 2000 INTERFERENCE LIMITING FUNCTIONALITY UPGRADE, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - SERVICE BULLETIN SB750-34-53 IS NOT APPLICABLE TO THIS AIRCRAFT SERIAL NUMBER 750-0204 DUE THAT ACSS TCAS 2000 IS NOT INSTALLED. BENDIX/KING TPU-67A IS INSTALLED.
07-MAR-2012		MOS		22-MAY-2012			
		HRS/MSC	-	6971			
		AFL		3245			
SB 750-34-53 R1	TCAS 2000 INTERFERENCE LIMITING FUNCTIONALITY UPGRADE FOR SOFTWARE VERSION 7.0, SERVICE BULLETIN					MANDATORY	
26-JUN-2012		MOS					
		HRS/MSC	-				
		AFL					
FAA 2012-02-08	AVIATION COMMUNICATION AND SURVEILLANCE SYSTEMS (ACSS) TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) UNITS					MANDATORY	NOT APPLICABLE - AD2012-02-08 IS NOT APPLICABLE DUE THAT ACSS TCAS 2000 IS NOT INSTALLED IN THIS AIRCRAFT.
13-MAR-2012		MOS		22-MAY-2012			
		HRS/MSC	-	6971			
		AFL		3245			
SB 750-34-53 R2	NAVIGATION - TCAS 2000 INTERFERENCE LIMITING FUNCTIONALITY UPGRADE FOR SOFTWARE VERSION 7.0					MANDATORY	
24-OCT-2012		MOS					
		HRS/MSC	-				
		AFL					



# AD/SI Status Report

CITATION X (MSG) S/N 750-0204 (XA-KYE): 7814HRS, 3680 AFL as of 21-Aug-2015

**AIRFRAME**  
**SI with Compliance or Due**  
**Report Date: 22-Sep-2015**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 750-34-53 R2	NAVIGATION - TCAS 2000 INTERFERENCE LIMITING FUNCTIONALITY UPGRADE FOR SOFTWARE VERSION 7.0, SERVICE BULLETIN					MANDATORY	
24-OCT-2012		MOS					
		HRS/MSC -					
		AFL					
FAA 2012-02-08	AVIATION COMMUNICATION AND SURVEILLANCE SYSTEMS (ACSS) TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) UNITS					MANDATORY	NOT APPLICABLE - AD2012-02-08 IS NOT APPLICABLE DUE THAT ACSS TCAS 2000 IS NOT INSTALLED IN THIS AIRCRAFT.
13-MAR-2012		MOS		22-MAY-2012			
		HRS/MSC -		6971			
		AFL		3245			
SB 750-34-53 R1	TCAS 2000 INTERFERENCE LIMITING FUNCTIONALITY UPGRADE FOR SOFTWARE VERSION 7.0					MANDATORY	
26-JUN-2012		MOS					
		HRS/MSC -					
		AFL					
SB 750-34-57	AH800 TO LASEREF IV MODIFICATION, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - SERVICE BULLETIN SB750-34-57 IS NOT APPLICABLE TO THIS AIRCRAFT DUE TO SERIAL NUMBER EFFECTIVITY STATED IN THE SERVICE BULLETIN.
10-AUG-2012		MOS		15-AUG-2012			
		HRS/MSC -		6997.2			
		AFL		3276			
SB 750-36-18	PNEUMATIC - VACUUM-EJECTOR-JET PARTICLE-TRAP-ASSEMBLY REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
27-APR-2004		MOS		04-JAN-2007			
		HRS/MSC A/R		3428			
		AFL					
SB 750-36-19	AIR CONDITIONING- RAM AIR TEMPERATURE PROBE ORIFICE INSTALLATION, SERVICE BULLETIN					DISCRETIONARY	- NOT APPLICABLE-EQUIPMENT NOT INSTALLED
10-AUG-2004		MOS		(EFF)			
		HRS/MSC A/R					
		AFL					
SB 750-36-21	PNEUMATIC - HIGH-PRESSURE BLEED-AIR PRESSURE SWITCH INSTALLATION MODIFICATION, SERVICE BULLETIN					DISCRETIONARY	COMPLIED WITH
10-MAY-2007		MOS		16-AUG-2007			
		HRS/MSC A/R		3867			
		AFL					
SB 750-49-10 R1	STINGER INTERNAL HEAT REDUCTION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
05-DEC-2002		MOS		01-AUG-2003			
		HRS/MSC -		437			
		AFL					
SB 750-49-11	AUXILIARY POWER - APU ELECTRONIC CONTROL UNIT SURGE LOGIC UPGRADE, SERVICE BULLETIN					DISCRETIONARY	COMPLIED WITH
22-FEB-2007		MOS		04-JUN-2008			
		HRS/MSC A/R		4505			
		AFL					

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks \*-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



# AD/SI Status Report

CITATION X (MSG) S/N 750-0204 (XA-KYE): 7814HRS, 3680 AFL as of 21-Aug-2015

**AIRFRAME**  
**SI with Compliance or Due**  
**Report Date: 22-Sep-2015**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 750-49-12 R1	AUXILIARY POWER - APU FUEL LINE INSTALLATION IMPROVEMENT, SERVICE BULLETIN					MANDATORY	COMPLIED WITH
03-AUG-2006		MOS HRS/MSC AFL	A/R	04-JAN-2007 3428			
FAA 2006-24-01	APU FUEL TUBE LEAKS					AIRWORTHINESS	COMPLIED WITH
06-DEC-2006		MOS HRS/MSC AFL	A/R	04-JAN-2007 3428			
SB 750-52-29 R2	BAGGAGE DOOR SEAL IMPROVEMENT, SERVICE BULLETIN					DISCRETIONARY	COMPLIED WITH
02-NOV-2005		MOS HRS/MSC AFL	A/R	13-JAN-2009 4915			
SB 750-53-26	FUSELAGE - IMPROVEMENT TO THE ENGINE INLET COVER TIEDOWN, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
30-MAY-2007		MOS HRS/MSC AFL	A/R	24-SEP-2007 3947			
SB 750-53-29	FUSELAGE - STINGER DRAINAGE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - ACCOMPLISHED SB750-53-29, DATED JUNE 8, 2009, STINGER DRAINAGE
08-JUN-2009		MOS HRS/MSC AFL	A/R (s)	14-JAN-2011 6199.7 2845			
SB 750-53-31 R1	FUSELAGE - NOSE DRIP CAP BOND INSPECTION, SERVICE BULLETIN					MANDATORY	COMPLIED WITH - C/W SB750-53-31 REV 1, EDDY CURRENT INSPECTION C/W BY ATS ON 1/05/2013 JOB# P191398 CRS# HC4D227M. NO DEFECTS NOTED.
05-OCT-2011		MOS HRS/MSC AFL	A/R	08-JAN-2013 7125.6 3344			
SB 750-53-32	FUSELAGE - FORWARD PRESSURE BULKHEAD FASTENER INSPECTION, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER CESSNA CITATIO SERVICE BULLETIN SB750-53-32 IS NOT APPLICABLE TO THIS AIRCRAFT DUE TO SERIAL NUMBER. THIS AIRCRAFT SERIAL NUMBE IS 0204
01-OCT-2010		MOS HRS/MSC AFL	A/R	26-OCT-2010 6087.3 2793			
SB 750-54-04 R3	NACELLES/PYLONS - PYLON ACCESS PANEL MODIFICATION, SERVICE BULLETIN					RECOMMENDED	
05-JUN-2012		MOS HRS/MSC AFL	8800		8800 M		

# AD/SI Status Report

CITATION X (MSG) S/N 750-0204 (XA-KYE): 7814HRS, 3680 AFL as of 21-Aug-2015

**AIRFRAME**  
**SI with Compliance or Due**  
**Report Date: 22-Sep-2015**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 750-55-10	HORIZONTAL STABILIZER TRIM ACTUATOR ELECTRONIC CONTROL MODULE IMPROVEMENT, SERVICE BULLETIN					OPTIONAL	
27-JUN-2012		MOS					
		HRS/MSC	-				
		AFL					
SB 750-55-10 R1	HORIZONTAL STABILIZER TRIM ACTUATOR ELECTRONIC CONTROL MODULE IMPROVEMENT					OPTIONAL	
09-NOV-2012		MOS					
		HRS/MSC	-				
		AFL					
SB 750-55-11 R1	INSPECTION AND MODIFICATION OF THE UPPER RUDDER HINGE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - ACCOMPLISHED SB750-55-11 REV 1, DATED JUNE 22, 2010, INSPECTION AND MODIFICATION OF THE UPPER RUDDER HINGE.
22-JUN-2010		MOS		14-JAN-2011			
		HRS/MSC	-	6199.7			
		AFL		2845			
SB 750-57-11	WING WIRE BUNDLE ANCHOR ASSEMBLY INSTALLATION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
10-OCT-2003		MOS		22-MAR-2005			
		HRS/MSC	A/R	1975			
		AFL					
SB 750-57-12	WING ACCESS PANEL SCREW REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
01-MAR-2005		MOS		08-JUN-2006			
		HRS/MSC	A/R	2997			
		AFL					
SB 750-57-13 R1	ACCESS PANEL SEAL AND P-STATIC PAINT IMPROVEMENT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - ACCOMPLISHED SB750-57-13 REV 1, DATED JAN 25/2013
25-JAN-2013		MOS		02-OCT-2014			
		HRS/MSC	-	7653.8			
		AFL		3588			
SB 750-71-06 R1	ENGINE DRAIN LINE REMOVAL, SERVICE BULLETIN					MANDATORY	COMPLIED WITH
19-APR-1999		MOS		12-DEC-2002			
		HRS/MSC	A/R	13			
		AFL		0			
SB 750-71-06 R2	ENGINE DRAIN LINE REMOVAL, SERVICE BULLETIN					MANDATORY	COMPLIED WITH
20-JAN-2003		MOS		12-JUN-2003			
		HRS/MSC	-	388			
		AFL					
SB 750-71-11	POWER PLANT - INSPECTION OF THE FORWARD ENGINE MOUNT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
17-APR-2007		MOS		04-JUN-2008			
		HRS/MSC	A/R	4505			
		AFL					
SB 750-76-06 R1	FADEC SOFTWARE UPGRADE C9, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
03-DEC-2004		MOS		03-JAN-2006			
		HRS/MSC	A/R	2632			
		AFL					



# AD/SI Status Report

CITATION X (MSG) S/N 750-0204 (XA-KYE): 7814HRS, 3680 AFL as of 21-Aug-2015

**AIRFRAME**  
**SI with Compliance or Due**  
**Report Date: 22-Sep-2015**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 750-76-07 R1	LEFT ENGINE CONTROLS - FULL AUTHORITY DIGITAL ENGINE CONTROL (FADEC) SOFTWARE UPGRADE VERSION C9.1, SERVICE BULLETIN					MANDATORY	COMPLIED WITH - ACCOMPLISHED SB750-76-07 REV 1, DATED OCTOBER 5, 2009, FULL AUTHORITY DIGITAL ENGINE CONTROL (FADEC) SOFTWARE UPGRADE VERSION C9.1
05-OCT-2009		MOS HRS/MSC AFL	A/R	14-JAN-2011 6199.7 2845			
SB 750-76-07 R1	RIGHT ENGINE CONTROLS - FULL AUTHORITY DIGITAL ENGINE CONTROL (FADEC) SOFTWARE UPGRADE VERSION C9.1, SERVICE BULLETIN					MANDATORY	COMPLIED WITH - ACCOMPLISHED SB750-76-07 REV 1, DATED OCTOBER 5, 2009, FULL AUTHORITY DIGITAL ENGINE CONTROL (FADEC) SOFTWARE UPGRADE VERSION C9.1.
05-OCT-2009		MOS HRS/MSC AFL	A/R	14-JAN-2011 6199.7 2845			
SB 750-76-09	ENGINE CONTROLS - FULL AUTHORITY DIGITAL ENGINE CONTROL (FADEC) SOFTWARE UPGRADE VERSION C9.2, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - ROLLS ROYCE SERVICE BULLETIN AE3007C-73-053 R1 WAS COMPLIED WITH BY GREENSBORO CITATION SERVICE CENTER ON 07/02/2012. ACTT: 6984.8 LDINGS: 3255 LEFT ENGINE TT: 6850.7 CYC: 3190 MTR ID NUMBER 2023030
03-AUG-2011		MOS HRS/MSC AFL	A/R	18-FEB-2014 7633.2 3575			
SB 750-78-04	EXHAUST- THRUST REVERSER LOGIC MODULE REPLACEMENT, SERVICE BULLETIN					MANDATORY	COMPLIED WITH
25-JUN-2003		MOS HRS/MSC AFL	A/R	01-AUG-2003 437			
SL CIL-32-02 R1	NOSE LANDING GEAR ISOLATOR-PIN INSPECTION, SERVICE LETTER					MANDATORY	NOT APPLICABLE - THIS CIL IS NOLONGER APPLICABLE DUE TO SB750-32-61 BEING ACCOMPLISHED.
17-OCT-2013		DAYS HRS/MSC AFL	-	18-NOV-2013 7558.3 3527			
SB 750-32-61	NOSE LANDING GEAR ISOLATOR-PIN REPLACEMENT					MANDATORY	COMPLIED WITH - PER TEAM X - ALL REQUIREMENTS OF SB750-32-61 WERE PREVIOUSLY ACCOMPLISHED ON 9/24/2012 AT 7029.9 ACFT TT, 3298 TLNDGS WHEN ISOLATION PIN AND HARDWARE WAS REPLACED WITH NEW ITEMS - REF NGSC WO # 15696 AND MTR # 2063222.
17-OCT-2013		MOS HRS/MSC AFL	-	18-NOV-2013 7558.3 3527			



# AD/SI Status Report

CITATION X (MSG) S/N 750-0204 (XA-KYE): 7814HRS, 3680 AFL as of 21-Aug-2015

**AIRFRAME**  
**SI with Compliance or Due**  
**Report Date: 22-Sep-2015**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL CIL-34-02	TRANSMITTAL OF HONEYWELL SIL D201301000032, PRIMUS II INTEGRATED RADIO SYSTEM, SERVICE LETTER					MANDATORY	COMPLIED WITH - COMPLIED WITH MANDATORY SERVICE LETTER CIL-34-02 PRIMUS II INTEGRATED RADIO SYSTEM. FOUND NAV. 1 PART NUMBER 7510100-731 SERIAL NUMBER 9507155 AND NAV. 2 PART NUMBER 7510100-733 SERIAL NUMBER 02056554 BOTH HAVING AS MOD AND TO BE IN COMPLIANCE WITH AD2010-07-02.
18-MAR-2013		MOS HRS/MSC - AFL		27-MAR-2013 7201 3378			
FAA 2010-07-02	PERFORM A ONE-TIME GENERAL VISUAL INSPECTION OF THE MODIFICATION PLATE FOR THE HONEYWELL PRIMUS II NV-850 NAVIGATION RECEIVER MODULE (NRM)					MANDATORY	COMPLIED WITH - COMPLIED WITH AD2010-07-02 ON NGAD WORK ORDER NUMBER 15833 DTED 11/09/2012
03-MAY-2010		MOS HRS/MSC A/R (s) AFL		27-MAR-2013 7201 3378			
SL CIL-99-03	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP), SERVICE LETTER					RECOMMENDED	COMPLIED WITH - COMPLIED WITH CIL-99-03 R1 ON 06/14/2013 ACTT: 7339.1 LDINGS: 3441 NORTHROP GRUMMAN WORK ORDER NUMBER 16238.
04-JAN-2013		MOS HRS/MSC - AFL		19-FEB-2014 7633.2 3575			
SL CIL-99-03 R1	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP), SERVICE LETTER					RECOMMENDED	COMPLIED WITH - COMPLIED WITH THE LANDING GEAR, NOSE LANDING GEAR WHEEL WELL, AND MAIN LANDING GEAR WHEEL WELL CORROSION INSPECTION IN ACCORDANCE WITH CESSNA CITATION SERVICE LETTER CIL-99-03R1
25-MAR-2013		MOS HRS/MSC - AFL		14-JUN-2013 7339.1 3441			
SL SL750-21-05	AIR CYCLE MACHINE INSPECTION/REPLACEMENT, SERVICE LETTER					RECOMMENDED	NOT APPLICABLE - NOT APPLICABLE BY COMPONENT SERIAL NUMBER.
17-OCT-2003		MOS HRS/MSC A/R AFL		27-JAN-2005 1826			
SL SL750-21-07	AIR CONDITIONING - TRANSMITTAL OF AIRBORNE SERVICE LETTER 74 MANDATORY REPLACEMENT OF CONTROLLER-INVERTER (PARKER PART NUMBER 1E48-1), SERVICE LETTER					MANDATORY	COMPLIED WITH
16-SEP-2008		MOS HRS/MSC A/R AFL		06-AUG-2010 5912.8 2703			
SL SL750-21-08	AIR CONDITIONING - MS21919WDF YELLOW NITRILE CLAMP INSPECTION, SERVICE LETTER					RECOMMENDED	COMPLIED WITH - ACCOMPLISHED SL750-21-08 AND REV #1 BY REPLACING ALL CLAMPS REQUIRED IAW FIGURES 1
04-JUN-2009		MOS HRS/MSC A/R AFL		13-DEC-2013 7581.8 3536			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks \*-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



# AD/SI Status Report

CITATION X (MSG) S/N 750-0204 (XA-KYE): 7814HRS, 3680 AFL as of 21-Aug-2015

**AIRFRAME**  
**SI with Compliance or Due**  
**Report Date: 22-Sep-2015**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL SL750-21-08 R1	MS21919WDF YELLOW NITRILE CLAMP INSPECTION, SERVICE LETTER					RECOMMENDED	COMPLIED WITH - ACCOMPLISHED BY REPLACING ALL REQUIRED CLAMPS IAW SL750-21-08 R1 FIGURES 1 - 4
21-APR-2010		MOS HRS/MSC AFL	A/R	13-DEC-2013 7581.8 3536			
SL SL750-23-09	COMMUNICATIONS - AIRSHOW RELIABILITY IMPROVEMENTS AND SERVICE PACK SOFTWARE UPGRADES, SERVICE LETTER					RECOMMENDED	COMPLIED WITH
18-SEP-2002		MOS HRS/MSC AFL	A/R	01-AUG-2003 437			
SL SL750-23-12 R1	COMMUNICATIONS - INTEGRATED COMMUNICATION UNIT MOD Z SOFTWARE UPGRADE, SERVICE LETTER					RECOMMENDED	COMPLIED WITH
08-OCT-2007		MOS HRS/MSC AFL	A/R	04-JUN-2008 4505			
SL SL750-24-05	ELECTRICAL POWER - EMERGENCY POWER SPLIT BUS SWITCHING WIRING INSPECTION, SERVICE LETTER					RECOMMENDED	COMPLIED WITH
07-JUN-2007		MOS HRS/MSC AFL	A/R	04-JUN-2008 4505			
SL SL750-25-07	EQUIPMENT/FURNISHINGS - TRANSMITTAL OF GOODRICH SB 5A3204-25-329, INSTALL NEW BEACON POUCH AND PAD ON P/N 5A3204-XXX1X LIFERAFTS, SERVICE LETTER					RECOMMENDED	COMPLIED WITH
15-JAN-2003		MOS HRS/MSC AFL	A/R	01-AUG-2003 437			
SL SL750-25-15	EQUIPMENT/FURNISHINGS - TRANSMITTAL OF PACIFIC SCIENTIFIC AEROSPACE SERVICE BULLETIN SB 25-1111432, INFORMATION REGARDING THE POTENTIAL FAILURE OF THE GUARDED ROTARY BUCKLE PLASTIC HANDLE, SERVICE LETTER					MANDATORY	NOT APPLICABLE - N/A BY MANUFACTURER EFFECTIVITY
10-DEC-2007		MOS HRS/MSC AFL	A/R	07-FEB-2008 4248			
SL SL750-25-16	EQUIPMENT/FURNISHINGS - TRANSMITTAL OF WINSLOW SERVICE INFORMATION LETTER SIL001STS, SERVICE LETTER					INFORMATIONAL	NOT APPLICABLE - NOT APPLICABLE-EQUIPMENT NOT INSTALLED
18-OCT-2007		MOS HRS/MSC AFL	A/R	11-DEC-2007 4146			
SL SL750-25-19	TRANSMITTAL OF ROCKWELL COLLINS AIRSHOW 4000 SERVICE BULLETIN 30, CORRECTION OF HARD DRIVE MOUNTING SCREWS - MOD U, SERVICE LETTER					RECOMMENDED	NOT APPLICABLE - INSPECTED AIRSHOW COMPONENTS - SYSTEM INSTALLED IS A AIRSHOW 400 - THIS SL IS NOT APPLICABLE BY COMPONENT P/NS.
22-MAR-2010		MOS HRS/MSC AFL	A/R (s)	17-SEP-2011 6706.9 3089			
SL SL750-25-20	PASSENGER SEAT INSPECTION, SERVICE LETTER					MANDATORY	COMPLIED WITH
01-JUL-2010		MOS HRS/MSC AFL	A/R	06-AUG-2010 5912.8 2703			





# AD/SI Status Report

CITATION X (MSG) S/N 750-0204 (XA-KYE): 7814HRS, 3680 AFL as of 21-Aug-2015

**AIRFRAME**  
**SI with Compliance or Due**  
**Report Date: 22-Sep-2015**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL SL750-25-22	TRANSMITTAL OF GOODRICH SERVICE BULLETIN 1423-25-003 REVISION C LUMBAR ASSEMBLY CABLE WEAR, SERVICE LETTER					RECOMMENDED	NOT APPLICABLE - NOT APPLICABLE TO THIS AIRCRAFT, GOODRICH SEAT PART NUMBER 1423 NOT INSTALLED.
		MOS			17-FEB-2014		
		HRS/MSC -			7633.2		
		AFL			3575		
03-AUG-2012							
SL SL750-25-22 R1	TRANSMITTAL OF GOODRICH SERVICE BULLETIN 1423-25-003 REVISION C LUMBAR ASSEMBLY CABLE WEAR					RECOMMENDED	COMPLIED WITH - NOT APPLICABLE TO THIS AIRCRAFT, GOODRICH SEAT PART NUMBER 1423 NOT INSTALLED.
		MOS			17-FEB-2014		
		HRS/MSC -			7633.2		
		AFL			3575		
31-OCT-2012							
SL SL750-25-22 R1	TRANSMITTAL OF GOODRICH SERVICE BULLETIN 1423-25-003 REVISION C LUMBAR ASSEMBLY CABLE WEAR, SERVICE LETTER					RECOMMENDED	COMPLIED WITH - NOT APPLICABLE TO THIS AIRCRAFT, GOODRICH SEAT PART NUMBER 1423 NOT INSTALLED.
		MOS			17-FEB-2014		
		HRS/MSC -			7633.2		
		AFL			3575		
31-OCT-2012							
SL SL750-25-22	TRANSMITTAL OF GOODRICH SERVICE BULLETIN 1423-25-003 REVISION C LUMBAR ASSEMBLY CABLE WEAR					RECOMMENDED	NOT APPLICABLE - NOT APPLICABLE TO THIS AIRCRAFT, GOODRICH SEAT PART NUMBER 1423 NOT INSTALLED.
		MOS			17-FEB-2014		
		HRS/MSC -			7633.2		
		AFL			3575		
03-AUG-2012							
SL SL750-26-03	FIRE DETECT LOOP ROUTING MODIFICATION, SERVICE LETTER					RECOMMENDED	COMPLIED WITH
		MOS			12-DEC-2002		
		HRS/MSC A/R			13		
		AFL			0		
04-JUN-2002							
SL SL750-27-19	INBOARD ELEVATOR HINGE INSP, SERVICE LETTER					MANDATORY	COMPLIED WITH
		MOS			20-OCT-2006		
		HRS/MSC A/R			3315		
		AFL					
17-MAY-2006							
SL SL750-28-08	CENTER WIRING REFUEL VALVE LEVER ARM STOP INSPECTION, SERVICE LETTER					RECOMMENDED	COMPLIED WITH
		MOS			01-AUG-2003		
		HRS/MSC A/R			437		
		AFL					
15-MAY-2003							
SL SL750-28-09	WING BOOST PUMP INSPECTION, SERVICE LETTER					MANDATORY	COMPLIED WITH
		MOS			08-SEP-2005		
		HRS/MSC A/R			2359		
		AFL					
01-JUL-2005							
SL SL750-28-11	FUEL - FUEL BOOST PUMP INSPECTION, SERVICE LETTER					MANDATORY	COMPLIED WITH - IAW THE SB BOOST PUMPS RH-1, LH-3
		MOS			21-MAR-2011		
		HRS/MSC A/R			6291.4		
		AFL			2876		
03-MAR-2011							



# AD/SI Status Report

CITATION X (MSG) S/N 750-0204 (XA-KYE): 7814HRS, 3680 AFL as of 21-Aug-2015

**AIRFRAME**  
**SI with Compliance or Due**  
**Report Date: 22-Sep-2015**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL SL750-29-21	HYDRAULIC POWER - INSPECTION OF THE STALL-LINE CHECK-VALVE ON THE POWER TRANSFER UNIT (PTU), SERVICE LETTER					MANDATORY	COMPLIED WITH
23-APR-2009		MOS		06-APR-2010			
		HRS/MSC	A/R	5720			
		AFL					
SL SL750-29-23 R1	HYDRAULIC POWER - PLUG AND PRESSURE TRANSDUCER INSPECTION, SERVICE LETTER					RECOMMENDED	COMPLIED WITH - ACCOMPLISHED DURING COMPLETION OF SL750-29-23 REV1
05-MAY-2011		MOS		24-NOV-2011			
		HRS/MSC	A/R	6800.1			
		AFL		3152			
SL SL750-29-24 R1	HYDRAULIC POWER - ALTERNATE PLUG INSTALLATION WITH SAFETY WIRE					OPTIONAL	
05-MAY-2011		MOS					
		HRS/MSC	A/R				
		AFL					
SL SL750-29-24 R1	HYDRAULIC POWER - ALTERNATE PLUG INSTALLATION WITH SAFETY WIRE, SERVICE LETTER					OPTIONAL	
05-MAY-2011		MOS					
		HRS/MSC	A/R				
		AFL					
SL SL750-29-23 R1	HYDRAULIC POWER - PLUG AND PRESSURE TRANSDUCER INSPECTION					RECOMMENDED	COMPLIED WITH - ACCOMPLISHED DURING COMPLETION OF SL750-29-23 REV1
05-MAY-2011		MOS		24-NOV-2011			
		HRS/MSC	A/R	6800.1			
		AFL		3152			
SL SL750-30-06	ICE AND RAIN PROTECTION - RTD SENSOR WIRING INSPECTION AND CORRECTION, SERVICE LETTER					RECOMMENDED	COMPLIED WITH
26-JAN-2007		MOS		02-MAY-2008			
		HRS/MSC	A/R	4452			
		AFL					
SL SL750-30-07	ICE AND RAIN PROTECTION - GRAFOIL SEAL INSPECTION, SERVICE LETTER					RECOMMENDED	COMPLIED WITH
02-MAY-2007		MOS		04-JUN-2008			
		HRS/MSC	A/R	4505			
		AFL					
SL SL750-30-08	ICE AND RAIN PROTECTION - CABIN ALTITUDE/PITOT STATIC HEATER MODULE ASSEMBLY INSPECTION, SERVICE LETTER					MANDATORY	COMPLIED WITH - ACCOMPLISHED BY INSTALLING NEW HEATER MODULES NC006 AND NC007 IAW SL INSTRUCTIONS
07-JUN-2011		MOS		19-OCT-2012			
		HRS/MSC	A/R	7055.1			
		AFL		3308			



# AD/SI Status Report

CITATION X (MSG) S/N 750-0204 (XA-KYE): 7814HRS, 3680 AFL as of 21-Aug-2015

**AIRFRAME**  
**SI with Compliance or Due**  
**Report Date: 22-Sep-2015**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL SL750-30-08 R1	ICE AND RAIN PROTECTION - CABIN ALTITUDE/PITOT STATIC HEATER MODULE ASSEMBLY INSPECTION, SERVICE LETTER					MANDATORY	COMPLIED WITH - ACCOMPLISHED BY INSTALLING NEW HEATER MODULES NC006 AND NC007 IAW SL INSTRUCTIONS
11-JUL-2011		MOS HRS/MSC AFL	A/R	19-OCT-2012 7055.1 3308			
FAA 2013-04-03	CABIN ALTITUDE/PITOT STATIC HEATER MODULE					MANDATORY	COMPLIED WITH - COMPLIED WITH AD2013-04-03 PARAGRAPH G AND H IN ACCORDANCE WITH CESSNA CITATION 750 SERVICE LETTER SL750-30-08 ON THE FOLLOWING WORK ORDERS 14832, AND 15763.
39-17360 11-APR-2013		MOS HRS/MSC AFL	-	28-MAR-2013 7201 3378			
SL SL750-31-01	INDICATING/RECORDING SYSTEMS - TRANSMITTAL OF L-3 COMMUNICATIONS ALERT BULLETIN NO. CESSNA SB 001, SERVICE LETTER					MANDATORY	COMPLIED WITH - INSPECTED CVR AND FOUND TO BE SERVICABLE BY S/N ( 000167229 ) AND INSTALLATION DATE 12/12/2002. NOTE - FDR NOT INSTALLED IN THIS AIRCRAFT
04-AUG-2011		MOS HRS/MSC AFL	A/R	17-SEP-2011 6706.9 3089			
SL SL750-32-25	LANDING GEAR - TRANSMITTAL OF GOODRICH SERVICE BULLETIN 3-1537-32-2, SERVICE LETTER					RECOMMENDED	COMPLIED WITH
13-JUL-2007		MOS HRS/MSC AFL	A/R	08-JAN-2009 4915			
SL SL750-32-26	LANDING GEAR - TRANSMITTAL OF GOODRICH SERVICE BULLETIN 3-1537-32-3 INTRODUCTION OF IMPROVED THERMAL RELIEF PLUG ASSEMBLY, SERVICE LETTER					DISCRETIONARY	COMPLIED WITH
25-OCT-2007		MOS HRS/MSC AFL	A/R	08-JAN-2009 4915			
SL SL750-32-31	NOSE WHEEL STEERING CABLE INSPECTION, SERVICE LETTER					RECOMMENDED	COMPLIED WITH - ACCOMPLISHED SERVICE LETTER BY REMOVING ID SLEEVES FROM BOTH RUDDER NOSE WHEEL STEERING CABLES' LOWER TURNBUCKLES.
24-OCT-2013		MOS HRS/MSC AFL	-	18-NOV-2013 7558.3 3527			
SL SL750-33-04	AFT SIDE LEDGE DIVIDER LIGHT INSPECTION/REPLACEMENT, SERVICE LETTER					RECOMMENDED	COMPLIED WITH - COMPLIED WITH SERVICE LETTER SL750-33-04 AFT SIDELEDGE DIVIDER LIGHT INSPECTION. FOUND THAT THE PROPER PART NUMBER BULB 301 ARE INSTALLED AS PER CESSNA SERVICE BULLETIN SB750-33-16
06-AUG-2010		MOS HRS/MSC AFL	A/R	10-JUN-2013 7333.7 3435			
SL SL750-34-11	TRANSMITTAL OF HONEYWELL PUB A21-3440-001, PRIMUS 1000/2000 INTEGRATED AVIONICS SYSTEM - AZ-840/850 MICRO AIR DATA COMPUTER (MADC) - INSPECT FOR PRESENCE OF VENDOR SPECIFIC COMPONENTS AND REPLACE AS REQUIRED, SERVICE LETTER					RECOMMENDED	COMPLIED WITH - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME
27-OCT-2003		MOS HRS/MSC AFL	A/R	04-JAN-2007 3428			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks \*-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



# AD/SI Status Report

CITATION X (MSG) S/N 750-0204 (XA-KYE): 7814HRS, 3680 AFL as of 21-Aug-2015

**AIRFRAME**  
**SI with Compliance or Due**  
**Report Date: 22-Sep-2015**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL SL750-34-14	TRANSMITTAL OF HONEYWELL SB 7014700-34-0040, SERVICE LETTER					RECOMMENDED	COMPLIED WITH
30-JUL-2003		MOS HRS/MSC AFL	A/R	22-MAR-2005 1975			
SL SL750-34-15	NAVIGATION - TRANSMITTAL OF HONEYWELL SERVICE BULLETIN 965-0976-XXX-34-70, ENHANCED GROUND PROXIMITY WARNING SYSTEM (EGPWS), SERVICE LETTER					RECOMMENDED	COMPLIED WITH
03-NOV-2003		MOS HRS/MSC AFL	-	04-JAN-2007 3428			
SL SL750-34-19	ELEMENTARY SURVEILLANCE TRANSPONDER PRODUCT IMPROVEMENT, SERVICE LETTER					MANDATORY	NOT APPLICABLE - THIS MTR REPLACES MISSING MTR ENTRY FOR SL750-34-19 PREVIOUSLY ACCOMPLISHED ON 22 JAN 2007 AS NOT APPLICABLE DUE TO NON JAA/EASA AIRCRAFT.
17-MAY-2006		MOS HRS/MSC AFL	A/R	04-MAR-2014 7651.3 3586			
SL SL750-35-06	OXYGEN - TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240, SERVICE LETTER					MANDATORY	COMPLIED WITH - INSPECTED BOTH CREW O2 MASKS AND FOUND TO BE SERVICABLE BY MASK P/NS AND S/NS PILOT'S P/N MC10-16-100 S/N 98293, CO-PILOT'S P/N MC10-16-100 S/N 99578 - BOTH OVH'LD JAN 2008
02-SEP-2011		MOS HRS/MSC AFL	-	17-SEP-2011 6706.9 3089			
SL SL750-36-01	PNEUMATIC - THRUST REVERSER INSPECTION, SERVICE LETTER					RECOMMENDED	COMPLIED WITH
18-JUL-2006		MOS HRS/MSC AFL	A/R	25-AUG-2006 3173			
SL SL750-36-03	SERVICE AIR IN-LINE FILTER REMOVAL, SERVICE LETTER					RECOMMENDED	COMPLIED WITH - ACCOMPLISHED SL750-36-03 BY REMOVING IN-LINE FILTERS P/N 20666-6-500 FROM EACH SERVICE AIR PRESSURE REGULATOR OUTLET PLUMBING AS INSTRUCTED.
01-MAR-2011		MOS HRS/MSC AFL	A/R	29-SEP-2011 6731.8 3102			
SL SL750-38-01	WATER/WASTE - AFT OVERBOARD DRAIN INSPECTION, SERVICE LETTER					RECOMMENDED	COMPLIED WITH
12-APR-2007		MOS HRS/MSC AFL	A/R	16-SEP-2008 4699			
SL SL750-49-06 R1	APU TRUSS MOUNT CUP INSPECTION, SERVICE LETTER					RECOMMENDED	COMPLIED WITH
05-SEP-2003		MOS HRS/MSC AFL	A/R	07-MAR-2004 1044			



# AD/SI Status Report

CITATION X (MSG) S/N 750-0204 (XA-KYE): 7814HRS, 3680 AFL as of 21-Aug-2015

**AIRFRAME**  
**SI with Compliance or Due**  
**Report Date: 22-Sep-2015**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL SL750-49-07	TRANSMITTAL OF HONEYWELL SB GTCP36-49-7717, GAS TURBINE ENGINE - ONE TIME INSPECTION/REPLACEMENT OF THE COUPLING CLAMP, P/N 234-511-9059, T-BOLT (FUEL CONTROL TO LUBE PUMP FLANGES), SERVICE LETTER	MOS		17-MAR-2003		INFORMATIONAL	COMPLIED WITH
14-FEB-2003		HRS/MSC	A/R	185			
		AFL					
SL SL750-53-02 R1	LIGHTNING DIVERTER STRIP INSTALLATION/INSPECTION PROCEDURE CHANGE (RADOME), SERVICE LETTER	MOS		12-DEC-2002		INFORMATIONAL	COMPLIED WITH
25-APR-2001		HRS/MSC	A/R	13			
		AFL		0			
SL SL750-56-01	WINDOWS - OPENABLE COCKPIT WINDOW HINGE AND LATCH INSPECTION, SERVICE LETTER	MOS		13-OCT-2006		MANDATORY	COMPLIED WITH
30-AUG-2006		HRS/MSC	A/R	3309			
		AFL					
SL SL750-56-03	WINDOWS - OPENABLE COCKPIT WINDOW HINGE AND LATCH INSPECTION, SERVICE LETTER	MOS		16-DEC-2010		MANDATORY	NOT APPLICABLE - THE EFFECTIVITY OF THIS SERVICE LETTER IS FOR SERIAL NUMBERS 0254 THUR 0303, AND 0305. THIS SERVICE LETTER IS NOT APPLICABLE BY SERIAL NUMBER. SERIAL NUMBER OF AIRCRAFT IS 0204.
07-DEC-2010		HRS/MSC	A/R	6189.1			
		AFL		2839			
SL SL750-57-02	WINGS- OUTBOARD DRY BAY WING SEALANT INSPECTION/REMOVAL, SERVICE LETTER	MOS		17-MAR-2008		MANDATORY	COMPLIED WITH
11-SEP-2007		HRS/MSC	A/R	4346			
		AFL					
SL SL750-71-13	POWER PLANT - TRANSMITTAL OF ROLLS-ROYCE NOTICE TO OPERATORS (NTO) NUMBER AE3007C-082, SERVICE LETTER	MOS		11-APR-2007		MANDATORY	NOT APPLICABLE - N/A - OPERATOR IS CURRENTLY ENROLLED IN ROLLS- ROYCE CORP. CARE TREND MONITORING PROGRAM
06-APR-2007		HRS/MSC	A/R	3633			
		AFL					
SL SL750-72-13	RIGHT ENGINE ENGINE - TRANSMITTAL OF ROLLS-ROYCE SERVICE BULLETIN AE3007C-72-230/AE3007C-72-190, ENGINE - NEW MID-SPAN BEARING HOUSING COVER, SERVICE LETTER	MOS		22-DEC-2009		RECOMMENDED	COMPLIED WITH
28-FEB-2002		HRS/MSC	A/R	5549			
		AFL					
SL SL750-72-14	RIGHT ENGINE POWER PLANT - TRANSMITTAL OF ROLLS-ROYCE SERVICE BULLETIN AE 3007C-72-203, ENGINE - REINFORCING PLATES (23075877) FOR PLUG REPAIRED FRONT FRAME FORWARD FLANGE, SERVICE LETTER	MOS		22-DEC-2009		RECOMMENDED	COMPLIED WITH
09-JAN-2003		HRS/MSC	A/R	5549			
		AFL					
SL SL750-72-15	LEFT ENGINE ENGINE - TRANSMITTAL OF ROLLS-ROYCE SERVICE BULLETIN AE3007C-72-213 - ENGINE - ACCESSORY GEARBOX STARTER PAD DRAIN - INSTALL THE STARTER DRAIN ADAPTER, SERVICE LETTER	MOS		01-AUG-2003		RECOMMENDED	COMPLIED WITH
20-JAN-2003		HRS/MSC	A/R	437			
		AFL					

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks \*-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

# AD/SI Status Report

CITATION X (MSG) S/N 750-0204 (XA-KYE): 7814HRS, 3680 AFL as of 21-Aug-2015

**AIRFRAME**  
**SI with Compliance or Due**  
**Report Date: 22-Sep-2015**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL SL750-72-15	RIGHT ENGINE ENGINE - TRANSMITTAL OF ROLLS-ROYCE SERVICE BULLETIN AE3007C-72-213 - ENGINE - ACCESSORY GEARBOX STARTER PAD DRAIN - INSTALL THE STARTER DRAIN ADAPTER, SERVICE LETTER					RECOMMENDED	COMPLIED WITH
20-JAN-2003		MOS		22-DEC-2009			
		HRS/MSC	A/R	5549			
		AFL					
SL SL750-72-16	ENGINE - TRANSMITTAL OF ROLLS-ROYCE SERVICE BULLETIN AE 3007A-72-299/AE 3007C-72-240 R1, ENGINE - NEW RADIAL DRIVE QUILL SHAFT, SERVICE LETTER					RECOMMENDED	COMPLIED WITH
01-MAR-2005		MOS		19-MAR-2006			
		HRS/MSC	-	2800			
		AFL					
SL SL750-72-17	ENGINE - TRANSMITTAL OF ROLLS ROYCE SERVICE BULLETIN AE 3007C-72-223, ENGINE ACCESSORY GEARBOX STARTER PAD DRAIN, SERVICE LETTER					RECOMMENDED	COMPLIED WITH
19-JUL-2006		MOS		04-JAN-2007			
		HRS/MSC	A/R	3428			
		AFL					
SL SL750-72-17	RIGHT ENGINE - TRANSMITTAL OF ROLLS ROYCE SERVICE BULLETIN AE 3007C-72-223, ENGINE ACCESSORY GEARBOX STARTER PAD DRAIN, SERVICE LETTER					RECOMMENDED	COMPLIED WITH
19-JUL-2006		MOS		04-JAN-2007			
		HRS/MSC	A/R	3428			
		AFL					
SL SL750-72-18	ENGINE - TRANSMITTAL OF ROLLS-ROYCE SERVICE BULLETIN AE 3007C-72-250, ACCESSORY DRIVE GEARBOX ASSEMBLY, NEW STARTER SHAFT SEAL., SERVICE LETTER					INFORMATIONAL	COMPLIED WITH
19-JUL-2006		MOS		22-DEC-2009			
		HRS/MSC	A/R	5549			
		AFL					
SL SL750-72-18	RIGHT ENGINE - TRANSMITTAL OF ROLLS-ROYCE SERVICE BULLETIN AE 3007C-72-250, ACCESSORY DRIVE GEARBOX ASSEMBLY, NEW STARTER SHAFT SEAL., SERVICE LETTER					INFORMATIONAL	COMPLIED WITH
		MOS		04-JAN-2007			
		HRS/MSC	A/R	3428			
		AFL					
SL SL750-72-19	ENGINE - TRANSMITTAL OF ROLLS-ROYCE SERVICE BULLETIN AE 3007C-72-264, ENGINE - INSPECTION OF THE FAN SPINNER ASSEMBLY, SERVICE LETTER					RECOMMENDED	COMPLIED WITH
09-FEB-2007		MOS		04-JAN-2007			
		HRS/MSC	A/R	3428			
		AFL					



# AD/SI Status Report

CITATION X (MSG) S/N 750-0204 (XA-KYE): 7814HRS, 3680 AFL as of 21-Aug-2015

**AIRFRAME**  
**SI with Compliance or Due**  
**Report Date: 22-Sep-2015**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL SL750-72-20	LEFT ENGINE - TRANSMITTAL OF ROLLS-ROYCE SERVICE BULLETIN AE3007C-72-285 ENGINE REDESIGNED ONE PIECE SPINNER (P/N 23087826), SERVICE LETTER					MANDATORY	COMPLIED WITH - PREVIOUSLY ACCOMPLISHED SL750-72-20 REV 1, DATED JUNE 4, 2010, TRANSMITTAL OF ROLLS ROYCE SERVICE BULLETIN AE3007C-72-285, REDESIGNED ONE PIECE SPINNER (P/N 23087826)
18-DEC-2008		MOS		14-JAN-2011			
		HRS/MSC	A/R	6199.7			
		AFL		2845			
SL SL750-72-20 R1	TRANSMITTAL OF ROLLS-ROYCE SERVICE BULLETIN AE3007C-72-285 ENGINE - REDESIGNED ONE PIECE SPINNER (P/N 23087826)					RECOMMENDED	COMPLIED WITH - ACCOMPLISHED SL750-72-20 REV 1, DATED JUNE 4, 2010, TRANSMITTAL OF ROLLS ROYCE SERVICE BULLETIN AE3007C-72-285, REDESIGNED ONE PIECE SPINNER (P/N 23087826)
04-JUN-2010		MOS		14-JAN-2011			
		HRS/MSC	-	6199.7			
		AFL		2845			
SL SL750-72-20	RIGHT ENGINE - TRANSMITTAL OF ROLLS-ROYCE SERVICE BULLETIN AE3007C-72-285 ENGINE REDESIGNED ONE PIECE SPINNER (P/N 23087826), SERVICE LETTER					MANDATORY	COMPLIED WITH
18-DEC-2008		MOS		22-DEC-2009			
		HRS/MSC	A/R	5549			
		AFL					
SL SL750-72-20 R1	TRANSMITTAL OF ROLLS-ROYCE SERVICE BULLETIN AE3007C-72-285 ENGINE - REDESIGNED ONE PIECE SPINNER (P/N 23087826)					RECOMMENDED	
04-JUN-2010		MOS					
		HRS/MSC	-				
		AFL					
SL SL750-72-20 R1	LEFT ENGINE TRANSMITTAL OF ROLLS-ROYCE SERVICE BULLETIN AE3007C-72-285 ENGINE - REDESIGNED ONE PIECE SPINNER (P/N 23087826), SERVICE LETTER					RECOMMENDED	COMPLIED WITH - ACCOMPLISHED SL750-72-20 REV 1, DATED JUNE 4, 2010, TRANSMITTAL OF ROLLS ROYCE SERVICE BULLETIN AE3007C-72-285, REDESIGNED ONE PIECE SPINNER (P/N 23087826)
04-JUN-2010		MOS		14-JAN-2011			
		HRS/MSC	-	6199.7			
		AFL		2845			
SL SL750-72-20	ENGINE - TRANSMITTAL OF ROLLS-ROYCE SERVICE BULLETIN AE3007C-72-285 ENGINE REDESIGNED ONE PIECE SPINNER (P/N 23087826)					MANDATORY	COMPLIED WITH - PREVIOUSLY ACCOMPLISHED SL750-72-20 REV 1, DATED JUNE 4, 2010, TRANSMITTAL OF ROLLS ROYCE SERVICE BULLETIN AE3007C-72-285, REDESIGNED ONE PIECE SPINNER (P/N 23087826)
18-DEC-2008		MOS		14-JAN-2011			
		HRS/MSC	A/R	6199.7			
		AFL		2845			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL SL750-72-20 R1	RIGHT ENGINE TRANSMITTAL OF ROLLS-ROYCE SERVICE BULLETIN AE3007C-72-285 ENGINE - REDESIGNED ONE PIECE SPINNER (P/N 23087826), SERVICE LETTER					RECOMMENDED	
04-JUN-2010		MOS HRS/MSC - AFL					
SL SL750-72-20	ENGINE - TRANSMITTAL OF ROLLS-ROYCE SERVICE BULLETIN AE3007C-72-285 ENGINE REDESIGNED ONE PIECE SPINNER (P/N 23087826)					MANDATORY	COMPLIED WITH
18-DEC-2008		MOS HRS/MSC A/R AFL		22-DEC-2009 5549			
SL SL750-73-02	LEFT ENGINE ENGINE - TRANSMITTAL OF ROLLS/ROYCE SB AE3007C-73-028, ENGINE FUEL AND CONTROL - CLEARANCE INSPECTION BETWEEN THE FUEL MANIFOLD AND THE AFT-SUMP FORWARD PRESSURE OIL TUBE, SERVICE LETTER					RECOMMENDED	COMPLIED WITH
09-JAN-2003		MOS HRS/MSC A/R AFL		18-MAR-2003 194			
SL SL750-73-02	RIGHT ENGINE ENGINE - TRANSMITTAL OF ROLLS/ROYCE SB AE3007C-73-028, ENGINE FUEL AND CONTROL - CLEARANCE INSPECTION BETWEEN THE FUEL MANIFOLD AND THE AFT-SUMP FORWARD PRESSURE OIL TUBE, SERVICE LETTER					RECOMMENDED	COMPLIED WITH
09-JAN-2003		MOS HRS/MSC A/R AFL		18-MAR-2003 194			
SL SL750-73-03	LEFT ENGINE ENGINE FUEL AND CONTROL - TRANSMITTAL OF ROLLS ROYCE SERVICE BULLETIN AE 3007C-73-039: ENGINE FUEL AND CONTROL - REPLACE THE FUEL NOZZLES, SERVICE LETTER					RECOMMENDED	COMPLIED WITH
01-JUL-2004		MOS HRS/MSC A/R AFL		22-MAR-2005 1975			
SL SL750-73-03	RIGHT ENGINE ENGINE FUEL AND CONTROL - TRANSMITTAL OF ROLLS ROYCE SERVICE BULLETIN AE 3007C-73-039: ENGINE FUEL AND CONTROL - REPLACE THE FUEL NOZZLES, SERVICE LETTER					RECOMMENDED	COMPLIED WITH
01-JUL-2004		MOS HRS/MSC A/R AFL		22-DEC-2009 5549			
SL SL750-73-08	TRANSMITTAL OF ROLLS-ROYCE SERVICE BULLETIN AE3007C-73-036, ENGINE FUEL AND CONTROL - FUEL PUMP AND METERING UNIT - FUEL-FILTER ELECTRICAL IMPENDING-BYPASS INDICATOR INSPECTION, SERVICE LETTER					RECOMMENDED	COMPLIED WITH - ACCOMPLISHED SL750-73-08, DATED NOVEMBER 3, 2010, TRANSMITTAL OF ROLLS-ROYCE SERVICE BULLETIN AE3007C-73-036, ENGINE FUEL AND CONTROL - FUEL PUMP AND METERING UNIT - FUEL-FILTER ELECTRICAL IMPENDING-BYPASS INDICATOR INSPECTION.
03-NOV-2010		MOS HRS/MSC A/R AFL		28-JUN-2011 6563.2 3005			
SL SL750-73-08 R1	ENGINE FUEL AND CONTROL - TRANSMITTAL OF ROLLS-ROYCE SERVICE BULLETIN AE3007C-73-036, ENGINE FUEL AND CONTROL - FUEL PUMP AND METERING UNIT - FUEL-FILTER ELECTRICAL IMPENDING-BYPASS INDICATOR INSPECTION, SERVICE LETTER					RECOMMENDED	COMPLIED WITH - ORIGINAL ISSUE ACCOMPLISHED BY WICHITA SERVICE CENTER ON 6/28/11 AT 6563.2 ACFT TT / 3005 TLNDGS - NO FURTHER ACTION REQUIRED.
11-MAR-2011		MOS HRS/MSC A/R AFL		12-MAR-2012 6900.1 3211			





# AD/SI Status Report

CITATION X (MSG) S/N 750-0204 (XA-KYE): 7814HRS, 3680 AFL as of 21-Aug-2015

**AIRFRAME**  
**SI with Compliance or Due**  
**Report Date: 22-Sep-2015**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL SL750-73-09	INSPECTION AND REPLACEMENT OF THE MOTIVE FLOW FUEL PUMPS, SERVICE LETTER					RECOMMENDED	COMPLIED WITH - INSPECTED PER SL. NO MOD B PUMPS INSTALLED ON ENGINES
26-MAY-2010		MOS HRS/MSC AFL	A/R	13-SEP-2010 6001.2 2747			
SL SL750-74-01L	LEFT ENGINE IGNITION - TRANSMITTAL OF ROLLS-ROYCE SERVICE BULLETIN AE3007C-74-010 - INSPECT/REPLACE THE PERMANENT MAGNET ALTERNATOR STATOR, SERVICE LETTER					RECOMMENDED	COMPLIED WITH
12-SEP-2007		MOS HRS/MSC AFL	A/R	04-JUN-2008 4505			
SL SL750-74-01R	RIGHT ENGINE IGNITION - TRANSMITTAL OF ROLLS-ROYCE SERVICE BULLETIN AE3007C-74-010 - INSPECT/REPLACE THE PERMANENT MAGNET ALTERNATOR STATOR, SERVICE LETTER					RECOMMENDED	COMPLIED WITH
12-SEP-2007		MOS HRS/MSC AFL	A/R	22-DEC-2009 5549			
SL SL750-77-03	ENGINE INDICATING - TRANSMITTAL OF AMETEK SERVICE NEWS LETTER 172, STANBY ENGINE INDICATOR P/N 10485N03M03 AND 10485N04M03, SERVICE LETTER					RECOMMENDED	COMPLIED WITH
20-JUN-2006		MOS HRS/MSC AFL	A/R	04-JAN-2007 3428			
SL SL750-78-07	THRUST REVERSER PYLON CONNECTOR INSPECTION, SERVICE LETTER					RECOMMENDED	COMPLIED WITH
17-SEP-2002		MOS HRS/MSC AFL	A/R	12-DEC-2002 13 0			
SL SL750-78-10	RIGHT TRANSMITTAL OF ROLLS-ROYCE SERVICE BULLETIN AE3007A-78-004/AE3007C-78-004, EXHAUST - NEW FORCED CORE-TO-BYPASS MIXER (23077972), SERVICE LETTER					INFORMATIONAL	COMPLIED WITH
01-JUL-2008		MOS HRS/MSC AFL	A/R	22-DEC-2009 5549			
SL SL750-78-11	LEFT ENGINE TRANSMITTAL OF ROLLS-ROYCE SERVICE BULLETIN AE 3007C-78-006, EXHAUST - FORCED CORE-TO-BYPASS MIXER INSPECTION, SERVICE LETTER					RECOMMENDED	
14-AUG-2014		MOS HRS/MSC AFL	100	(EFF)	3688		
SL SL750-78-11	RIGHT ENGINE TRANSMITTAL OF ROLLS-ROYCE SERVICE BULLETIN AE 3007C-78-006, EXHAUST - FORCED CORE-TO-BYPASS MIXER INSPECTION, SERVICE LETTER					RECOMMENDED	
14-AUG-2014		MOS HRS/MSC AFL	100	(EFF)	3688		