

OWNER: AEROLINEAS EJECUTIVAS, S.A. DE C.V.
ADDRESS: AEROPUERTO INTERNACIONAL DE
TOLUCA
TOLUCA 50200
PHONE: +52-722-279-1600
FAX: +52-722-279-1656

OPERATOR: AEROLINEAS EJECUTIVAS, S.A. DE C.V.
ADDRESS: CALLE 2 LOTES 14-18
TOLUCA 50200
PHONE: +52-722+279-1618
FAX:

ANALYST: PATRICK EMERSON
EMAIL: PEMERSON@CESCOM.CAMPSYSTEMS.CO
M
1-866-581-2267 (OFFICE)
316-462-2442 (FAX)
WWW.CAMPSYSTEMS.COM
800-787-9749 (EFAX-CARDS)
631-980-4222 (EFAX-CARDS)
PLEASE RECORD CHANGES TO ADDRESS, LAST
ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO
CAMP.

AIRCRAFT SERIAL/REGNO: 750-0204/XA-KYE **MODEL:** CITATION X (MSG) **MANUFACTURER:** CESSNA AIRCRAFT COMPANY - WICHITA

DATES	LAST ACTUALS	CURRENT ACTUAL
CERTIFICATION DATE: 12-DEC-2002	7814 A/C HRS as of 21-AUG-2015	A/C HRS as of ___/___/___
	3680 AFL as of 21-AUG-2015	AFL as of ___/___/___
	4383 APH as of 29-JUL-2015	APH as of ___/___/___
	4951 APS as of 29-JUL-2015	APS as of ___/___/___

APU SERIAL/PART: P327/3800576-1 **MODEL:** GTCP36-150(CX) **MANUFACTURER:** HONEYWELL

INSTALLED ON 12-SEP-2009	LAST ACTUALS	CURRENT ACTUAL
0 APU HRS	4383 APU HRS as of 29-JUL-2015	APU HRS as of ___/___/___
0 APUS	4951 APUS as of 29-JUL-2015	APUS as of ___/___/___

ENGINE NO. 1 SERIAL/PART: 330439/23074408 **MODEL:** AE3007C/C1 **MANUFACTURER:** ROLLS ROYCE

INSTALLED ON 04-JUN-2008	LAST ACTUALS	CURRENT ACTUAL
4371 ENG. HRS 4505 A/C HRS	7679.9 ENG. HRS as of 21-AUG-2015	ENG. HRS as of ___/___/___
ENC	3608 ENC as of 21-AUG-2015	ENC as of ___/___/___

ENGINE NO. 2 SERIAL/PART: 330426/23074408 **MODEL:** AE3007C/C1 **MANUFACTURER:** ROLLS ROYCE

INSTALLED ON 28-APR-2011	LAST ACTUALS	CURRENT ACTUAL
5837.5 ENG. HRS 6413.9 A/C HRS	7237.5 ENG. HRS as of 21-AUG-2015	ENG. HRS as of ___/___/___
2693 ENC	3429 ENC as of 21-AUG-2015	ENC as of ___/___/___



AD/SI Status Report

CITATION X (MSG) S/N 750-0204 (XA-KYE): 7814HRS, 3680 AFL as of 21-Aug-2015

AIRFRAME
AD with Compliance or Due
Report Date: 22-Sep-2015

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
AIRFRAME - AD - 750-0204/XA-KYE							
FAA 1974-08-09 R2	LAVATORY PAPER OR LINEN WASTE RECEPTACLE FIRE PREVENTION (SUPERSEDED BY FAA AD 1974-08-09 R3)					MANDATORY	COMPLIED WITH - ACCOMPLISHED AS REQUIRED, NO FAULTS FOUND - NEXT DUE 7749 ACFT TT
29-JUL-1996		MOS HRS/MSC - AFL		11-OCT-2011 6749.9 3115			
FAA 1974-08-09 R3	LAVATORY PAPER OR LINEN WASTE RECEPTACLE FIRE PREVENTION					MANDATORY	COMPLIED WITH - ACCOMPLISHED AD BY VISUAL INSPECTION, ALL REQUIRED PLACARDS AND SILKSCREENS LEGABLE AND ASHTRAY INSTALLED. ALSO VERIFIED ALL " NO SMOKING SIGNS ILLUMINATE AND PASSENGER BRIEFING SYSTEM INSTRUCTS ABOUT NO SMOKING
28-MAR-2012		MOS HRS/MSC 1000 AFL		26-FEB-2014 7647.4 3584	8647.4	RECURRING	
FAA 1998-16-17	SEC. HORIZONTAL PITCH TRIM SY						COMPLIED WITH
		MOS HRS/MSC A/R AFL		12-DEC-2002 13 0			
FAA 2005-09-01	APU FUEL LINE INSPECTION					MANDATORY	COMPLIED WITH
10-MAY-2005		MOS HRS/MSC A/R AFL		04-JAN-2007 3428			
ASL ASL750-49-09 R2	APU FUEL LINE INSPECTION					MANDATORY	COMPLIED WITH
10-MAR-2005		MOS HRS/MSC A/R AFL		26-JUL-2006 3108			
FAA 2006-04-10	THIS AD REQUIRES INSTALLING IDENTIFICATION SLEEVES ON THE WIRES FOR THE POSITIVE AND NEGATIVE STUDS OF THE ENGINE AND/ OR (APU) FIRE EXTINGUISHING BOTTLES, AS APPLICABLE, AND RECONNECTING THE WIRES TO THE CORRECT TERMINAL STUDS.					MANDATORY	COMPLIED WITH
24-MAR-2006		MOS HRS/MSC - AFL		18-APR-2006 2855			



AD/SI Status Report

CITATION X (MSG) S/N 750-0204 (XA-KYE): 7814HRS, 3680 AFL as of 21-Aug-2015

AIRFRAME
AD with Compliance or Due
Report Date: 22-Sep-2015

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2006-23-05	INSPECT FOR CRACKS IN ELEVATOR INBOARD-HINGE BRACKETS	MOS HRS/MSC AFL	A/R	10-NOV-2006 3381		SUPERSEDED	COMPLIED WITH
FAA 2010-20-10	GENERAL VISUAL INSPECTION FOR CRACKING OF THE INBOARD-HINGE BRACKETS OF THE LEFT AND RIGHT ELEVATOR	MOS HRS/MSC AFL	A/R	14-JAN-2011 6199.7 2845		MANDATORY	COMPLIED WITH - ACCOMPLISHED AD2010-20-10 EFFECTIVE NOV 1/2010 BY MEANS OF ACCOMPLISHING SB750-27-62 REV 3 NO FURTHER ACTION REQUIRED. THIS AD2010-20-10 WAS COMPLIED WITH BY WICHITA CITATION SERVICE CENTER ON JAN 14 2011 WORK ORDER # 2-78826. WICHITA SIGN OFF THE SB750-27-62 REV 3 BUT DID NOT SIGN OFF THE AD2010-20-10.
SB 750-27-62 R3	FLIGHT CONTROLS - HORIZONTAL STABILIZER AND ELEVATOR HINGE IMPROVEMENT (COMPLIANCE OF SB 750-27-62 REMOVES INSPECTION DOCUMENT 33 REQUIREMENTS AS PER 750 CHAPTER 5) SERVICE BULLETIN	MOS HRS/MSC AFL	A/R	14-JAN-2011 6199.7 2845		MANDATORY	COMPLIED WITH - ACCOMPLISHED SB750-27-62 REV 3, DATED AUGUST 21, 2009, HORIZONTAL STABILIZER HINGE IMPROVEMENT AND ELEVATOR REPLACEMENT
21-AUG-2009							
FAA 2006-24-01	APU FUEL TUBE LEAKS	MOS HRS/MSC AFL	A/R	04-JAN-2007 3428		AIRWORTHINESS	COMPLIED WITH
06-DEC-2006							
SB 750-49-12 R1	AUXILIARY POWER - APU FUEL LINE INSTALLATION IMPROVEMENT	MOS HRS/MSC AFL	A/R	04-JAN-2007 3428		MANDATORY	COMPLIED WITH
03-AUG-2006							
FAA 2007-11-17	IDENTIFICATION OF WIRES FOR FIRE EXTINGUISHING BOTTLES	MOS HRS/MSC AFL	A/R	01-JUN-2007 3753		MANDATORY	COMPLIED WITH
06-JUL-2007							

AD/SI Status Report

CITATION X (MSG) S/N 750-0204 (XA-KYE): 7814HRS, 3680 AFL as of 21-Aug-2015

AIRFRAME
AD with Compliance or Due
Report Date: 22-Sep-2015

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2010-20-10	GENERAL VISUAL INSPECTION FOR CRACKING OF THE INBOARD-HINGE BRACKETS OF THE LEFT AND RIGHT ELEVATOR					MANDATORY	COMPLIED WITH - ACCOMPLISHED AD2010-20-10 EFFECTIVE NOV 1/2010 BY MEANS OF ACCOMPLISHING SB750-27-62 REV 3 NO FURTHER ACTION REQUIRED. THIS AD2010-20-10 WAS COMPLIED WITH BY WICHITA CITATION SERVICE CENTER ON JAN 14 2011 WORK ORDER # 2-78826. WICHITA SIGN OFF THE SB750-27-62 REV 3 BUT DID NOT SIGN OFF THE AD2010-20-10.
		MOS			14-JAN-2011		
		HRS/MSC	A/R		6199.7		
		AFL			2845		
FAA 2006-23-05	INSPECT FOR CRACKS IN ELEVATOR INBOARD-HINGE BRACKETS					SUPERSEDED	COMPLIED WITH
		MOS			10-NOV-2006		
		HRS/MSC	A/R		3381		
		AFL					
FAA 2010-20-10 (G)	GENERAL VISUAL INSPECTION FOR CRACKING OF THE INBOARD-HINGE BRACKETS OF THE LEFT AND RIGHT ELEVATOR					MANDATORY	COMPLIED WITH - ACCOMPLISHED AD2010-20-10 EFFECTIVE NOV 1/2010 BY MEANS OF ACCOMPLISHING SB750-27-62 REV 3 NO FURTHER ACTION REQUIRED. THIS AD2010-20-10 WAS COMPLIED WITH BY WICHITA CITATION SERVICE CENTER ON JAN 14 2011 WORK ORDER # 2-78826. WICHITA SIGN OFF THE SB750-27-62 REV 3 BUT DID NOT SIGN OFF THE AD2010-20-10.
		MOS					
22-NOV-2006		HRS/MSC	A/R				
		AFL					
FAA 2010-20-10 (K)	GENERAL VISUAL INSPECTION FOR CRACKING OF THE INBOARD-HINGE BRACKETS OF THE LEFT AND RIGHT ELEVATOR					MANDATORY	COMPLIED WITH - ACCOMPLISHED AD2010-20-10 EFFECTIVE NOV 1/2010 BY MEANS OF ACCOMPLISHING SB750-27-62 REV 3 NO FURTHER ACTION REQUIRED. THIS AD2010-20-10 WAS COMPLIED WITH BY WICHITA CITATION SERVICE CENTER ON JAN 14 2011 WORK ORDER # 2-78826. WICHITA SIGN OFF THE SB750-27-62 REV 3 BUT DID NOT SIGN OFF THE AD2010-20-10.
		MOS					
01-NOV-2010		HRS/MSC	A/R				
		AFL					
SB 750-27-62 R3	FLIGHT CONTROLS - HORIZONTAL STABILIZER AND ELEVATOR HINGE IMPROVEMENT (COMPLIANCE OF SB 750-27-62 REMOVES INSPECTION DOCUMENT 33 REQUIREMENTS AS PER 750 CHAPTER 5) SERVICE BULLETIN					MANDATORY	COMPLIED WITH - ACCOMPLISHED SB750-27-62 REV 3, DATED AUGUST 21, 2009, HORIZONTAL STABILIZER HINGE IMPROVEMENT AND ELEVATOR REPLACEMENT
		MOS			14-JAN-2011		
21-AUG-2009		HRS/MSC	A/R		6199.7		
		AFL			2845		



AD/SI Status Report

CITATION X (MSG) S/N 750-0204 (XA-KYE): 7814HRS, 3680 AFL as of 21-Aug-2015

AIRFRAME
AD with Compliance or Due
Report Date: 22-Sep-2015

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2011-03-16	AUXILIARY POWER UNIT (APU) GENERATOR AND LEFT AND RIGHT ENGINE 400 AMP DC GENERATORS					MANDATORY	
22-MAR-2011		MOS					
		HRS/MSC	A/R				
		AFL					
FAA 2011-03-16 (G)	AUXILIARY POWER UNIT (APU) GENERATOR AND LEFT AND RIGHT ENGINE 400 AMP DC GENERATORS					MANDATORY	NOT APPLICABLE - AD2011-03-16 SECTION "G" IS NOT APPLICABLE DUE TO SERIAL NUMBER OF AIRCRAFT.
22-MAR-2011		MOS		17-FEB-2014			
		HRS/MSC	A/R	7633.2			
		AFL		3575			
FAA 2011-03-16 (H)	AUXILIARY POWER UNIT (APU) GENERATOR AND LEFT AND RIGHT ENGINE 400 AMP DC GENERATORS					MANDATORY	COMPLIED WITH - COMPLIED WITH CHECK OF TEMPORARY AIRPLANE FLIGHT MANUAL TC 75FMA TC-R01-46 HAS BEEN INSERTED IN AIRPLANE FLIGHT MANUAL
22-MAR-2011		DAYS		11-MAR-2011			
		HRS/MSC	A/R	6317.6			
		AFL		2887			
FAA 2012-02-08	AVIATION COMMUNICATION AND SURVEILLANCE SYSTEMS (ACSS) TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) UNITS					MANDATORY	NOT APPLICABLE - AD2012-02-08 IS NOT APPLICABLE DUE THAT ACSS TCAS 2000 IS NOT INSTALLED IN THIS AIRCRAFT.
13-MAR-2012		MOS		22-MAY-2012			
		HRS/MSC	-	6971			
		AFL		3245			
SB 750-34-53 R1	TCAS 2000 INTERFERENCE LIMITING FUNCTIONALITY UPGRADE FOR SOFTWARE VERSION 7.0					MANDATORY	
26-JUN-2012		MOS					
		HRS/MSC	-				
		AFL					
SB 750-34-53 R2	NAVIGATION - TCAS 2000 INTERFERENCE LIMITING FUNCTIONALITY UPGRADE FOR SOFTWARE VERSION 7.0					MANDATORY	
24-OCT-2012		MOS					
		HRS/MSC	-				
		AFL					
FAA 2012-18-16	REPLACEMENT OF AUXILIARY POWER UNIT (APU) GENERATOR CONTROL UNIT (GCU).					MANDATORY	NOT APPLICABLE - AD2012-18-16 IS NOT APPLICABLE TO THIS AIRCRAFT SERIAL NUMBER 750-0204 DUE TO THE APPLICABILITY SERIAL NUMBERS SATED IN THE AD
24-OCT-2012		MOS		11-OCT-2012			
		HRS/MSC	-	7040.9			
		AFL		3303			
SB 750-24-30	APU GENERATOR CONTROL UNIT (GCU) IMPROVEMT					MANDATORY	COMPLIED WITH - SERVICE BULLETIN SB750-24-30 IS NOT APPLICABLE TO THIS AIRCRAFT DUE TO SERIAL NUMBEREFFECTIVITY CALL OUT IN THE SERVICE BULLETIN.
05-DEC-2011		MOS		13-FEB-2012			
		HRS/MSC	A/R	6856.9			
		AFL		3188			



AD/SI Status Report

CITATION X (MSG) S/N 750-0204 (XA-KYE): 7814HRS, 3680 AFL as of 21-Aug-2015

AIRFRAME
AD with Compliance or Due
Report Date: 22-Sep-2015

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2013-04-03	CABIN ALTITUDE/PITOT STATIC HEATER MODULE					MANDATORY	COMPLIED WITH - COMPLIED WITH AD2013-04-03 PARAGRAPH G AND H IN ACCORDANCE WITH CESSNA CITATION 750 SERVICE LETTER SL750-30-08 ON THE FOLLOWING WORK ORDERS 14832, AND 15763.
39-17360		MOS		28-MAR-2013			
11-APR-2013		HRS/MSC -		7201			
		AFL		3378			
FAA 2013-04-03 PARA G	CABIN ALTITUDE/PITOT STATIC HEATER MODULE					MANDATORY	COMPLIED WITH - COMPLIED WITH AD2013-04-03 PARAGRAPH G IN ACCORDANCE WITH CESSNA CITATION 750 SERVICE LETTER SL750-30-08 ON THE FOLLOWING WORK ORDER NUMBERS 14832, AND 15763.
11-APR-2013		MOS		28-MAR-2013			
		HRS/MSC -		7201			
		AFL		3378			
FAA 2013-04-03 PARA H	CABIN ALTITUDE/PITOT STATIC HEATER MODULE					MANDATORY	COMPLIED WITH - COMPLIED WITH AD2013-04-03 PARAGRAPH H IN ACCORDANCE WITH AD INSTRUCTIONS ON MARCH 08 2013.
11-APR-2013		MOS		28-MAR-2013			
		HRS/MSC -		7201			
		AFL		3378			
FAA 2013-04-03 PARA I	CABIN ALTITUDE/PITOT STATIC HEATER MODULE					MANDATORY	COMPLIED WITH - COMPLIED WITH AD2013-04-03 PARAGRAPH I IN ACCORDANCE WITH AD INSTRUCTIONS ON WORK ORDER NUMBER 15763.
11-APR-2013		MOS		28-MAR-2013			
		HRS/MSC -		7201			
		AFL		3378			
SL SL750-30-08 R1	ICE AND RAIN PROTECTION - CABIN ALTITUDE/PITOT STATIC HEATER MODULE ASSEMBLY INSPECTION					MANDATORY	COMPLIED WITH - ACCOMPLISHED BY INSTALLING NEW HEATER MODULES NC006 AND NC007 IAW SL INSTRUCTIONS
11-JUL-2011		MOS		19-OCT-2012			
		HRS/MSC A/R		7055.1			
		AFL		3308			
AD 71AD-03	COLD WEATHER STARTING <32'						COMPLIED WITH
		MOS		12-DEC-2002			
		HRS/MSC -		13			
		AFL		0			



AD/SI Status Report

CITATION X (MSG) S/N 750-0204 (XA-KYE): 7814HRS, 3680 AFL as of 21-Aug-2015

AIRFRAME
AD with Compliance or Due
Report Date: 22-Sep-2015

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
APPLIANCE - 750-0204/XA-KYE							
FAA 1998-25-10 R1	APPLIANCE AD - AIRCRAFT BELTS					MANDATORY	COMPLIED WITH - NOT APPLICABLE
		MOS		12-DEC-2002			
		HRS/MSC -		13			
		AFL		0			
FAA 1999-08-21	APPLIANCE AD - PURITAN BENNETT OXYGEN MASKS					MANDATORY	COMPLIED WITH - NOT APPLICABLE
		MOS		12-DEC-2002			
		HRS/MSC -		13			
		AFL		0			
FAA 2003-04-06	APPLIANCE AD - HONEYWELL PRIMUSII RNZ-850/85					MANDATORY	COMPLIED WITH
		MOS		10-MAR-2003			
		HRS/MSC -		156			
		AFL					
FAA 2003-26-14	APPLIANCE AD - KIDDE HALON FIRE BOTTLE					MANDATORY	COMPLIED WITH
		MOS		11-FEB-2004			
		HRS/MSC -		934			
		AFL					
FAA 2009-08-01	APPLIANCE AD - HONEYWELL NZ-2000 NAVIGATION COMPUTERS AND HONEYWELL IC-800					MANDATORY	NOT APPLICABLE - NOT APPLICABLE
		MOS		09-OCT-2009			
14-MAY-2009		HRS/MSC A/R		5370			
		AFL					
FAA 2010-04-16	APPLIANCE AD - TYPE H1-10 AIR HALON 1211 (BCF) PORTABLE FIRE EXTINGUISHERS MANUFACTURED BY SICLI					MANDATORY	NOT APPLICABLE - N/A BY MANUFACTURER EFFECTIVITY
		MOS		01-MAR-2010			
08-MAR-2010		HRS/MSC A/R		5645			
		AFL					
FAA 2010-07-02	APPLIANCE AD - PERFORM A ONE-TIME GENERAL VISUAL INSPECTION OF THE MODIFICATION PLATE FOR THE HONEYWELL PRIMUS II NV-850 NAVIGATION RECEIVER MODULE (NRM)					MANDATORY	COMPLIED WITH - COMPLIED WITH AD2010-07-02 ON NGAD WORK ORDER NUMBER 15833 DTED 11/09/2012
		MOS		27-MAR-2013			
03-MAY-2010		HRS/MSC A/R (s)		7201			
		AFL		3378			
SL CIL-34-02	TRANSMITTAL OF HONEYWELL SIL D201301000032, PRIMUS II INTEGRATED RADIO SYSTEM					MANDATORY	COMPLIED WITH - COMPLIED WITH MANDATORY SERVICE LETTER CIL-34-02 PRIMUS II INTEGRATED RADIO SYSTEM. FOUND NAV. 1 PART NUMBER 7510100-731 SERIAL NUMBER 9507155 AND NAV. 2 PART NUMBER 7510100-733 SERIAL NUMBER 02056554 BOTH HAVING AS MOD AND TO BE IN COMPLIANCE WITH AD2010-07-02.
		MOS		27-MAR-2013			
18-MAR-2013		HRS/MSC -		7201			
		AFL		3378			
FAA 2011-14-08	APPLIANCE AD - B/E AEROSPACE, CONTINUOUS FLOW PASSENGER OXYGEN MASK ASSEMBLY					MANDATORY	COMPLIED WITH
		MOS		17-SEP-2011			
19-AUG-2011		HRS/MSC A/R		6706.9			
		AFL		3089			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2013-18-09	APPLIANCE AD - EMERGENCY LOCATOR TRANSMITTER - BATTERY WIRING DISCREPANCIES - HONEYWELL ASCA INC (SUPERSEDED BY FAA AD 2014-17-02)					MANDATORY	NOT APPLICABLE - INSTALLED ELT IS A KANNAD P/N S1821502-02 - AD 2013-18-09 IS APPLICABLE TO HONEYWELL ASCA INC. ELTS ONLY. THIS AD IS N/A BY P/N AND MANUFACTURER INSTALLATION
03-OCT-2013		DAYS		30-SEP-2013			
		HRS/MSC	- (s)	7465.1			
		AFL		3492			
FAA 2014-18-01	APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS - INSPECTION / MODIFICATION					MANDATORY	COMPLIED WITH - ACCOMPLISHED AD2014-18-01 EFFECTIVE 10/14/2014; AFFECTED PARTS NOT INSTALLED. NO FURTHER ACTION REQUIRED.
14-OCT-2014		MOS		03-NOV-2014			
		HRS/MSC	-	7655			
		AFL		3589			