



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
120005	MAINTENANCE SERVICE INSPECTION (MSC)	PVG		DAYS 18-Oct-2019 HRS 8531.1 LDG 6809		15		02-Nov-2019	-1 m 7 d
									Over Due
5-12-01 051201	PHASE 1	KICT		MTH 20-Apr-2018 HRS 8329.5 LDG 6657		24 300		30-Apr-2020 8629.5	4 m 21 d 87.9
5-12-02 051202	PHASE 2	KICT		MTH 20-Apr-2018 HRS 8329.5 LDG 6657		24 300		30-Apr-2020 8629.5	4 m 21 d 87.9
5-12-03 051203	PHASE 3	KICT		MTH 20-Apr-2018 HRS 8329.5 LDG 6657		24 300		30-Apr-2020 8629.5	4 m 21 d 87.9
5-12-04 051204	PHASE 4	KICT		MTH 20-Apr-2018 HRS 8329.5 LDG 6657		24 300		30-Apr-2020 8629.5	4 m 21 d 87.9
5-12-05 051205	PHASE 5	KICT		MTH 20-Apr-2018 HRS 8329.5 LDG 6657		36 1200		30-Apr-2021 9529.5	16 m 21 d 987.9
5-12-0B 051200B	PHASE B	KLYH		MTH 30-Apr-2019 HRS 8443.3 LDG 6746		150		8593.3	51.7
5-12-11 051211	PHASE 11	PVG		MTH 26-Sep-2019 HRS 8520.7 LDG 6807		6		31-Mar-2020	3 m 22 d
5-12-13 051213	PHASE 13	LUK		MTH 15-Dec-2012 HRS 4724.2 LDG 3774		5000		9724.2	1182.6
5-12-14 051214	PHASE 14	*CF		MTH 19-Oct-2006 HRS 0		12000		12000	3458.4
5-12-15 051215	PHASE 15	*CF		MTH 19-Oct-2006 HRS 0		10000		10000	1458.4
5-12-16 051216	PHASE 16	*CF		MTH 19-Oct-2006 HRS 0		10000		10000	1458.4
5-12-17 051217	PHASE 17	*CF		MTH 19-Oct-2006 HRS 0		10000		10000	1458.4
5-12-18 051218	PHASE 18	PVG		MTH 26-Sep-2019 HRS 8520.7 LDG 6807		12		30-Sep-2020	9 m 21 d
A262003 CABIN 051208	INSPECT/WEIGH PORTABLE HALON FIRE EXTINGUISHER : PHASE 18	PVG	C352CS E-68636245	MTH 26-Sep-2019		12		30-Sep-2020	9 m 21 d
A262003 COCKPIT 051208	INSPECT/WEIGH PORTABLE HALON FIRE EXTINGUISHER : PHASE 18	PVG	C352CS E-68636244	MTH 26-Sep-2019		12		30-Sep-2020	9 m 21 d
5-12-20	PHASE 20 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	KICT		MTH 20-Apr-2018 HRS 8329.5 LDG 6657		24			
341068 051220 : ADU	CALIBRATION TEST SECONDARY FLIGHT ADU (91.411)	KICT	501-1890-03 1996	MTH 14-Mar-2018		24		31-Mar-2020	3 m 22 d
A341008 051220	PERFORM STATIC PORT HEIGHT AND SLOPE CHECK (AIRPLANES -0260 AND ON CERTIFIED FOR RVSM): PHASE 20	KICT		MTH 14-Mar-2018		24		31-Mar-2020	3 m 22 d
B341013 NO. 1 051220 : ADC	CALIBRATION TEST AIR DATA COMPUTER (FAR 91.411) AIRPLANES -0644 THRU -0750: PHASE 20	KICT	7030700-71703 06050983	MTH 14-Mar-2018		24		31-Mar-2020	3 m 22 d



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
B341013 NO. 2 <i>051220 : ADC#2</i>	CALIBRATION TEST AIR DATA COMPUTER (FAR 91.411) AIRPLANES -0644 THRU -0750: PHASE 20	KICT	7030700-71703 06071064	MTH 14-Mar-2018		24		31-Mar-2020	3 m 22 d
B345001 NO. 1 <i>051220 : XPDR1</i>	CALIBRATION TEST ATC TRANSPONDER (FAR 91.413): PHASE 20	KICT	7517400-932 0710D186	MTH 15-Mar-2018		24		31-Mar-2020	3 m 22 d
B345001 NO. 2 <i>051220 : XPDR2</i>	CALIBRATION TEST ATC TRANSPONDER (FAR 91.413): PHASE 20	KICT	7517400-932 03077380	MTH 15-Mar-2018		24		31-Mar-2020	3 m 22 d
5-12-21	PHASE 21 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	PVG		MTH 29-Jul-2019 HRS 8503.7 LDG 6792		24		31-Jul-2021	19 m 22 d
A237003 <i>051221 : CVR</i>	INSPECT CVR UNDERWATER LOCATOR BEACON : PHASE 21	PVG	DK120 SD17949	MTH 29-Jul-2019 HRS 8503.7 LDG 6792		24		31-Jul-2021	19 m 22 d
B237004 <i>051221 : CVR</i>	OPERATIONAL TEST CVR UNDERWATER LOCATOR BEACON : PHASE 21	PVG	DK120 SD17949	MTH 29-Jul-2019 HRS 8503.7 LDG 6792		24		31-Jul-2021	19 m 22 d
5-12-30 <i>051230</i>	PHASE 30	KCMH		MTH 16-Jul-2017 HRS 8327 LDG 6656		600		8927	385.4
5-12-32 <i>051232</i>	PHASE 32	*CF		MTH 19-Oct-2006 LDG 0		15000		15000	8182
5-12-33 <i>051233</i>	PHASE 33	*CF		MTH 19-Oct-2006 LDG 0		15000		15000	8182
5-12-34 <i>051234</i>	PHASE 34			MTH 05-Dec-2014 HRS 6314.5 LDG 5067		6725		13039.5	4497.9
5-12-48	PHASE 48 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)			MTH 19-Oct-2006		72			
B262004 CABIN <i>051248 : A</i>	EMPTY/INSPECT/RECHARGE PORTABLE HALON FIRE EXTINGUISHER : PHASE 48	KICT	C352CS E-68636245	MTH 24-Apr-2018 HRS 8330.5 LDG 6658		72		30-Apr-2024	52 m 21 d
B262004 COCKPIT <i>051248 : F</i>	EMPTY/INSPECT/RECHARGE PORTABLE HALON FIRE EXTINGUISHER : PHASE 48	KICT	C352CS E-68636244	MTH 24-Apr-2018 HRS 8330.5 LDG 6658		72		30-Apr-2024	52 m 21 d
5-12-49 <i>051249 : 1ST</i>	PHASE 49	KCMH		MTH 16-Jul-2017 HRS 8327 LDG 6656		36 1200		31-Jul-2020 9527	7 m 22 d 985.4
5-12-54	PHASE 54	KLYH		MTH 30-Apr-2019 HRS 8443.3 LDG 6746		12 600		30-Apr-2020 9043.3	4 m 21 d 501.7
5-12-55	PHASE 55 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)			MTH 12-Jul-2019 HRS 8498.5 LDG 6788		12 600		31-Jul-2020 9098.5	7 m 22 d 556.9
D243003	INSPECT MAIN SHIP BATTERY LEAD ACID BATTERY: PHASE 55		RG-380E/44LA2 41014221	MTH 12-Jul-2019 HRS 8498.5 LDG 6788		12 600		31-Jul-2020 9098.5	7 m 22 d 556.9
5-12-56 <i>051256</i>	PHASE 56	KLYH		MTH 30-Apr-2019 HRS 8443.3 LDG 6746		12		30-Apr-2020	4 m 21 d



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
5-12-59	PHASE 59 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)								
				MTH 19-Oct-2006		A/R			
				HRS 0					
				LDG 0					
A561004 RIGHT INBOARD	PERFORM CO-PILOTS INNER WINDOW COPILOT SIDE WINDOW INSPECTION : PHASE 59		5511285-6 NSN	MTH 19-Oct-2006		A/R			
A561004 RIGHT OUTBOARD	PERFORM CO-PILOTS OUTER WINDOW COPILOT'S SIDE WINDOW INSPECTION : PHASE 59		5511285-48 NSN	MTH 19-Oct-2006		A/R			
5-12-61	PHASE 61			MTH 19-Oct-2006					
				HRS 0		13200		13200	4658.4
5-12-62	PHASE 62			MTH 19-Oct-2006					
				HRS 0		15600		15600	7058.4
5-12-63	PHASE 63			MTH 19-Oct-2006					
				HRS 0		15600		15600	7058.4
5-12-64	PHASE 64	PVG		MTH 26-Sep-2019		6		31-Mar-2020	3 m 22 d
				HRS 8520.7					
				LDG 6807					
5-12-65	PHASE 65	KICT		MTH 24-Apr-2018					
				HRS 8330.5					
				LDG 6658					
				ACH 3111		500		3611	500
5-12-66	PHASE 66			MTH 16-Dec-2015					
				HRS 7143.8		6000		13143.8	4602.2
				LDG 5715					
5-12-67	PHASE 67			MTH					
				HRS		10000		10000	1458.4
5-12-MA 0512MA	PHASE MA	KLYH		MTH 30-Apr-2019					
				HRS 8443.3		150		8593.3	51.7
				LDG 6746					
5-12-MC 0512MC	PHASE MC	KCMH		MTH 16-Jul-2017					
				HRS 8327		1456		9783	1241.4
				LDG 6656					
5-12-MD 0512MD	PHASE MD	*CF		MTH 11-Dec-2015					
				HRS 7143.8		2523		9666.8	1125.2
5-12-ME 0512ME	PHASE ME	KLUK		MTH 13-Jun-2012					
				HRS 4363.3		4450		8813.3	271.7
				LDG 3468					
5-12-MF 0512MF	PHASE MF	*CF		MTH 17-Dec-2012					
				HRS 4724.2		5000		9724.2	1182.6
5-12-MG	PHASE MG (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)								
				MTH 19-Oct-2006					
				LDG 0		10000			
A325009 0512MG	INSPECT NOSE GEAR FORK/PISTON NOSE LANDING GEAR FORK: PHASE MG		6642000-209 26426171A	MTH 09-Jan-2017					
				HRS 7959.7					
				LDG 6366		10000		16366	9548
5-12-MI 0512MI	PHASE MI	*CF		MTH 17-Dec-2012					
				HRS 4724.2		5130		9854.2	1312.6
5-12-MJ 0512MJ	PHASE MJ	*CF		MTH 20-Dec-2013					
				HRS 5530		5900		11430	2888.4
5-12-MK 0512MK	PHASE MK	*CF		MTH 09-Dec-2014					
				HRS 6314.5		6725		13039.5	4497.9
5-12-ML	PHASE ML	KCMH		MTH 16-Jul-2017					
				HRS 8327		300		8627	85.4
				LDG 6656					



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
790040 E1	INSTALL NEW OIL FILTER UNK	UNK	MTH HRS LDG	31-Dec-2017 8328.5 6657		24 900		31-Dec-2019 (10776.1)9228.5	22 d 686.9
790040 E2	INSTALL NEW OIL FILTER UNK	UNK	MTH HRS LDG	24-Dec-2017 8328.1 6657		24 900		31-Dec-2019 (10773)9228.1	22 d 686.5
051254 E1	MINOR INSPECTION KLYH	KLYH	MTH HRS LDG	26-Dec-2018 8398 6717		12 600		31-Dec-2019 (10495.62)8998	22 d 456.4
051254 E2	MINOR INSPECTION KLYH	KLYH	MTH HRS LDG	26-Dec-2018 8398 6717		12 600		31-Dec-2019 (10492.9)8998	22 d 456.4
081251 082001	WEIGHT AND BALANCE EMPTY AIRCRAFT KICT		MTH HRS LDG	24-Apr-2018 8330.5 6658		36		30-Apr-2021	16 m 21 d
215012	REPLACE MOTOR COMPRESSOR DRIVE MOTOR BRUSHES (COMPRESSOR MOTORS P/N 1134104-1, -5 OR FWA1134104-1, -5 ONLY) KCMH		1134104-5 6026	MTH HRS LDG ACH	21-Jul-2017 8327 6656 3111		500	3611	500
263005 FORWARD LEFT 262003 : FL	REPLACE FORWARD LEFT (SERVICE LIFE) CARTRIDGE *CF		13083-5 ESD15D590-001	MTH	11-Dec-2015		72 8	30-Apr-2021	16 m 21 d
263007 FORWARD RIGHT 262003 : FR	REPLACE FORWARD RIGHT (SERVICE LIFE) CARTRIDGE *CF		13083-5 ESD15D590-001	MTH	11-Dec-2015		72 8	30-Apr-2021	16 m 21 d
263009 AFT LEFT 262003 : AL	REPLACE AFT LEFT (SERVICE LIFE) CARTRIDGE *CF		13083-5 ESD15D590-001	MTH	11-Dec-2015		72 8	30-Apr-2021	16 m 21 d
263011 AFT RIGHT 262003 : AR	REPLACE AFT RIGHT (SERVICE LIFE) CARTRIDGE *CF		13083-5 ESD15B579-001	MTH	11-Dec-2015		72 10	28-Feb-2021	14 m 19 d
B262002 AFT 051223 : A	HYDROSTATIC TEST ENGINE FIRE BOTTLE		30401102 44084B1	MTH	01-Jun-2015		60	30-Jun-2020	6 m 21 d
B262002 FORWARD 051223 : F	HYDROSTATIC TEST ENGINE FIRE BOTTLE		30401102 43752B1	MTH	01-Jun-2015		60	30-Jun-2020	6 m 21 d
B262003 CABIN 051247 : A	HYDROSTATIC TEST PORTABLE HALON FIRE EXTINGUISHER KICT		C352CS E-68636245	MTH	24-Apr-2018		144	30-Apr-2030	124 m 21 d
B262003 COCKPIT 051247 : F	HYDROSTATIC TEST PORTABLE HALON FIRE EXTINGUISHER KICT		C352CS E-68636244	MTH	24-Apr-2018		144	30-Apr-2030	124 m 21 d
324201 LEFT	NON DESTRUCTIVE TEST MLG WHEEL ASSEMBLY KICT		3-1607-1 0182	MTH HRS LDG	25-Oct-2018 8363.9 6691		T/C		
324201 RIGHT	NON DESTRUCTIVE TEST MLG WHEEL ASSEMBLY		3-1607-1 0261	MTH HRS LDG	13-Nov-2016 7852.1 6279		T/C		
324202	NON DESTRUCTIVE TEST NOSE WHEEL ASSEMBLY		3-1418 6566	MTH			T/C		
B326003 051222 : GEAR	HYDROSTATIC TEST PNEUMATIC BLOWDOWN/EMERGENCY BRAKE BOTTLE		212940-2 1532	MTH	01-Oct-2016		36	31-Oct-2019	-1 m 9 d

Over Due



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
350004 051222 : OXY	HYDROSTATIC TEST OXYGEN CYLINDER	KCMH		176176-64 1376-1960067	MTH 22-Mar-2017		36		31-Mar-2020	3 m 22 d
710015 E1	PERFORM RECOVERY WASH				MTH		A/R			
710015 E2	PERFORM RECOVERY WASH				MTH		A/R			
710050 E1	DO A FIVE POINT PERFORMANCE UNCAPPED CALIBRATION RUN	KLYH			MTH 26-Dec-2018 HRS 8398 LDG 6717		12 600		31-Dec-2019 (10495.6)8998	22 d 456.4
710050 E2	DO A FIVE POINT PERFORMANCE UNCAPPED CALIBRATION RUN	KLYH			MTH 26-Dec-2018 HRS 8398 LDG 6717		12 600		31-Dec-2019 (10492.9)8998	22 d 456.4
710060 E1 057106 : E1**L	DISCONNECT EACH WIRING HARNESS CONNECTOR, CLEAN, INSPECT, RECONNECT AND PERFORM ENGINE CHECKS REQUIRED FOLLOWING WIRING HARNESS REPLACEMENT	UNK			MTH 31-Dec-2017 HRS 8329.5 LDG 6657		900		(10776.1)9229.5	687.9
710060 E2 057106 : E2**R	DISCONNECT EACH WIRING HARNESS CONNECTOR, CLEAN, INSPECT, RECONNECT AND PERFORM ENGINE CHECKS REQUIRED FOLLOWING WIRING HARNESS REPLACEMENT	UNK			MTH 24-Dec-2017 HRS 8329.5 LDG 6657		900		(10773)9229.5	687.9
720010 E1 710001 : E1**L	OVERHAUL ENGINE	KICT			MTH 30-Jan-2018 HRS 8328.5 LDG 6657		5000		(14876.1)13328.5	4786.9
720010 E2 710001 : E2**R	OVERHAUL ENGINE	KICT			MTH 30-Jan-2018 HRS 8328.1 LDG 6657		5000		(14873)13328.1	4786.5
720020 E1 057120 : E1**L	INSPECTION LOW UTILIZATION	KICT			MTH 30-Jan-2018 HRS 8328.5 LDG 6648		120		31-Jan-2028	97 m 22 d
720020 E2 057120 : E2**R	INSPECTION LOW UTILIZATION	KICT			MTH 30-Jan-2018 HRS 8328.1 LDG 6657		120		31-Jan-2028	97 m 22 d
720060 E1 051225A : E1**L	HOT SECTION INSPECTION	KICT			MTH 30-Jan-2018 HRS 8329.5 LDG 6657		2500		(12376.1)10829.5	2287.9
720060 E2 051225A : E2**R	HOT SECTION INSPECTION	KICT			MTH 30-Jan-2018 HRS 8329.5 LDG 6657		2500		(12373)10829.5	2287.9
724050 E1	DISCARD HIGH PRESSURE TURBINE BLADES	UNK		3076231-01 SN-UNKNOWN	MTH 31-Dec-2017 HRS 8329.5 LDG 6657		-			
724050 E2	DISCARD HIGH PRESSURE TURBINE BLADES				MTH 30-Sep-2016 HRS 7714.2 LDG 6181		-			
725060 E1	DISCARD TURBINE SUPPORT CASE				MTH 10-Feb-2004 LDG -1197		12200		(12200)11003	4185
725060 E2	DISCARD TURBINE SUPPORT CASE				MTH 10-Feb-2004 LDG -1186		12200		(12200)11014	4196
731030 E1 052803 : E1**L	INSTALL NEW FUEL FILTER	UNK			MTH 31-Dec-2017 HRS 8329.5 LDG 6657		24 900		31-Dec-2019 (10776.1)9229.5	22 d 687.9
731030 E2 052803 : E2**R	INSTALL NEW FUEL FILTER	UNK			MTH 24-Dec-2017 HRS 8329.5 LDG 6657		24 900		31-Dec-2019 (10773)9229.5	22 d 687.9



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
731100 E1 <i>052805 : E1**L</i>	INSPECT EMERGENCY FUEL SHUTOFF LEVER AND CABLE	UNK	MTH HRS LDG	31-Dec-2017 8329.5 6657		24 900		31-Dec-2019 (10776.1)9229.5	22 d 687.9
731100 E2 <i>052805 : E2**R</i>	INSPECT EMERGENCY FUEL SHUTOFF LEVER AND CABLE	UNK	MTH HRS LDG	24-Dec-2017 8329.5 6657		24 900		31-Dec-2019 (10773)9229.5	22 d 687.9
731110 E1	DIMENSIONAL CHECK EMERGENCY FUEL SHUTOFF PIN	UNK	MTH HRS LDG	31-Dec-2017 8329.5 6657		A/R			
731110 E2	DIMENSIONAL CHECK EMERGENCY FUEL SHUTOFF PIN	UNK	MTH HRS LDG	24-Dec-2017 8329.5 6657		A/R			
731120 E1	REPLACE FUEL MANIFOLD ASSEMBLY /INSPECT WITH BOROSCOPE FUEL MANIFOLD	TOL	PN SN-UNKNOWN	MTH HRS LDG	28-Sep-2016 7714.6 6172		N/A		
731120 E2	REPLACE FUEL MANIFOLD ASSEMBLY /INSPECT WITH BOROSCOPE FUEL MANIFOLD	UNK	PN SN-UNKNOWN	MTH HRS LDG	21-Mar-2014 5807.3 4626		N/A		
731150 E1	OVERHAUL OR REFURBISH FLOW DIVIDER FLOW DIVIDER	KICT	823660-02 F57352	MTH HRS LDG	30-Jan-2018 8328.5 6657	5000		(14876.1)13328.5	4786.9
731150 E2	OVERHAUL OR REFURBISH FLOW DIVIDER FLOW DIVIDER	KICT	823660-02 F57531	MTH HRS LDG	30-Jan-2018 8328.1 6657	5000		(14873)13328.1	4786.5
731200 E1	OVERHAUL/REFURBISH FUEL NOZZLES	KICT		MTH HRS LDG	30-Jan-2018 8328.5 6657	5000		(14876.1)13328.5	4786.9
731200 E2	OVERHAUL/REFURBISH FUEL NOZZLES	KICT		MTH HRS LDG	30-Jan-2018 8328.1 6657	5000		(14873)13328.1	4786.5
732150 E1	OVERHAUL - FUEL CONTROL UNIT AND PUMP	UNK	1012633-35 F83842	MTH HRS LDG	30-Jan-2018 8328.5 6657	5000		(14876.1)13328.5	4786.9
732150 E2	OVERHAUL - FUEL CONTROL UNIT AND PUMP	UNK	1012633-35 F65189	MTH HRS LDG	30-Jan-2018 8328.1 6657	5000		(14873)13328.1	4786.5
750100 E1	OVERHAUL OR REFURBISH ANTI-ICING VALVE	KICT		MTH HRS LDG	30-Jan-2018 8328.5 6657	5000		(14876.1)13328.5	4786.9
750100 E2	OVERHAUL OR REFURBISH ANTI-ICING VALVE	KICT		MTH HRS LDG	30-Jan-2018 8328.1 6657	5000		(14873)13328.1	4786.5
751030 E1	REPLACE INTERCOMPRESSORBLEEDVALVE SERVOVALVE	UNK	3075987-01 TR9471	MTH HRS LDG	31-Dec-2017 8329.5 6657	-			
751030 E2	REPLACE INTERCOMPRESSORBLEEDVALVE SERVOVALVE			MTH HRS LDG	07-Jan-2013 4851.8 3841	-			



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
790020 E1	CHANGE OIL			MTH 27-Aug-2008 HRS 2288.4		A/R			
790020 E2	CHANGE OIL			MTH 27-Aug-2008 HRS 2291.1		A/R			
790030 E1	MONITOR OIL QUALITY			MTH 10-Feb-2004		O/C			
790030 E2	MONITOR OIL QUALITY			MTH 10-Feb-2004		O/C			
790060 E1	FUEL TO OIL HEAT EXCHANGER - OVERHAUL OR REFURBISH KICT			MTH 30-Jan-2018 HRS 8328.5 LDG 6657		5000		(14876.1)13328.5	4786.9
790060 E2	FUEL TO OIL HEAT EXCHANGER - OVERHAUL OR REFURBISH KICT			MTH 30-Jan-2018 HRS 8328.1 LDG 6657		5000		(14873)13328.1	4786.5



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
211002	EMERGENCY PRESSURE VALVE *CF			4713-24 1033	MTH 19-Oct-2006		O/C			
212004	OVERHEAD CABIN FAN VNY			9912323-2 3488A	MTH 04-Apr-2017 HRS 8130.4 LDG 6501		1000	0 0	9130.4	588.8
212006	COCKPIT DEFOGGER FAN 9918002-1 *CF			BC64A-2 228	MTH 19-Oct-2006		O/C			
212009	FLOW DIVIDER CABIN UNDERFLOOR ACTUATOR *CF			NYLC50466-2 060501	MTH 19-Oct-2006		O/C			
212011 AFT	TEMP DUCT SENSOR 9912085-3 *CF			27221274 9BA396	MTH 19-Oct-2006		O/C			
212011 FORWARD	TEMP DUCT SENSOR 9912085-3 *CF			27221274 5BB278	MTH 19-Oct-2006		O/C			
213001	CABIN PRESSURE INDICATOR 3001J73 *CF			C668511-0106 23327	MTH 19-Oct-2006		O/C			
213005 NO. 1	MASS FLOW CONTROL VALVE UNK			1H124-12 7BD35	MTH 08-Jun-2018		O/C	12		
213005 NO. 2	MASS FLOW CONTROL VALVE KICT			1H124-12 10AT36	MTH 20-Apr-2018 HRS 8329.5 LDG 6657		O/C			
213006	CABIN ALTITUDE CONTROLLER 9912409-13 SMF		F	52770-116 2824	MTH 29-Jun-2011 HRS 3636.7 LDG 2870		O/C	0 0		
213007 NO. 1	PRIMARY OUTFLOW VALVE 9912409-17 KMCO			52771-318 925	MTH 03-Sep-2016 HRS 7700.2 LDG 6159 ACH 2264.4		O/C	6 0		
213007 NO. 2	SECONDARY OUTFLOW VALVE 9912409-8 *CF			52772-112 1168	MTH 19-Oct-2006		O/C			
213008	MANUAL TOGGLE VALVE 9912409-4 *CF		A	52773-001 1908	MTH 19-Oct-2006		O/C			
215001	ACM REFRIGERATOR PACKAGE ASSEMBLY *CF			782343-5 2006070177	MTH 19-Oct-2006		O/C			
215004	AIR CYCLE MACHINE			738384-26 9705102	MTH 20-Dec-2013 HRS 5530 LDG 4424		5000	0 0	10530	1988.4
RECOMMENDED ECONOMIC OVERHAUL PERIOD DEFINED BY HAMILTON STANDARD.										
215005	ACM BYPASS VALVE KBFI			754751-2 791827	MTH 27-May-2017 HRS 8248.4 LDG 6593		O/C	0 0 0		
215008	DUCT OVERHEAT SENSOR *CF			1173T42-1 3731	MTH 19-Oct-2006		O/C			
215009	ACM OVERHEAT SWITCH KMCO			746833-1 2423	MTH 07-Apr-2019 HRS 8443.3 LDG 6745		O/C	0 0		
215016	AC COMPRESSOR			1134160 UNK5	MTH 11-Jun-2016 HRS 7518.9 LDG 5992		O/C	0 0 0		
215017	AC CONDENSER 9912459-1 *CF			1134400-17 661	MTH 19-Oct-2006		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
215021	MOTOR	KMKE		1134104-5 6026	MTH 09-Sep-2016 HRS 7711.2 LDG 6165 ACH 2569.2		O/C	0 0		
215022	AFT EVAPORATOR	*CF		1134240-3 927	MTH 19-Oct-2006		O/C			
215023	FWD EVAPORATOR	KMKE		1134240-23 370	MTH 07-Mar-2017 HRS 8055 LDG 6442 ACH 2611.3		O/C	0 0		
215024	PRESSURE SWITCH	KICT		1250232-4 11773	MTH 20-Apr-2018 HRS 8329.5 LDG 6657		O/C	0 0		
215025	BAROMETRIC SWITCH	*CF		GBC300-82 0534504	MTH 19-Oct-2006		O/C			
216001	CABIN TEMPERATURE SENSOR	BWI		1942T100-11 1615	MTH 22-Jun-2017 HRS 8296.7 LDG 6631		O/C	0 0 0		
216002	CABIN TEMPERATURE CONTROLLER	KBZN		754661-5 9912069-22 98091207	MTH 08-Jun-2017 HRS 8256.6 LDG 6600		O/C			
216003	DUCT TEMPERATURE SENSOR	*CF		754691-3 9912069-14 N04141	MTH 19-Oct-2006		O/C			
216010	DOOR ACTUATOR MOTOR ASSEMBLY	*CF		5A3032 9910059-3 NSN	MTH 19-Oct-2006		O/C			
217001	WATER SEPARATOR	*CF		738386-3 9912069-13 2006071162	MTH 19-Oct-2006		O/C			
221009	AUTOPILOT CONTROL	GSO		7003897-923 PC-400 00082040	MTH 10-Dec-2009 HRS 2400		O/C		457	
221010 AILERON	SERVO	*CF		4006719-921 06029944	MTH 19-Oct-2006		O/C			
221010 ELEVATOR	SERVO	GSO		4006719-919 79053529	MTH 06-Jan-2014 HRS 5575.5 LDG 4455		O/C			
221010 RUDDER	SERVO	LGB		4006719-921 0611H462	MTH 07-Aug-2008 HRS 1641		O/C		426	
231003	KTR953 HF RECEIVER/EXCITER	UNK	9	064-01015-0001 KTR-953 34622	MTH 08-Jun-2018		O/C			
231004	KAC952 HF POWER AMP COUPLER	KICT	13	064-01017-0001 KAC-952 19581	MTH 20-Apr-2018 HRS 8329.5 LDG 6657		O/C			
231005	KCU951/KFS594 HIGH FREQUENCY CONTROLLER	UNK	8	071-01274-0002 KFS-594 5931	MTH 08-Jun-2018		O/C			
231007	KA594 HIGH FREQUENCY ADAPTER	*CF	3	071-01268-0001 KA-594 5090	MTH 19-Oct-2006		O/C			
232002 NO. 2	VHF COMM ANTENNA	ICT		21-38-1RF/36 50297	MTH 16-Aug-2013 HRS 5251.1 LDG 4190		O/C	0 0 0		



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
232003 NO. 1	VHF COMM ANTENNA			VF10-108-6 0245	MTH 28-Feb-2016 HRS 7280.7 LDG 5811		O/C	0 0 0		
232003	AFIS ANTENNA	KHOU		21-38-1RF/36 50148	MTH 13-Aug-2013 HRS 5249.6 LDG 4189		O/C			
232004	TRANSCEIVER PHONE			724855-801 MSA0634	MTH 09-Dec-2014 HRS 6314.5 LDG 5067		O/C			
232005 CABIN	HANDSET PHONE			725729-815BK MX46297	MTH 04-Oct-2007 HRS 833.4 LDG 648		O/C			
232006 COCKPIT	HANDSET PHONE			725729-815BK MX44575	MTH 09-Dec-2014 HRS 6314.5 LDG 5067		O/C			
232007	PHONE ANTENNA	*CF		DMNI29-18-1 3384	MTH 19-Oct-2006		O/C			
232008 NO. 1	VHF INTEGRATED CONTROL UNIT	KICT	AV	7510733-666 0710B677	MTH 20-Apr-2018 HRS 8329.5 LDG 6657		O/C			
232008 NO. 2	VHF INTEGRATED CONTROL UNIT	KICT	AV	7510733-666 03078272	MTH 20-Apr-2018 HRS 8329.5 LDG 6657		O/C			
232010 NO. 1	VHF COMMUNICATION TRANSCEIVER TR-833	KICT		7510763-901 0710B844	MTH 20-Apr-2018 HRS 8329.5 LDG 6657		O/C			
232010 NO. 2	VHF COMMUNICATION TRANSCEIVER TR-833	KICT		7510763-901 03065717	MTH 20-Apr-2018 HRS 8329.5 LDG 6657		O/C			
232013 NO. 1	COMM CLUSTER MODULE	KICT	L	7510784-839 0709B997	MTH 20-Apr-2018 HRS 8329.5 LDG 6657		O/C			
232013 NO. 2	COMM CLUSTER MODULE	KICT	L	7510784-839 03058805	MTH 20-Apr-2018 HRS 8329.5 LDG 6657		O/C			
232018	CDBR REPEATER	*CF		724864-801 MSW0915	MTH 19-Oct-2006		O/C			
232019	MAGNASTAR DUPLEXER	*CF		620317-2 01670	MTH 19-Oct-2006		O/C			
232020	CABIN ALERTER SWITCH	*CF		725256-801 MSL0746	MTH 19-Oct-2006		O/C			
235001 NO. 1	AUDIO AMPLIFIER AV-850A	*CF	AC	7511001-915 0604B030	MTH 19-Oct-2006		O/C			
235001 NO. 2	AUDIO AMPLIFIER AV-850A	*CF	AC	7511001-915 0604B031	MTH 19-Oct-2006		O/C			
237001	COCKPIT VOICE RECORDER FA2100		7	2100-1020-02 000596526	MTH 17-Mar-2013 HRS 4953.6 LDG 3948		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
237004	CVR CONTROLLER	*CF		S251-1120-00 000393278	MTH 19-Oct-2006		O/C			
237006	CVR UNDERWATER LOCATOR BEACON 266-E0305-00			DK120 SD17949	MTH 16-Jun-2013 HRS 5133 LDG 4097		O/C	0 0 0		
237006A	REPLACE ULB (CVR) BATTERY PVG			810-2007/K AUG/2025	MTH 29-Jul-2019 HRS 8503.7 LDG 6792		DUE DUE DUE DUE	0	31-Aug-2025	68 m 22 d
Expiration Date: 31-Aug-2025										
237010	CVR IMPACT SWITCH	*CF		6895-D-2-X-5-5 6037	MTH 19-Oct-2006		O/C			
242001 NO. 1	STATIC INVERTER			PC251-123H 11920	MTH 19-Nov-2016 HRS 7856.5 LDG 6283		O/C			
242001 NO. 2	STATIC INVERTER			PC-251-123H 13290	MTH 22-Dec-2013 HRS 5530 LDG 4424		O/C			
243001 LEFT	STARTER/GENERATOR 9912125-5			300SGL129Q-2 6097XL	MTH 08-Jan-2017 HRS 7959.7 LDG 6366		1000	0 0 0	8959.7	418.1
243001 RIGHT	STARTER/GENERATOR 9912125-5			300SGL129Q-2 5895XL	MTH 08-Jan-2017 HRS 7959.7 LDG 6366		1000	0 0 0	8959.7	418.1
243003 NO. 1	GENERATOR CONTROL UNIT KSBN			51525-001F Y11044	MTH 13-Jan-2015 HRS 6355.9 LDG 5097		O/C			
243003 NO. 2	GENERATOR CONTROL UNIT TIST			51525-001F P6457	MTH 16-Jan-2015 HRS 6361.6 LDG 5101		O/C	0 0		
243004 NO. 1	AMMETER	*CF		C662501-0104 E0610547	MTH 19-Oct-2006		O/C			
243004 NO. 2	AMMETER	*CF		C662501-0104 B0611379	MTH 19-Oct-2006		O/C			
243005	DC VOLTMETER	*CF		C662502-0101 E0610791	MTH 19-Oct-2006		O/C			
243007	MAIN SHIP BATTERY S3597-4	PVG		RG-380E/44LA2 41014221	MTH 12-Jul-2019 HRS 8498.5 LDG 6788		O/C	0 0		
243008	BATTERY TEMP MONITOR- *CF			1529-1 4584	MTH 19-Oct-2006		O/C			
243009	BATTERY TEMP GAGE			1229-1 1921	MTH 17-Oct-2009 HRS 2333.1 LDG 1865		O/C	0 0 0		
243015	BATTERY DISCONNECT RELAY KLUK			A-876K CD-46854	MTH 02-Feb-2017 HRS 7996.3 LDG 6399		O/C			
243016	CURRENT/VOLTAGE SENSOR *CF			1645-1-3 3942	MTH 19-Oct-2006		O/C			
245002	CABIN ALTITUDE SWITCH 9910095-6	*CF		GB300NA161 0610423	MTH 19-Oct-2006		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
251006	CABIN DISPLAY SYSTEM MONITOR-			15001-00300 135367	MTH 26-Apr-2015 HRS 6624.7 LDG 5289		O/C	0 0 0		
252012	ARINC 429 COMPUTER			90006-003 133818	MTH 15-May-2013 HRS 5067.3 LDG 4036		O/C			
252015	PBE			PN SN-UNKNOWN	MTH 19-Oct-2006		-	0		
256002	EMERGENCY LOCATOR TRANSMITTER C406-2			453-5000-366 210-10835	MTH 30-Apr-2019 HRS 8443.3 LDG 6746		O/C			
256003	EMERGENCY LOCATOR TRANSMITTER BEACON BATTERY			452-0133 380204-002	MTH 30-Apr-2019 HRS 8443.3 LDG 6746		DUE DUE DUE DUE		01-Feb-2024	49 m 23 d
256004 NO. 1	ELT ANTENNA	*CF		DMQ18-3 11413	MTH 19-Oct-2006		O/C			
256006	COFFEE POT			81319A0500G1100 780/72278	MTH 09-Sep-2016 HRS 7711.2 LDG 6165		O/C			
256010 NO. 10	LIFE VEST			P01074-207 841773	MTH 18-Dec-2015 HRS 7143.8 LDG 5715		60	0 0 0	31-Dec-2020	12 m 22 d
256010 NO. 1	LIFE VEST			P01074-207 912893	MTH 18-Dec-2015 HRS 7143.8 LDG 5715		60	0 0 0	31-Dec-2020	12 m 22 d
256010 NO. 2	LIFE VEST			P01074-207 899662	MTH 18-Dec-2015 HRS 7143.8 LDG 5715		60	0 0 0	31-Dec-2020	12 m 22 d
256010 NO. 3	LIFE VEST			P01074-207 899719	MTH 18-Dec-2015 HRS 7143.8 LDG 5715		60	0 0 0	31-Dec-2020	12 m 22 d
256010 NO. 4	LIFE VEST			P01074-207 899655	MTH 18-Dec-2015 HRS 7143.8 LDG 5715		60	0 0 0	31-Dec-2020	12 m 22 d
256010 NO. 5	LIFE VEST			P01074-207 899663	MTH 18-Dec-2015 HRS 7143.8 LDG 5715		60	0 0 0	31-Dec-2020	12 m 22 d
256010 NO. 6	LIFE VEST			P01074-207 899726	MTH 18-Dec-2015 HRS 7143.8 LDG 5715		60	0 0 0	31-Dec-2020	12 m 22 d
256010 NO. 7	LIFE VEST			P01074-207 899687	MTH 18-Dec-2015 HRS 7143.8 LDG 5715		60	0 0 0	31-Dec-2020	12 m 22 d
256010 NO. 8	LIFE VEST			P01074-207 899691	MTH 18-Dec-2015 HRS 7143.8 LDG 5715		60	0 0 0	31-Dec-2020	12 m 22 d
256010 NO. 9	LIFE VEST			P01074-207 019988	MTH 18-Dec-2015 HRS 7143.8 LDG 5715		60	0 0 0	31-Dec-2020	12 m 22 d
261001 NO. 1 ENGINE	FIRE DETECTOR SENSOR 9912036-3	*CF		244-18882 NSN	MTH 19-Oct-2006		O/C			
261001 NO. 2 ENGINE	FIRE DETECTOR SENSOR 9912036-3	*CF		244-18882 NSN	MTH 19-Oct-2006		O/C			
261002 NO. 1	FIRE DETECTOR CONTROL 9912036-12	*CF		377-02838 0613272	MTH 19-Oct-2006		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
261002 NO. 2	FIRE DETECTOR CONTROL 9912036-12	*CF		377-02838 0613268	MTH 19-Oct-2006		O/C			
262001 AFT	ENGINE FIRE BOTTLE 9912048-2			30401102 44084B1	MTH 11-Dec-2015 HRS 7143.8 LDG 5715		O/C	190 0 0		
262001 FORWARD	ENGINE FIRE BOTTLE 9912048-2			30401102 43752B1	MTH 11-Dec-2015 HRS 7143.8 LDG 5715		O/C	193 0 0		
262002 CABIN	PORTABLE HALON FIRE EXTINGUISHER HALON 1211	KICT		C352CS E-68636245	MTH 24-Apr-2018 HRS 8330.5 LDG 6658		O/C	0 0		
262002 COCKPIT	PORTABLE HALON FIRE EXTINGUISHER HALON 1211	KICT		C352CS E-68636244	MTH 24-Apr-2018 HRS 8330.5 LDG 6658		O/C	0 0		
262003 AFT LEFT	(MAX LIFE) CARTRIDGE	LNK		13083-5 ESD15D590-001	MTH 11-Dec-2015 HRS 7143.8 LDG 5715		72		30-Apr-2021	16 m 21 d
Manufacture Date: 01-Apr-2015										
262003 AFT RIGHT	(MAX LIFE) CARTRIDGE	LNK		13083-5 ESD15B579-001	MTH 11-Dec-2015 HRS 7143.8 LDG 5715		72		28-Feb-2021	14 m 19 d
Manufacture Date: 01-Feb-2015										
262003 FORWARD LEFT	(MAX LIFE) CARTRIDGE	LNK		13083-5 ESD15D590-001	MTH 11-Dec-2015 HRS 7143.8 LDG 5715		72		30-Apr-2021	16 m 21 d
Manufacture Date: 01-Apr-2015										
262003 FORWARD RIGHT	(MAX LIFE) CARTRIDGE	LNK		13083-5 ESD15D590-001	MTH 11-Dec-2015 HRS 7143.8 LDG 5715		72		30-Apr-2021	16 m 21 d
Manufacture Date: 01-Apr-2015										
271001	AILERON TRIM ACTUATOR *CF			6660361-18 NSN	MTH 19-Oct-2006		O/C			
272002 RIGHT	STICK SHAKER CONTROL *CF			201 6986	MTH 19-Oct-2006		O/C			
273002	TRIM MIXER ACTUATOR HPN			1U662-001 T254	MTH 04-May-2008 HRS 1433		O/C	0		
273003 LEFT	ELEVATOR TRIM ACTUATOR *CF			6361215-21 NSN	MTH 19-Oct-2006		O/C			
273003 RIGHT	ELEVATOR TRIM ACTUATOR *CF			6361215-22 NSN	MTH 19-Oct-2006		O/C			
275001	FLAP CONTROL VALVE *CF			66720 3100	MTH 19-Oct-2006		O/C			
275003 NO. 1	FLAP ACTUATOR 9912007-1	*CF		1535000-1 2330	MTH 19-Oct-2006		O/C			
275003 NO. 2	FLAP ACTUATOR 9912007-1	*CF		1535000-1 2331	MTH 19-Oct-2006		O/C			
275004 LEFT WING LEFT INBOARD	AFT FLAP ROLLER	LUK		S3049-5F8 NSN	MTH 12-Jun-2014 HRS 5921 LDG 4721		N/R	0 0 0		
275004 LEFT WING LEFT OUTBOARD	AFT FLAP ROLLER	LUK		S3049-5F8 NSN	MTH 12-Jun-2014 HRS 5921 LDG 4721		N/R	0 0 0		



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
275004 LEFT WING RIGHT INBOARD	AFT FLAP ROLLER	LUK		S3049-5F8 NSN	MTH 12-Jun-2014 HRS 5921 LDG 4721		N/R	0 0 0		
275004 LEFT WING RIGHT OUTBOARD	AFT FLAP ROLLER	LUK		S3049-5F8 NSN	MTH 12-Jun-2014 HRS 5921 LDG 4721		N/R	0 0 0		
275004 RIGHT WING LEFT INBOARD	AFT FLAP ROLLER	LUK		S3049-5F8 NSN	MTH 12-Jun-2014 HRS 5921 LDG 4721		N/R	0 0 0		
275004 RIGHT WING LEFT OUTBOARD	AFT FLAP ROLLER	LUK		S3049-5F8 NSN	MTH 12-Jun-2014 HRS 5921 LDG 4721		N/R	0 0 0		
275004 RIGHT WING RIGHT INBOARD	AFT FLAP ROLLER	LUK		S3049-5F8 NSN	MTH 12-Jun-2014 HRS 5921 LDG 4721		N/R	0 0 0		
275004 RIGHT WING RIGHT OUTBOARD	AFT FLAP ROLLER	LUK		S3049-5F8 NSN	MTH 12-Jun-2014 HRS 5921 LDG 4721		N/R	0 0 0		
276001 NO. 1	SPEED BRAKE ACTUATOR			9912344-1 373	MTH 11-Jan-2017 HRS 7959.7 LDG 6366		O/C			
276001 NO. 2	SPEED BRAKE ACTUATOR			9912344-1 374	MTH 11-Jan-2017 HRS 7959.7 LDG 6366		O/C			
276002	SPEED BRAKE FLAP CONTROL VALVE *CF			66720 3098	MTH 19-Oct-2006		O/C			
276003	SAFETY SPDBK VALVE *CF			68930 1568	MTH 19-Oct-2006		O/C			
280001 LEFT	FUEL FLOAT VALVE 9914268-5	*CF		60221-4 1443	MTH 19-Oct-2006		O/C			
280001 RIGHT	FUEL FLOAT VALVE 9914268-5	*CF		60221-4 1440	MTH 19-Oct-2006		O/C			
280003 LEFT	PRESSURE RELIEF VALVE 9912501-2	*CF		840203-105 4114	MTH 19-Oct-2006		O/C			
280003 RIGHT	PRESSURE RELIEF VALVE 9912501-2	*CF		840203-105 4308	MTH 19-Oct-2006		O/C			
280004 LEFT	PILOT HIGH LEVEL VALVE 9914107-1	*CF		61087 4343	MTH 19-Oct-2006		O/C			
280004 RIGHT	PILOT HIGH LEVEL VALVE 9914107-1	*CF		61087 4327	MTH 19-Oct-2006		O/C			
280005	SINGLE PT REFUEL VALVE 9914168-2	*CF		61088 1527	MTH 19-Oct-2006		O/C			
280006 LEFT	SINGLE POINT REFUEL VALVE *CF			80002-101 NSN	MTH 19-Oct-2006		O/C			
280006 RIGHT	SINGLE POINT REFUEL VALVE *CF			80002-101 NSN	MTH 19-Oct-2006		O/C			
280007 LEFT	DEFUEL SINGLE PT VALVE *CF			61084-2 1152	MTH 19-Oct-2006		O/C			
280007 RIGHT	DEFUEL SINGLE PT VALVE *CF			61084-2 1218	MTH 19-Oct-2006		O/C			
280008 LEFT	MANUAL FUEL SHUTOFF VALVE 9914107-3	*CF		61086 3261	MTH 19-Oct-2006		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
280008 RIGHT	MANUAL FUEL SHUTOFF VALVE 9914107-3	*CF		61086 3263	MTH 19-Oct-2006		O/C			
282001 NO. 1	ELECTRIC FUEL BOOST PUMP 9912553-1	*CF		1C7-23 5BB68	MTH 19-Oct-2006		O/C			
282001 NO. 2	ELECTRIC FUEL BOOST PUMP 9912553-1	*CF		1C7-23 5BB66	MTH 19-Oct-2006		O/C			
282010 LEFT	MOTIVE FUEL VALVE 9912013-1	*CF		4073 1832	MTH 19-Oct-2006		O/C			
282010 RIGHT	MOTIVE FUEL VALVE 9912013-1	*CF		4073 1829	MTH 19-Oct-2006		O/C			
284001 NO. 1	FUEL LOW LEVEL SWITCH 9912556-5	*CF		L16H-9 1501	MTH 19-Oct-2006		O/C			
284001 NO. 2	FUEL LOW LEVEL SWITCH 9912556-5	*CF		L16H-9 1540	MTH 19-Oct-2006		O/C			
284002 LEFT	FUEL QTY COMPENSATOR 9912556-5	SWF		10635B02Y03 06041206	MTH 26-Dec-2009 HRS 2424		O/C	0 0		
284011 LEFT	FUEL QTY PROBE 9912556-2	*CF		10634T10Y00 MN03929	MTH 19-Oct-2006		O/C			
284011 RIGHT	FUEL QTY PROBE 9912556-2	*CF		10634T10Y00 MN03915	MTH 19-Oct-2006		O/C			
284012 LEFT	FUEL QTY PROBE 9912556-3	*CF		10634T08Y00 MN02029	MTH 19-Oct-2006		O/C			
284012 RIGHT	FUEL QTY PROBE 9912556-3	*CF		10634T08Y00 MN03647	MTH 19-Oct-2006		O/C			
284013 LEFT	FUEL QTY PROBE 9912556-4	*CF		10634T09Y00 MN02032	MTH 19-Oct-2006		O/C			
284013 RIGHT	FUEL QTY PROBE 9912556-4	*CF		10634T09Y00 MN03645	MTH 19-Oct-2006		O/C			
284014 LEFT	FUEL QTY PROBE 9912498-3	*CF		10634T04Y00 MN03024	MTH 19-Oct-2006		O/C			
284014 RIGHT	FUEL QTY PROBE 9912498-3	*CF		10634T04Y00 MN03022	MTH 19-Oct-2006		O/C			
284015 LEFT	FUEL QTY PROBE 9912498-4	*CF		10634T05Y00 MN01660	MTH 19-Oct-2006		O/C			
284015 RIGHT	FUEL QTY PROBE 9912498-4	*CF		10634T05Y00 MN02539	MTH 19-Oct-2006		O/C			
284016 LEFT	FUEL QTY PROBE 9912498-5	*CF		10634T01Y00 MN02505	MTH 19-Oct-2006		O/C			
284016 RIGHT	FUEL QTY PROBE 9912498-5	*CF		10634T01Y00 MN02506	MTH 19-Oct-2006		O/C			
284017 LEFT	FUEL QTY PROBE 9912498-6	SWF		10634T06Y00 MN01734	MTH 26-Dec-2009 HRS 2424		O/C		0	
284017 RIGHT	FUEL QTY PROBE 9912498-6	*CF		10634T06Y00 MN03347	MTH 19-Oct-2006		O/C			
291001	MAIN HYD RESERVOIR			9912542-1 564	MTH 08-Jan-2011 HRS 3205.2 LDG 2542		O/C		0 0 0	
291002 LEFT	HYDRAULIC PUMP 9912062-4	*CF		24195-LAA 4887	MTH 19-Oct-2006		O/C			
291002 RIGHT	HYDRAULIC PUMP 9912062-4			9912062-4 6211	MTH 09-Dec-2014 HRS 6314.5 LDG 5067		O/C		0 0 0	
291005 NO. 1	CK VALVE HYDRAULIC FLOW SWITCH 9912194-3	*CF		3520020100-4 06681	MTH 19-Oct-2006		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
291005 NO. 2	CK VALVE HYDRAULIC FLOW SWITCH 9912194-3	MCO		3520020100-4 07791	MTH 17-Sep-2013 HRS 5294.7 LDG 4234		O/C	0 0 0		
291007 NO. 1	MOTOR ACTUATOR VALVE *CF			AV24B1325C5 AA89107	MTH 19-Oct-2006		O/C			
291007 NO. 2	MOTOR ACTUATOR VALVE *CF			AV24B1325C5 AA78580	MTH 19-Oct-2006		O/C			
291008	THERMAL RELIEF VALVE LUK			1785-2 167	MTH 15-Dec-2012 HRS 4724.2 LDG 3774		O/C	0 0 0		
291009	PRESSURE RELIEF VALVE GSO			4614 1331A	MTH 23-Jan-2011 HRS 3249.3 LDG 2572		O/C	0 0		
291012	SOLENOID BYPASS VALVE *CF			61510-1 2311A	MTH 19-Oct-2006		O/C			
301001 LEFT	TEMP CONTROL SL002 SWITCH 3703			1173T42-3 3703	MTH 19-Jun-2009 HRS 2155.8 LDG 1702		O/C	0 0 0		
301001 RIGHT	TEMP CONTROL SR002 SWITCH *CF			1173T42-3 3726	MTH 19-Oct-2006		O/C			
301001 WING	ANTI-ICE BLEED AIR CROSSFLOW ISOLATION VALVE 9912403-2	*CF		2602-36 1481	MTH 19-Oct-2006		O/C			
301002 NO. 1	HORIZONTAL STABILIZER DEICE BOOT NCD9350			P29S5D5225-05 NCD9350	MTH 09-Dec-2014 HRS 6314.5 LDG 5067		O/C	0 0 0		
301002 NO. 2	HORIZONTAL STABILIZER DEICE BOOT NDD1680			P29S-5D5225-06 NDD1680	MTH 10-Oct-2016 HRS 7788.4 LDG 6227		O/C	0 0 0		
301004 LEFT WING	ANTI-ICE BLEED AIR PRESSURE REG SHUTOFF VT001 VLV 9912495-6	*CF		1962-00-11 3058	MTH 19-Oct-2006		O/C			
301004 RIGHT WING	ANTI-ICE BLEED AIR PRESSURE REG SHUTOFF VT002 VLV 9912495-6	*CF		1962-00-11 3164	MTH 19-Oct-2006		O/C			
301005 NO. 1	DEICE PRESSURE ST003 SWITCH *CF			1106P55-1 4033A	MTH 19-Oct-2006		O/C			
301005 NO. 2	DEICE PRESSURE ST004 SWITCH *CF			1106P55-1 4040A	MTH 19-Oct-2006		O/C			
301008 LEFT	DEICE CONTROL SLV19 VLV *CF			3D2353-06 N061440	MTH 19-Oct-2006		O/C			
301008 RIGHT	DEICE CONTROL SLV18 VLV *CF			3D2353-06 N062824	MTH 19-Oct-2006		O/C			
302003 LEFT ENGINE	ANTI-ICE SOLENOID VLV 9912495-4	*CF		1946-00-19 4103	MTH 19-Oct-2006		O/C			
302003 RIGHT ENGINE	ANTI-ICE SOLENOID VLV 9912495-4	*CF		1946-00-19 4080	MTH 19-Oct-2006		O/C			
302005 LEFT	ANTI ICING VALVE 3119722-04	UNK		540-0406-4 3194	MTH 31-Dec-2017 HRS 8329.5 LDG 6657		O/C	0 0 0		



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
302005 RIGHT	ANTI ICING VALVE 3119722-04	UNK		540-0406-4 3229	MTH 24-Dec-2017 HRS 8329.5 LDG 6657		O/C	0 0 0		
303001 LEFT	PITOT TUBE	*CF		PH1100-1-LJ C4380	MTH 19-Oct-2006		O/C			
303001 RIGHT	PITOT TUBE	*CF		PH1100-1-LJ C4382	MTH 19-Oct-2006		O/C			
303001 STANDBY	PITOT TUBE			PH1100-2A 864808	MTH 20-Nov-2009 HRS 2349.8 LDG 1879		O/C	0 0 0		
304001	BLEED AIR MONITOR-	*CF		1169-1 3805	MTH 19-Oct-2006		O/C			
304002	ANTI-ICE BLEED AIR WNDSHLD HEAT EXCHANGER 9912041-2	*CF		10654A 703	MTH 19-Oct-2006		O/C			
304004	ALCOHOL WINDSHIELD ANTI-ICE PUMP	*CF		476411 SN-UNKNOWN	MTH 19-Oct-2006		O/C			
304005	TEMP CONTROL VALVE 9912085-1	*CF		27241287 2BB15	MTH 19-Oct-2006		O/C			
304006	ANTI-ICE BLEED AIR WNDSHLD TEMP XMTR26 SENSOR	TEB		9912085-6 11BC240	MTH 12-Dec-2009 HRS 2403.7 LDG 1920		O/C	0 0 0		
304007	ANTI-ICE BLEED AIR WNDSHLD HEAT EXCHANGER PRESS S130 SWITCH	*CF		1115P25 4390AB	MTH 19-Oct-2006		O/C			
304009	WINDSHIELD ANTI-ICE BLEED AIR CONTROL VALVE 9912086-4			67410-2 3501	MTH 10-Nov-2013 HRS 5427.5 LDG 4341		O/C			
312001 COPILOT	DIGITAL CLOCK			M877A5V 22788	MTH 17-Apr-2015 HRS 6595 LDG 5268		O/C	0 0 0		
312001 PILOT	DIGITAL CLOCK	KMKE		M877A5V 23518	MTH 09-Sep-2016 HRS 7711.2 LDG 6165 ACH 2569.2		O/C	0 0		
313001	FLIGHT HOUR RECORDER 85071	*CF		C664503-0104 NSN	MTH 19-Oct-2006		O/C			
313003 NO. 1	ACCELEROMETER AG-222	MKE		7000992 009470	MTH 02-Jun-2012 HRS 4353.7 LDG 3462		O/C			
313003 NO. 2	ACCELEROMETER AG-222	*CF		7000992 9388	MTH 19-Oct-2006		O/C			
313003	EGPWS ACCELEROMETER	*CF		979-0223-001 3608	MTH 19-Oct-2006		O/C			
315001	MASTER WARNING ANNUNCIATOR 9912559-1	*CF		1730-1-1 205320151	MTH 19-Oct-2006		O/C			
321001 LEFT <i>321001T : T-L</i>	MAIN LANDING GEAR ASSEMBLY	*CF		6541510-3 60	MTH 19-Oct-2006		O/C			
321002 RIGHT <i>321002T : T-R</i>	MAIN LANDING GEAR ASSEMBLY	*CF		6541510-4 60	MTH 19-Oct-2006		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
321004 LEFT	MAIN LANDING GEAR UPPER OLEO CAP *CF			6541521-3 NSN	MTH 19-Oct-2006		O/C			
321004 RIGHT	MAIN LANDING GEAR UPPER OLEO CAP *CF			6541521-3 NSN	MTH 19-Oct-2006		O/C			
321005 LEFT	MAIN LANDING GEAR OLEO OUTER BEARING *CF			6541425-13 NSN	MTH 19-Oct-2006 LDG 0		21800	0	21800	14982
321005 RIGHT	MAIN LANDING GEAR OLEO OUTER BEARING *CF			6541425-13 NSN	MTH 19-Oct-2006 LDG 0		21800	0	21800	14982
321006 LEFT	MAIN LANDING GEAR ORIFICE FITTING *CF			6541428-3 NSN	MTH 19-Oct-2006		O/C			
321006 RIGHT	MAIN LANDING GEAR ORIFICE FITTING *CF			6541428-3 NSN	MTH 19-Oct-2006		O/C			
321007 LEFT	MAIN LANDING GEAR TRAILING LINK			6541535-3 80	MTH 07-Mar-2009 HRS 1999.3 LDG 1568			3583.2 2787	23781	16963
321007 RIGHT	MAIN LANDING GEAR TRAILING LINK			6541535-4 79	MTH 07-Mar-2009 HRS 1999.3 LDG 1568		25000	3583.2 2787	23781	16963
321008 LEFT MAIN LANDING GEAR	OLEO ASSEMBLY	KICT		6541520-4 126	MTH 20-Apr-2018 HRS 8329.5 LDG 6657		31900	6657	31900	25082
321008 RIGHT MAIN LANDING GEAR	OLEO ASSEMBLY	KICT		6541520-4 127	MTH 20-Apr-2018 HRS 8329.5 LDG 6657		31900	6657	31900	25082
321009 LEFT MAIN LANDING GEAR	TRUNNION MACHINING *CF			6541561-1 SN-UNKNOWN	MTH 19-Oct-2006 LDG 0		50100	0	50100	43282
321009 RIGHT MAIN LANDING GEAR	TRUNNION MACHINING *CF			6541561-2 SN-UNKNOWN	MTH 19-Oct-2006 LDG 0		50100	0	50100	43282
322001 <i>322001T : T</i>	NOSE LANDING GEAR ASSEMBLY *CF			6642000-54 30	MTH 19-Oct-2006 LDG 0		22566	0	22566	15748
322002	NOSE SHIMMY DAMPER KSWF			5543001-12 080610-12X	MTH 24-Aug-2013 HRS 5267.2 LDG 4208		O/C	1 0 0		
322004 <i>322004T : T</i>	NOSE GEAR FORK/PISTON			6642000-209 26426171A	MTH 09-Jan-2017 HRS 7959.7 LDG 6366		13061	0	19427	12609
323003 <i>323003T : T</i>	NOSE LANDING GEAR ACTUATOR			9912485-5 1064	MTH 17-Sep-2012 HRS 4546.2 LDG 3637		15000	285	18352	11534
323004 LEFT	MLG UPLOCK ACTUATOR *CF			6527504-1 361	MTH 19-Oct-2006		O/C			
323004 NOSE	UPLOCK ACTUATOR *CF			5527504-2 3531	MTH 19-Oct-2006		O/C			
323004 RIGHT	MLG UPLOCK ACTUATOR *CF			6527504-1 367	MTH 19-Oct-2006		O/C			
323006	PNEUMATIC BLOWDOWN/EMERGENCY BRAKE BOTTLE 9912103-3			212940-2 1532	MTH 06-Jan-2017 HRS 7959.7 LDG 6366		288	243	31-Oct-2020	10 m 22 d
Manufacture Date: 01-Oct-1996										
323007	LANDING GEAR CONTROL VALVE *CF			71839 0570	MTH 19-Oct-2006		O/C			
323008	DUMP VALVE *CF			OAS5319-1 1587	MTH 19-Oct-2006		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
323015 LEFT <i>323001T : T-L</i>	SIDE BRACE ACTUATOR 9912569-2			9912569-3 0465	MTH 09-Jan-2017 HRS 7959.7 LDG 6366		50100	0	56466	49648
323016 RIGHT <i>323002T : T-R</i>	SIDE BRACE ACTUATOR 9912569-2	*CF		1556600-2 378	MTH 19-Oct-2006 LDG 0		50100	0	50100	43282
323019	EMERGENCY AIR BOTTLE GAUGE *CF			2341128 033247	MTH 19-Oct-2006		O/C	0		
324001 LEFT	MLG WHEEL ASSEMBLY 9912561-5	KICT		3-1607-1 0182	MTH 25-Oct-2018 HRS 8363.9 LDG 6691		O/C	0		
324001 RIGHT	MLG WHEEL ASSEMBLY 9912561-5	KICT		3-1607-1 0261	MTH 13-Nov-2016 HRS 7852.1 LDG 6279		O/C			
324002	NOSE WHEEL ASSEMBLY 9914069-2	KGSO		3-1418 6566	MTH 12-Apr-2017 HRS 8153.2 LDG 6519		O/C			
324003 LEFT	MLG BRAKE ASSEMBLY 9912561-3	SRQ		2-1656 0081	MTH 23-Feb-2017 HRS 8037.2 LDG 6430		O/C	0	0	0
324004 RIGHT	MLG BRAKE ASSEMBLY 9912561-3	KLYH		2-1656 0059	MTH 26-Dec-2018 HRS 8398 LDG 6717		O/C	0	0	
324005 LEFT	MLG TIRE 9912467-2	KICT		229K48-2 8032571	MTH 25-Oct-2018 HRS 8363.9 LDG 6691		O/C	0	0	
324005 RIGHT	MLG TIRE 9912467-2	PVG		229K48-2 81990664	MTH 08-Mar-2019 HRS 8431 LDG 6737		O/C	0	0	
324006	NOSE TIRE 9914070-1	KGSO		031-613-8 6029S00358	MTH 12-Apr-2017 HRS 8153.2 LDG 6519		O/C			
324010 LEFT	MLG SHUTTLE VALVE *CF			98120 3373	MTH 19-Oct-2006		O/C			
324010 NOSE LANDING GEAR	SHUTTLE VALVE *CF			98120 3700	MTH 19-Oct-2006		O/C			
324010 RIGHT	MLG SHUTTLE VALVE SWF			211-111 2676	MTH 26-Dec-2009 HRS 2424 LDG 1933		O/C	0	0	0
324013	BRAKE METERING VALVE 9912562-1	*CF		32-079 279	MTH 19-Oct-2006		O/C			
324014	EMERGENCY AIR BRAKE VALVE *CF			895232-0875 V1193	MTH 19-Oct-2006		O/C			
324019	BRAKE PRESS PUMP ASSEMBLY			9912166-3 7207	MTH 13-Apr-2015 HRS 6575.5 LDG 5254		O/C	0	0	0



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
324021	POWER BRAKE ANTISKID VALVE 9912489-4	SMF		39-837 858	MTH 15-Apr-2010 HRS 2649.3 LDG 2098		O/C	0 0 0		
324022	BRAKE CONTROL BOX 9912564-2	*CF		142-021 276	MTH 19-Oct-2006		O/C			
324023	ANTISKID ACCUMULATOR *CF			57C57652 0365T	MTH 19-Oct-2006		O/C			
324024 LEFT	MLG WHEEL TRANSDUCER 9912305-2	*CF		40-955 NSN	MTH 19-Oct-2006		O/C			
324024 RIGHT	MLG WHEEL TRANSDUCER 9912305-2	*CF		40-955 NSN	MTH 19-Oct-2006		O/C			
324025	PRESSURE SWITCH			GPP1250-66 0825237	MTH 15-Feb-2011 HRS 3311.4 LDG 2626		O/C	0 0 0		
324026	POWER BRAKE ASSEMBLY MOTOR			MP50B-1 1232	MTH 13-Apr-2015 HRS 6575.5 LDG 5254		O/C			
324027	FAULT DISPLAY UNIT 9912305-9	*CF		42-92750 1820A	MTH 19-Oct-2006		O/C			
324101	PARKING BRAKE VALVE 9912388-2	*CF		95905 1598A	MTH 19-Oct-2006		O/C			
324102	PRESSURE SWITCH	LUK		GPP1250-52 0603137	MTH 15-Dec-2012 HRS 4724.2 LDG 3774		O/C	0 0 0		
325001	NOSE STEERING BUNGEE ASSEMBLY *CF			5565624-20 NSN	MTH 19-Oct-2006		O/C			
326005 LEFT	MAIN GEAR UP & LOCKED SWITCH *CF			65-430087 5135	MTH 19-Oct-2006		O/C			
326005 RIGHT	MAIN GEAR UP & LOCKED SWITCH *CF			65-430087 0227	MTH 19-Oct-2006		O/C			
326005	NOSE GEAR UP & LOCKED SWITCH *CF			65-430087 0546	MTH 19-Oct-2006		O/C			
331001 NO. 1	LIGHT PANEL DIMMER *CF			273-1 206180141	MTH 19-Oct-2006		O/C			
331001 NO. 2	LIGHT PANEL DIMMER *CF			273-1 206190462	MTH 19-Oct-2006		O/C			
331001 NO. 3	LIGHT PANEL DIMMER *CF			273-1 206090168	MTH 19-Oct-2006		O/C			
331011	INVT-115V EL PANEL *CF			EM2044-1 5231	MTH 19-Oct-2006		O/C			
334002	ROTATING/FLASHING BEACON KIWA			01-0790044-37 03558	MTH 05-Mar-2014 HRS 5715.7 LDG 4565		O/C			
334003 NO. 1	STROBE POWER SUPPLY KSAT			01-0790101-05 00183	MTH 23-Sep-2016 HRS 7750.9 LDG 6167		O/C			
334003 NO. 2	STROBE POWER SUPPLY			01-0790101-05 01096	MTH 28-Dec-2016 HRS 7948.8 LDG 6359		O/C			
334005	TAIL LIGHT ASSEMBLY KSWF			01-0770966-00 02788A	MTH 25-Apr-2017 HRS 8180.3 LDG 6537		O/C	0 0 0		



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
335001	EMERGENCY BATTERY PACK KICT			CBS28-1 5275M	MTH 20-Apr-2018 HRS 8329.5 LDG 6657		O/C			
340070	AIR DATA COMPUTER			PN SN-UNKNOWN	MTH 19-Oct-2006		O/C	0		
341006	PITOT PRESSURE SWITCH *CF			D45C31 548	MTH 19-Oct-2006		O/C			
341010	ANGLE OF ATTACK INDICATOR *CF			C-11605-1 83037	MTH 19-Oct-2006		O/C			
341011	ANGLE OF ATTACK STALL WARNING COMPUTER *CF			C-13106-1 1151	MTH 19-Oct-2006		O/C			
341012	AOA SENSOR KSAT			C-12717-1 1548	MTH 14-Mar-2011 HRS 3400.4 LDG 2687		O/C			
341014	ANGLE OF ATTACK INDEXER *CF			C12763-1 1097	MTH 19-Oct-2006		O/C			
341016	SECONDARY FLIGHT ADU			501-1890-03 1996	MTH 11-Dec-2015 HRS 7143.8 LDG 5715		O/C			
341017	SECONDARY FLIGHT DISPLAY GH-3000	17		501-1741-2103 1965A	MTH 12-Feb-2010 HRS 2526.8 LDG 2012		O/C			
342001	MAGNETIC COMPASS *CF			C660501-0301 NSN	MTH 19-Oct-2006		O/C			
342023	RADAR CONTROLLER WC-660	*CF		7008471-667 06078967	MTH 19-Oct-2006		O/C			
342042 NO. 1	MODE FLIGHT DIRECTOR SELECTOR MS-560			7018341-803 97090930	MTH 14-Jun-2016 HRS 7524.4 LDG 5995		O/C			
342043 NO. 1	VERTICAL FLIGHT DIRECTOR GYRO VG-14A			7000622-901 99028803	MTH 28-Dec-2016 HRS 7948.8 LDG 6359		O/C	0 0 0		
342043 NO. 2	VERTICAL FLIGHT DIRECTOR GYRO VG-14A KICT			7000622-901 82054213	MTH 24-Sep-2018 HRS 8362.7 LDG 6690		O/C	0 0		
342044 NO. 1	RATE OF TURN GYRO RG-204	*CF	K	7007453-903 06065772	MTH 19-Oct-2006		O/C			
342048 NO. 1	AIR DATA COMPUTER AZ-950		G	7030700-71703 06050983	MTH 14-Dec-2015 HRS 7143.8 LDG 5715		O/C			
342048 NO. 2	AIR DATA COMPUTER AZ-950		G	7030700-71703 06071064	MTH 14-Dec-2015 HRS 7143.8 LDG 5715		O/C	7143.8 5715		
342049 NO. 1	DIRECTIONAL GYRO C-14D		G	4020577-3 97076198	MTH 18-Mar-2013 HRS 4953.6 LDG 3948		O/C	0 0 0		



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
342049 NO. 2	DIRECTIONAL GYRO C-14D		G	4020577-3 97046181	MTH 31-Mar-2016 HRS 7336.8 LDG 5857		O/C			
342050 NO. 1	FLUX DETECTOR FX-220			2594484 02055330	MTH 22-Mar-2013 HRS 4969.7 LDG 3958		O/C			
342050 NO. 2	FLUX DETECTOR FX-220			2594484 96021589	MTH 26-Mar-2013 HRS 4973 LDG 3961		O/C			
342052	REMOTE COMPENSATOR CS-412	SLC		2593379-1 95071570	MTH 02-Apr-2012 HRS 4211.4 LDG 3355		O/C			
342053 STANDBY	HSI INDICATOR HSI-315A	*CF	3	520-3150-003 24312	MTH 19-Oct-2006		O/C			
342063 NO. 1	REMOTE COURSE CONTROL RI-553	KSUS	A	7016954-907 02101616	MTH 10-Jun-2010 HRS 2751.6 LDG 2190		O/C			
342064 STANDBY	GYRO POWER SUPPLY PS-855A	LUK		501-1712-01 3393	MTH 15-Dec-2012 HRS 4724.2 LDG 3774		O/C			
342069	MULTIFUNCTION DISPLAY CONTROLLER MC-800			7007062-941 04103053	MTH 01-May-2015 HRS 6649.2 LDG 5306		O/C			
342073	AFIS DATA MANAGEMENT UNIT DMU	UNK	12	400-045500-0003 3094	MTH 08-Jun-2018		O/C	60		
342078 NO. 1	DISPLAY GUIDANCE COMPUTER IC-615	KICT		7017000-96825 01105071	MTH 20-Apr-2018 HRS 8329.5 LDG 6657		O/C			
342078 NO. 2	DISPLAY GUIDANCE COMPUTER IC-615	UNK	AR	7017000-97825 02075619	MTH 08-Jun-2018		O/C			
342079 COPILOT	PRIMARY FLIGHT DISPLAY CONTROLLER DC-550	*CF	D	7016986-747 06076471	MTH 19-Oct-2006		O/C			
342079 PILOT	PRIMARY FLIGHT DISPLAY CONTROLLER DC-550	UNK	D	7016986-747 02054464	MTH 08-Jun-2018		O/C			
342080 CNTR	EFIS DISPLAY DU-870	*CF	F	7014300-901 0606F519	MTH 19-Oct-2006		O/C			
342080 NO. 1	EFIS DISPLAY DU-870	KICT	N	7014300-901 0209C022	MTH 10-Sep-2018 HRS 8362.7 LDG 6690		O/C			
342080 NO. 2	EFIS DISPLAY DU-870	KICT	N	7014300-901 00107821	MTH 20-Apr-2018 HRS 8329.5 LDG 6657		O/C			
342081 NO. 1	BEZEL DISPLAY UNIT BL-870	*CF	B	7014331-931 06076301	MTH 19-Oct-2006		O/C			
342081 NO. 2	BEZEL DISPLAY UNIT BL-870	*CF	B	7014331-931 06076300	MTH 19-Oct-2006		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
342081	MFD BEZEL DISPLAY UNIT BL-871			7014332-841 00114463	MTH 26-Jan-2015 HRS 6371.4 LDG 5109		O/C			
342177	PS-850/PS-855 EMERGENCY POWER SUPPLY KICT			501-1712-01 3206	MTH 20-Apr-2018 HRS 8329.5 LDG 6657		O/C			
344003	PRIMUS 650 RADAR RECEIVER/TRANSMITTER WU-660	ICT		7021450-601 04034781	MTH 01-Jun-2016 HRS 7491.8 LDG 5971		O/C			
344022	RADIO ALT TRANSCEIVER RT-300	*CF	AC	7001840-936 0607C917	MTH 19-Oct-2006		O/C			
344023 AFT	RECEIVER RADIO ALT ANTENNA *CF			S67-2002-4 55213610	MTH 19-Oct-2006		O/C			
344023 FORWARD	TRANSMITTER RADIO ALT ANTENNA *CF			S67-2002-4 55213609	MTH 19-Oct-2006		O/C			
344024	GROUND PROXIMITY WARNING SYS COMPUTER GSO			965-1076-040-219-219 2003	MTH 30-Mar-2007 HRS 332		O/C	0		
345004 AFT	TRANSPONDER ANTENNA 85226	*CF		DMNI50-2-2 108108	MTH 19-Oct-2006		O/C			
345004 FORWARD	TRANSPONDER ANTENNA 85226	*CF		DMNI50-2-2 108100	MTH 19-Oct-2006		O/C			
345004 TOP AFT	DIV TRANSPONDER ANTENNA 85226	*CF		DMNI50-2-2 108100	MTH 19-Oct-2006		O/C			
345004 TOP FORWARD	DIV TRANSPONDER ANTENNA 85226	*CF		DMNI50-2-2 108098	MTH 19-Oct-2006		O/C			
345005	TEMPERATURE PROBE *CF			102DB1AG A62109	MTH 19-Oct-2006		O/C			
345007 AFT	DME ANTENNA 85226	*CF		DMNI50-2-2 108112	MTH 19-Oct-2006		O/C			
345007 FORWARD	DME ANTENNA 85226	*CF		DMNI50-2-2 108104	MTH 19-Oct-2006		O/C			
345010 NO. 1	NAVIGATION ANTENNA CI120-200G/S-L	KICT		CI120-1-L 551203	MTH 24-Apr-2018 HRS 8330.5 LDG 6658		O/C	0	0	
345010 NO. 2	NAVIGATION ANTENNA CI120-200G/S-L	KICT		CI120-1-L 551294	MTH 24-Apr-2018 HRS 8330.5 LDG 6658		O/C	0	0	
345014 NO. 1	ADF ANTENNA AT-860	LUK		7510300-901 1108J597	MTH 29-Jul-2014 HRS 6028.8 LDG 4818		O/C			
345014 NO. 2	ADF ANTENNA	KICT		S3100-17 1710Q298	MTH 20-Apr-2018 HRS 8329.5 LDG 6657		O/C	0	0	
345015	LP/LPV MONITOR-	KICT		S3100-607 2357	MTH 20-Apr-2018 HRS 8329.5 LDG 6657		O/C	0	0	0
345017	MARKER BEACON ANTENNA			31-10-01 5247	MTH 16-Jun-2013 HRS 5133 LDG 4097		O/C	0	0	0



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
345018	GLIDESLOPE ANTENNA	SWF		RGS10-48 15754	MTH 27-Aug-2011 HRS 3753.9 LDG 2973		O/C	0 0		
345027 NO. 1	NAV MODULE NV-850	*CF	T	7510134-731 0512A263	MTH 19-Oct-2006		O/C			
345027 NO. 2	NAV MODULE NV-850	ICT	T	7510134-731 90120619	MTH 07-Jun-2018 HRS 8331.9 LDG 6660		O/C			
345028 NO. 1	ADF MODULE DF-850	*CF	K	7510114-901 0512A270	MTH 19-Oct-2006		O/C			
345028 NO. 2	ADF MODULE DF-850	ICT	K	7510114-901 90120593	MTH 07-Jun-2018 HRS 8331.9 LDG 6660		O/C			
345029 NO. 1	NAV CLUSTER MODULE XN-850	*CF	E	7510164-921 129320649	MTH 19-Oct-2006		O/C			
345029 NO. 2	NAV CLUSTER MODULE XN-850	ICT	E	7510164-921 90120646	MTH 07-Jun-2018 HRS 8331.9 LDG 6660		O/C			
345030	CLEARANCE DELIVERY CONTROL CD-850	*CF	G	7513000-835 06023134	MTH 19-Oct-2006		O/C			
345031	NAVIGATION(FMS) COMPUTER	KICT		S3100-608 1075	MTH 20-Apr-2018 HRS 8329.5 LDG 6657		O/C	0 0 0		
345034 NO. 1	ATC TRANSPONDER	KICT	G	7517400-932 0710D186	MTH 20-Apr-2018 HRS 8329.5 LDG 6657		O/C			
345034 NO. 2	ATC TRANSPONDER	KICT	G	7517400-932 03077380	MTH 20-Apr-2018 HRS 8329.5 LDG 6657		O/C			
345035 NO. 1	DME INDICATOR DI-851	*CF	A	7513006-911 06042745	MTH 19-Oct-2006		O/C			
345035 NO. 2	DME INDICATOR DI-851	UNK	A	7513006-911 06042744	MTH 08-Jun-2018		O/C			
345036 NO. 1	DME RECEIVER TRANSMITTER DM-850	*CF	M	7510184-902 0512A310	MTH 19-Oct-2006		O/C			
345036 NO. 2	DME RECEIVER TRANSMITTER DM-850	ICT	M	7510184-902 90120612	MTH 07-Jun-2018 HRS 8331.9 LDG 6660		O/C			
345038 NO. 1	INTERGRATED NAV UNIT RNZ-850	UNK	AS	7510100-731 0512A258	MTH 08-Jun-2018		O/C			
345038 NO. 2	INTERGRATED NAV UNIT RNZ-850	ICT	AS	7510100-731 91010620	MTH 07-Jun-2018 HRS 8331.9 LDG 6660		O/C			
345077	DATA TRANSFER UNIT	KICT	D	1408-00-1 4001	MTH 20-Apr-2018 HRS 8329.5 LDG 6657		O/C	0 0		
345088 NO. 1	RADIO MANAGEMENT UNIT RM-855	KICT		7013270-963 95040267	MTH 20-Apr-2018 HRS 8329.5 LDG 6657		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
345088 NO. 2	RADIO MANAGEMENT UNIT KICT	AT		7013270-983 10107413	MTH 20-Apr-2018 HRS 8329.5 LDG 6657		O/C			
345088	FMZ600 FMS CONTROL DISPLAY GSO			2888-07-1 C361255	MTH 06-Mar-2016 HRS 7284.5 LDG 5815		O/C			
345090	MAGNETOMETER MAG-3000			501-1826-03 1141	MTH 29-Apr-2007 HRS 423.9 LDG 313		O/C			
345093 NO. 1	GPS ANTENNA KICT			10708 10638	MTH 20-Apr-2018 HRS 8329.5 LDG 6657		O/C	0 0 0		
345093 NO. 2	GPS ANTENNA KICT			10708 10639	MTH 20-Apr-2018 HRS 8329.5 LDG 6657		O/C	0 0 0		
345093	GPS ANTENNA *CF			S67-1575-52 512-17503	MTH 19-Oct-2006		O/C			
346001	TCAS PROCESSOR TPU-67A	UNK	24	066-01146-1211 42387	MTH 08-Jun-2018		O/C			
346002 BOTTOM	TCAS ANTENNA ANT-67A	*CF		071-01548-0100 58313380	MTH 19-Oct-2006		O/C			
346002 TOP	TCAS ANTENNA SMF			S72-1735-1 583-15805	MTH 12-Jan-2016 HRS 7195.8 LDG 5748		O/C	0 0		
346006	TCAS CONFIGURATION MODULE CM2000	*CF	1	071-00097-0100 16281	MTH 19-Oct-2006		O/C			
351001	OXYGEN PRESSURE GAUGE MD-97	*CF		C668512-0101 D0611153	MTH 19-Oct-2006		O/C	0		
351002	OXYGEN PRESSURE SWITCH KICT			P24032 1745	MTH 20-Apr-2018 HRS 8329.5 LDG 6657		O/C	0 0		
351004 COPILOT	OXYGEN MASK 9914067-41	KLYH		MC10-16-101 SE52372	MTH 30-Apr-2019 HRS 8443.3 LDG 6746		72	0	30-Apr-2025	64 m 21 d
351004 PILOT	OXYGEN MASK 9914067-41	KICT		MC10-16-101 120883	MTH 10-Sep-2018 HRS 8362.7 LDG 6690		72	1	31-Aug-2024	56 m 22 d
351005	OXYGEN SUPPLY REGULATOR *CF			172170-01 4564	MTH 19-Oct-2006		O/C	0		
351006	OXYGEN CYLINDER ZC369-64 PB DOT3HT1850	KCMH		176176-64 1376-1960067	MTH 16-Jul-2017 HRS 8327 LDG 6656		288		30-Sep-2039	237 m 21 d
Manufacture Date: 01-Sep-2015										
361003	PNEUMATIC REGULATOR 9912510-1	UNK		1H75-18 8BB136	MTH 08-Jun-2018		O/C			
361004	BLEED AIR CROSS *CF			5267-00-3 0637	MTH 19-Oct-2006		O/C			
361006 LEFT	PRECOOLER ACTUATOR 9914519-4			1E50-2 2AV28	MTH 10-Oct-2009 HRS 2319 LDG 1851		O/C	0 0 0		



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
361006 RIGHT	PRECOOLER ACTUATOR 9914519-4			1E50-2 1AT14	MTH 10-Nov-2013 HRS 5427.5 LDG 4341		O/C	0 0 0		
361008 NO. 1	VALVE CHECK			1406-7 0152	MTH 15-Dec-2012 HRS 4724.2 LDG 3774		O/C	0 0 0		
361013 LEFT	REPLACE LEFT HEAT EXCHANGER PRECOOLER			8230-3 S4883T0538	MTH 19-Dec-2015 HRS 7143.8 LDG 5715		4800	0 0 0	11943.8	3402.2
361013 RIGHT	REPLACE RIGHT HEAT EXCHANGER PRECOOLER			8230-3 S4883T0534	MTH 19-Dec-2015 HRS 7143.8 LDG 5715		4800	0 0 0	11943.8	3402.2
361101 LEFT	OVERTEMP BLEED AIR SWITCH 9914149-2	*CF		1173T181-2 5393	MTH 19-Oct-2006		O/C			
361101 RIGHT	OVERTEMP BLEED AIR SWITCH 9914149-2			7243	MTH 02-Nov-2013 HRS 5414.1 LDG 4328		O/C	0		
361102 LEFT	BLEED AIR SENSOR 9914519-2	MKE		1E51-1 11BD669	MTH 28-Aug-2009 HRS 2250		O/C	0		
361102 RIGHT	BLEED AIR SENSOR 9914519-2	*CF		1E51-1 6BB320	MTH 19-Oct-2006		O/C			
383002	MOTOR AND PUMP TOILET			17200-382 858	MTH 25-Feb-2007 HRS 230.7 LDG 177		O/C			
521001	CABIN DOOR SEAL 9912075-4	*CF		S15501-4 NSN	MTH 19-Oct-2006		O/C			
521002	EMERGENCY EXIT SEAL	*CF		R881204 NSN	MTH 19-Oct-2006		O/C			
521003	SECONDARY DOOR SEAL	SMF		R881515 -NSN-	MTH 21-May-2013 HRS 5082.4 LDG 4048		O/C	0 0 0		
531001 <i>531001T : L</i>	NOSE LANDING GEAR TRUNNION SUPPORT	*CF		6613056-3 NSN	MTH 19-Oct-2006 LDG 0		11539	0	11539	4721
531001 <i>531001T : R</i>	NOSE LANDING GEAR TRUNNION SUPPORT	*CF		6613056-4 NSN	MTH 19-Oct-2006 LDG 0		11539	0	11539	4721
531202 NOSE LANDING GEAR <i>531202T : N</i>	ACTUATOR FITTING	*CF		6511105-1 NSN	MTH 19-Oct-2006 LDG 0		22556	0	22556	15738
535000	RADOME	LUK		6313101-846 508	MTH 08-Aug-2014 HRS 6053.8 LDG 4835		O/C			
561001 NO. 1	LEFTHAND MAIN WINDSHIELD ASSY, (LH)	KICT		9912064-15 2076	MTH 20-Apr-2018 HRS 8329.5 LDG 6657		O/C	0 0		
561002 NO. 2	RIGHTHAND MAIN WINDSHIELD ASSY, (RH)	KICT		9912064-16 10017	MTH 20-Apr-2018 HRS 8329.5 LDG 6657		O/C	0 0		



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
561003	FOUL WEATHER WINDOW UNK			PN-UNKNOWN SN-UNKNOWN	MTH 08-Jun-2018		O/C	0		
561005 LEFT INBOARD	PILOTS INNER WINDOW *CF			5511285-5 NSN	MTH 19-Oct-2006		O/C			
561005 LEFT OUTBOARD	PILOTS OUTER WINDOW LUK			5511285-47 N/A (1-22-15)	MTH 30-Mar-2015 HRS 6535.1 LDG 5227		O/C	0 0 0		
561005 RIGHT INBOARD	CO-PILOTS INNER WINDOW *CF			5511285-6 NSN	MTH 19-Oct-2006		O/C			
561005 RIGHT OUTBOARD	CO-PILOTS OUTER WINDOW *CF			5511285-48 NSN	MTH 19-Oct-2006		O/C			
562001 L1 <i>562002 : L1</i>	CABIN DOOR WINDOW 9912207-8 *CF			161100-03 5138	MTH 19-Oct-2006		O/C			
562001 L2	CABIN WINDOW 9912207-8 *CF			161100-03 5132	MTH 19-Oct-2006		O/C			
562001 L3	CABIN WINDOW 9912207-8 *CF			161100-03 5131	MTH 19-Oct-2006		O/C			
562001 L4	CABIN WINDOW 9912207-8 *CF			161100-03 5133	MTH 19-Oct-2006		O/C			
562001 L5	CABIN WINDOW 9912207-8 *CF			161100-03 5252	MTH 19-Oct-2006		O/C			
562001 L6	CABIN WINDOW 9912207-8 *CF			161100-03 5129	MTH 19-Oct-2006		O/C			
562001 L7	CABIN WINDOW 9912207-8 *CF			161100-03 5128	MTH 19-Oct-2006		O/C			
562001 R1	EMERGENCY DOOR WINDOW 9912207-8 *CF			161100-03 4803	MTH 19-Oct-2006		O/C			
562001 R2	CABIN WINDOW 9912207-8 *CF			161100-03 5349	MTH 19-Oct-2006		O/C			
562001 R3	CABIN WINDOW 9912207-8 *CF			161100-03 5301	MTH 19-Oct-2006		O/C			
562001 R4	CABIN WINDOW 9912207-8 *CF			161100-03 5300	MTH 19-Oct-2006		O/C			
562001 R5	CABIN WINDOW 9912207-8 *CF			161100-03 5299	MTH 19-Oct-2006		O/C			
562001 R6	CABIN WINDOW 9912207-8 *CF			161100-03 5256	MTH 19-Oct-2006		O/C			
562001 R 7	CABIN WINDOW 9912207-8 *CF			161100-03 5298	MTH 19-Oct-2006		O/C			
572001 LEFT AFT	MLG TRUNNION FITTING ASSEMBLY *CF			6522634-5 NSN	MTH 19-Oct-2006 LDG 0	1	23900	0	23901	17083
572001 LEFT FORWARD	MLG TRUNNION FITTING ASSEMBLY *CF			6522640-1 NSN	MTH 19-Oct-2006 LDG 0	1	23900	0	23901	17083
572001 RIGHT AFT	MLG TRUNNION FITTING ASSEMBLY *CF			6522634-6 NSN	MTH 19-Oct-2006 LDG 0	1	23900	0	23901	17083
572001 RIGHT FORWARD	MLG TRUNNION FITTING ASSEMBLY *CF			6522640-2 NSN	MTH 19-Oct-2006 LDG 0	1	23900	0	23901	17083
574003 <i>574003T : T-L</i>	MLG SIDE BRACE SUPPORT FITTING LEFT *CF			6521525-1 NSN	MTH 19-Oct-2006 LDG 0		50100	0	50100	43282
574004 <i>574004T : T-R</i>	MLG SIDE BRACE SUPPORT FITTING RIGHT *CF			6521525-2 NSN	MTH 19-Oct-2006 LDG 0		50100	0	50100	43282
575001 LEFT INBOARD	FLAP KICT			6525130-37 27261671	MTH 20-Apr-2018 HRS 8329.5 LDG 6657		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
575002 RIGHT INBOARD	FLAP	KICT		6525130-38 274	MTH 20-Apr-2018 HRS 8329.5 LDG 6657		O/C			
712001 LEFT	ENGINE AFT ISOLATOR 9912547-2	*CF		LM456SA2 LK1403	MTH 19-Oct-2006 HRS 0		10000	0	10000	1458.4
712001 RIGHT	ENGINE AFT ISOLATOR 9912547-2	*CF		LM456SA2 LK1361	MTH 19-Oct-2006 HRS 0		10000	0	10000	1458.4
712002 LEFT BOTTOM	FORWARD ENGINE ISOLATOR 9912547-1	*CF		LM456SA1 LKO714	MTH 19-Oct-2006 HRS 0		10000	0	10000	1458.4
712002 LEFT TOP	FORWARD ENGINE ISOLATOR 9912547-1	*CF		LM456SA1 LKO723	MTH 19-Oct-2006 HRS 0		10000	0	10000	1458.4
712002 RIGHT BOTTOM	FORWARD ENGINE ISOLATOR 9912547-1	*CF		LM456SA1 LKO717	MTH 19-Oct-2006 HRS 0		10000	0	10000	1458.4
712002 RIGHT TOP	FORWARD ENGINE ISOLATOR 9912547-1	*CF		LM456SA1 LKO696	MTH 19-Oct-2006 HRS 0		10000	0	10000	1458.4
712005	ENGINE VIBRATION MONITOR- 9912519-2	*CF		2789 030676	MTH 19-Oct-2006		O/C			
71EN1 NO. 1 <i>710001 : E1**L</i>	ENGINE 9912545-1	KICT		PW535A DC0233	MTH 30-Jan-2018 HRS 8329.5 LDG 6657		E/C	9876.1		
71EN2 NO. 2 <i>710001 : E2**R</i>	ENGINE 9912545-1	KICT		PW535A DC0234	MTH 30-Jan-2018 HRS 8329.5 LDG 6657		E/C	9873		
721010 E1	GEARBOX	BTV		3059858-01 PKAAA161990	MTH 09-Aug-2010 HRS 3464.9 LDG 2748		O/C	0 0 0		
721010 E2	GEARBOX	BTV		3059858-01 PKAAA161973	MTH 09-Aug-2010 HRS 3467.6 LDG 2759		O/C	0 0 0		
722001 E1	OIL PUMP	UNK		3052415-01 43A923	MTH 31-Dec-2017 HRS 8329.5 LDG 6657		O/C	0 9876.1 7845		
722001 E2	OIL PUMP	UNK		3052415-01 43A959	MTH 24-Dec-2017 HRS 8329.5 LDG 6657		O/C	0 9873 7843		
722608 E1	LP COMPRESSOR FAN ROTOR *CF			3054281-01 A001BFWW	MTH 10-Feb-2004 LDG -1197		15000	0	(15000)13803	6985
722608 E2	LP COMPRESSOR FAN ROTOR *CF			3054281-01 A001DCFT	MTH 10-Feb-2004 LDG -1186		15000	0	(15000)13814	6996
722609 E1	LP COMPRESSOR BOOST ROTOR *CF			3041742-01 A001A631	MTH 10-Feb-2004 LDG -1197		15000	0	(15000)13803	6985
722609 E2	LP COMPRESSOR BOOST ROTOR *CF			3041742-01 A001A630	MTH 10-Feb-2004 LDG -1186		15000	0	(15000)13814	6996
723705 E1	2ND-STAGE TURBINE DISK UNK			3053812-01 A001CP0X	MTH 31-Dec-2017 HRS 8329.5 LDG 6657		13500	9876.1 7845	(13500)12312	5494
723705 E2	2ND-STAGE TURBINE DISK			3053812-01 A001CP10	MTH 01-Mar-2010 HRS 920.6 LDG 716		13500	1902	(13500)12314	5496
724001 E1 INNER	COMBUSTION LINER *CF			3052890-01 A001B64C	MTH 10-Feb-2004		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
724001 E1 OUTER	COMBUSTION LINER	BTV		3052894-01 A0016A2P	MTH 09-Aug-2010 HRS 3464.9 LDG 2748		O/C	0 0 0		
724001 E2 INNER	COMBUSTION LINER	*CF		3052890-01 A001C643	MTH 10-Feb-2004		O/C			
724001 E2 OUTER	COMBUSTION LINER	*CF		3042613-01 A001B24Y	MTH 10-Feb-2004		O/C			
724006 E1	3RD-STAGE TURBINE DISK			3053743-01 A001BFHA	MTH 01-Mar-2007 HRS 917.9 LDG 705		13500	1902	(13500)12303	5485
724006 E2	3RD-STAGE TURBINE DISK			3053743-01 A001D4HL	MTH 01-Mar-2007 HRS 920.6 LDG 716		13500	1902	(13500)12314	5496
724706 E1	1ST-STAGE TURBINE DISK			3053331-01 A001C43R	MTH 09-Aug-2010 HRS 3464.9 LDG 2748		10000	3945	(10000)8803	1985
724706 E2	1ST-STAGE TURBINE DISK			3053331-01 A001H7FN	MTH 30-Sep-2016 HRS 7714.2 LDG 6181		10000	4989.9 4833	(12534)11348	4530
724707 E1	HIGH TURBINE BLADES	UNK		3076231-01 SN-UNKNOWN	MTH 31-Dec-2017 HRS 8329.5 LDG 6657		O/C	0 0 0		
724707 E2	HIGH TURBINE BLADES			3076231-01 SN-UNKNOWN	MTH 30-Sep-2016 HRS 7714.2 LDG 6181		O/C	0 0 0		
724708 E1	1ST-STAGE HP COMPRESSOR ROTOR	UNK		3070301-01 A004368L	MTH 31-Dec-2017 HRS 8329.5 LDG 6657		10000	0 0 0	(17845)16657	9839
724708 E2	1ST-STAGE HP COMPRESSOR ROTOR	UNK		3070301-01 A004420W	MTH 24-Dec-2017 HRS 8329.5 LDG 6657		10000	0 0 0	(17843)16657	9839
724709 E1	2ND-STAGE HP COMPRESSOR ROTOR	*CF		3056210-01 A001CA87	MTH 10-Feb-2004 LDG -1197		13500	0	(13500)12303	5485
724709 E2	2ND-STAGE HP COMPRESSOR ROTOR	*CF		3056210-01 A001CN2K	MTH 10-Feb-2004 LDG -1186		13500	0	(13500)12314	5496
724825 E1	CENTRIFUGAL IMPELLER	*CF		3052661-01 A001B4B1	MTH 10-Feb-2004 LDG -1197		13500	0	(13500)12303	5485
724825 E2	CENTRIFUGAL IMPELLER	*CF		3052661-01 A001CNX8	MTH 10-Feb-2004 LDG -1186		13500	0	(13500)12314	5496
731004 NO. 1	LOW FUEL PRESSURE SWITCH	*CF		1103P0448 SN-UNKNOWN	MTH 19-Oct-2006		O/C			
731004 NO. 2	LOW FUEL PRESSURE SWITCH	*CF		1103P0448 SN-UNKNOWN	MTH 19-Oct-2006		O/C			
733003 NO. 1	FUEL FLOW TRANSMITER	*CF		9-231-28 L9401	MTH 19-Oct-2006		O/C			
733003 NO. 2	FUEL FLOW TRANSMITER	*CF		9-231-28 L9397	MTH 19-Oct-2006		O/C			
731002 E1	FLOW DIVIDER	UNK		823660-02 F57352	MTH 31-Dec-2017 HRS 8329.5 LDG 6657		O/C	0 9876.1 7845		
731002 E2	FLOW DIVIDER	UNK		823660-02 F57531	MTH 24-Dec-2017 HRS 8329.5 LDG 6657		O/C	0 9873 7843		
731125 E1	FUEL MANIFOLD ASSEMBLY			PN SN-UNKNOWN	MTH 10-Feb-2004		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
731125 E2	FUEL MANIFOLD ASSEMBLY			PN SN-UNKNOWN	MTH 10-Feb-2004		O/C	0		
732000 E1	TEMPERATURE SENSOR 3052375-03	UNK		818487-4 KC-03-106	MTH 31-Dec-2017 HRS 8329.5 LDG 6657		O/C			
732000 E2	TEMPERATURE SENSOR 3052375-03	*CF		818487-4 KC03512	MTH 10-Feb-2004		O/C			
732001 E1	FUEL CONTROL UNIT 3074198-04	UNK		1012633-35 F83842	MTH 31-Dec-2017 HRS 8328.5 LDG 6648		O/C	0 0 0		
732001 E2	FUEL CONTROL UNIT 3074198-04	UNK		1012633-35 F65189	MTH 24-Dec-2017 HRS 8328.1 LDG 6657		O/C	0 0 0		
732005 E1	N2 SPEED SENSOR	*CF		3052370-01 CH638	MTH 10-Feb-2004		O/C			
732005 E2	N2 SPEED SENSOR	*CF		3052370-01 CH461	MTH 10-Feb-2004		O/C			
732006 E1	N1 SPEED SENSOR	*CF		3052630-01 CH358	MTH 10-Feb-2004		O/C			
732006 E2	N1 SPEED SENSOR	*CF		3052630-01 CH357	MTH 10-Feb-2004		O/C			
741001 E1	EXCITER IGNITION 31J2807-07	UNK		500335-1 NN02411472	MTH 31-Dec-2017 HRS 8329.5 LDG 6657		O/C			
741001 E2	EXCITER IGNITION 31J2807-07	UNK		500335-1 NNA17400130	MTH 24-Dec-2017 HRS 8329.5 LDG 6657		O/C	0 0 0		
742001 E1 INBOARD	IGNITER 3070508-01	UNK		502600-1 SN-UNKNOWN	MTH 31-Dec-2017 HRS 8329.5 LDG 6657		O/C	0 0 0		
742001 E1 OUTBOARD	IGNITER 3070508-01	UNK		502600-1 SN-UNKNOWN	MTH 31-Dec-2017 HRS 8329.5 LDG 6657		O/C	0 0 0		
742001 E2 INBOARD	IGNITER	LUK		3127408-01 NNA16060035	MTH 20-Apr-2016 HRS 7325.3 LDG 5852		O/C	0 0 0		
742001 E2 OUTBOARD	IGNITER	LUK		3127408-02 NNA16080055	MTH 20-Apr-2016 HRS 7325.3 LDG 5852		O/C	0 0 0		
742002 E1 INBOARD	SHORT IGNITOR LEAD			3127408-02 NNA16080111	MTH 20-Apr-2016 HRS 7322.6 LDG 5841		O/C	0 0 0		
742002 E2 INBOARD	SHORT IGNITOR LEAD			3127408-01 NNA16060035	MTH 20-Apr-2016 HRS 7325.3 LDG 5852		O/C			
742003 E1 OUTBOARD	LONG IGNITOR LEAD			3127408-01 NNA16050058	MTH 20-Apr-2016 HRS 7322.6 LDG 5841		O/C	0 0 0		



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
742003 E2 OUTBOARD	LONG IGNITOR LEAD			3127408-02 NNA16080055	MTH 20-Apr-2016 HRS 7325.3 LDG 5852		O/C	0 0 0		
750001 E1	BLEED VALVE CONTROL 3052768-02	UNK		822728-2-003 04049712	MTH 31-Dec-2017 HRS 8329.5 LDG 6657		O/C			
750001 E2	BLEED VALVE CONTROL 3052768-02	*CF		822728-2-003 02046004	MTH 10-Feb-2004		O/C			
753001 E1	LINEAR TRANSFORMER	UNK		GM9237-2 1958	MTH 31-Dec-2017 HRS 8329.5 LDG 6657		O/C			
753001 E2	LINEAR TRANSFORMER	UNK		GM9237-2 1917	MTH 24-Dec-2017 HRS 8329.5 LDG 6657		O/C			
753002 E1	INTERCOMPRESSOR BLEED VALVE SERVO VALVE	UNK		3075987-01 TR9471	MTH 31-Dec-2017 HRS 8329.5 LDG 6657		O/C	0 0 0		
753002 E2	INTERCOMPRESSOR BLEED VALVE SERVO VALVE			3075987-01 TR5964	MTH 07-Jan-2013 HRS 4851.8 LDG 3841		O/C	0 0 0		
761002	SYNCHRONIZER CONTROL BOX	LUK		213693 2251856	MTH 29-Jul-2014 HRS 6028.8 LDG 4818		O/C			
761003	ENGINE SYNC ACTUATOR	KSAT		5485-066 SN00072	MTH 18-Sep-2010 HRS 2916.8 LDG 2321		O/C	0 0 0		
771006	ENGINE (AMLCD) INDICATOR	*CF		10644D02M05 9912574-5 0040608A	MTH 19-Oct-2006		O/C			
773001 LEFT ENGINE	ACCELEROMETER	*CF		6222SM15 20292	MTH 19-Oct-2006		O/C			
773001 RIGHT ENGINE	ACCELEROMETER	*CF		6222SM15 20385	MTH 19-Oct-2006		O/C			
783001 LEFT ENGINE	THRUST REVERSER ASSEMBLY	*CF		03ND-78002-1 343	MTH 19-Oct-2006		O/C			
783001 RIGHT ENGINE	THRUST REVERSER ASSEMBLY	*CF		03ND-78002-2 342	MTH 19-Oct-2006		O/C			
783002 LEFT ENGINE	THRUST REVERSER CONTROL VALVE	*CF		65680 4772	MTH 19-Oct-2006		O/C			
783002 RIGHT ENGINE	THRUST REVERSER CONTROL VALVE	*CF		65680 3744	MTH 19-Oct-2006		O/C			
783003 LEFT ENGINE	THRUST REVERSER ISOLATION VALVE	*CF		13027-4 3400	MTH 19-Oct-2006		O/C			
783003 RIGHT ENGINE	THRUST REVERSER ISOLATION VALVE	*CF		13027-4 4407	MTH 19-Oct-2006		O/C			
783010 LEFT INBOARD	THRUST REVERSER ACTUATOR			53ND-78203-5 2422	MTH 20-Dec-2013 HRS 5530 LDG 4424		O/C	0 0 0		
783010 LEFT OUTBOARD	THRUST REVERSER ACTUATOR			53ND-78203-5 2444	MTH 20-Dec-2013 HRS 5530 LDG 4424		O/C	0 0 0		



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
783010	THRUST REVERSER ACTUATOR	53ND-78203-5	MTH	19-Oct-2006			O/C			
RIGHT INBOARD	*CF	2197								
783010	THRUST REVERSER ACTUATOR	53ND-78203-5	MTH	04-Jun-2011			O/C	0		
RIGHT OUTBOARD	LUK	1962	HRS	3576.7				0		
			LDG	2819				0		
793002	OIL TEMPERATURE TRANSMITTER	102-00083	MTH	19-Oct-2006			O/C			
LEFT ENGINE	*CF	05523								
793002	OIL TEMPERATURE TRANSMITTER	102-00083	MTH	19-Oct-2006			O/C			
RIGHT ENGINE	*CF	05522								
793004	OIL PRESSURE TRANSMITTER	APTE-237D-1000-250D	MTH	19-Oct-2006			O/C			
LEFT ENGINE	9912464-1 *CF	72326474								
793004	OIL PRESSURE TRANSMITTER	APTE-237D-1000-250D	MTH	19-Oct-2006			O/C			
RIGHT ENGINE	9912464-1 *CF	72326484								
793006	LOW OIL PRESSURE SWITCH	1153P0098-01	MTH	19-Oct-2006			O/C			
LEFT ENGINE	9912466-2 *CF	1696								
793006	LOW OIL PRESSURE SWITCH	1153P0098-01	MTH	19-Oct-2006			O/C			
RIGHT ENGINE	9912466-2 *CF	1702								



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 560-03-02 R01	SUPPLEMENTAL TYPE CERTIFICATE (STC) (SUPERSEDED BY CIL-03-01)			INFORMATIONAL			-			
	MOC :									
SB 560-03-06 R01	OPERATIONAL CERTIFICATION REQUIREMENTS - U.S. TO CANADIAN CONVERSION			OPTIONAL			-			
	MOC :									
SL CIL-03-01	SUPPLEMENTAL TYPE CERTIFICATE (STC)			INFORMATIONAL			-			
	MOC :									
SL CIL-99-02	AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS			RECOMMENDED MTH			-			
	MOC :									
SL CIL-99-03 R01	CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)			RECOMMENDED			-			
	MOC :									
SL CIL-99-04	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW			INFORMATIONAL			-			
	MOC :									
SL 560-99-02 R06	CESCOM PRICES (THIS SL CANCELS SL560-99-02 R5 AND PREVIOUS)			INFORMATIONAL			-			
	MOC :									
SL 560-99-04	MISCELLANEOUS - CESSNA PART NUMBER SUFFIXES FOR REMANUFACTURED PARTS			INFORMATIONAL			A/R			
	MOC :									
SL 560-99-05	MISCELLANEOUS - CESSNA SERVICE DOCUMENT CHANGE NOTIFICATION			INFORMATIONAL			A/R			
	MOC :									
SL 560-99-07	MISCELLANEOUS - TRANSMITTAL OF ROCKWELL COLLINS OPERATORS BULLETIN (OPSB) 0166-17 - THE FMS MAY TURN IN THE WRONG DIRECTION AFTER SEQUENCING A "CLIMB TO" ALTITUDE THAT WAS MANUALLY EDITED OR TEMPERATURE COMPENSATED			INFORMATIONAL			-			
	MOC :									
SL 560-05-12	TIME LIMITS / MAINTENANCE CHECKS - HEAT EXCHANGER LIFE LIMIT			INFORMATIONAL			-			
	MOC :									
SL CIL-99-01 R02	USE OF CORROSION INHIBITING COMPOUNDS			INFORMATIONAL			-			
	MOC :									
SL CIL-20-01 R02	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL			INFORMATIONAL			-			
	MOC :									
SL 560-20-01 R26	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY CIL-20-01 R01)			INFORMATIONAL			-			
	MOC :									
SL 560-20-04	STANDARD PRACTICES - CESSNA STANDARD PRACTICES MANUAL			INFORMATIONAL			-			
	MOC :									
SB 560-21-12 R02	RAM AIR DUCT IMPROVEMENT			OPTIONAL			A/R			
	MOC :									
SB 560-21-28 21SB-28	ALTITUDE PRESSURE SENSOR IMPROVEMENT			OPTIONAL MTH			A/R			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 560-21-32 21SB-32	PRESSURIZATION OUTFLOW VALVE PLUMBING IMPROVEMENT	SWF		RECOMMENDED	MTH 27-Aug-2011 HRS 3753.9 LDG 2973		A/R			Complete
MOC : COMPLIED WITH										
SB 560-21-34 21SB-34	AIR CONDITIONING FAN MOTOR WIRING MODIFICATION	KMKE		OPTIONAL	MTH 07-Mar-2017 HRS 8055 LDG 6442 ACH 2611.3		A/R			Complete
MOC : COMPLIED WITH - COMPLIED WITH SB560-21-34 AIR CONDITIONING FAN MOTOR WIRING MODIFICATION DATED 19 JUN 2009.										
SB 560-21-35	TEMPERATURE CONTROLLER IMPROVEMENT			OPTIONAL	MTH		A/R			
MOC :										
SB 560-21-36	TAILCONE WIRE PROTECTION INSTALLATION			MANDATORY	MTH 08-Jan-2011 HRS 3205.2 LDG 2542		A/R			Complete
MOC : COMPLIED WITH										
SL CIL-21-01	COMPRESSOR MOTOR BRUSH LIFE LIMIT			INFORMATIONAL			-			
MOC :										
SL CIL-21-02 R01	ENVIRONMENTAL HOUR METER INSTALLATION			OPTIONAL	MTH 23-Jan-2014		-			Complete
MOC : COMPLIED WITH - HOUR METER INSTALLED										
SL 560-21-16 21SL-16	AIR CONDITIONING - AIR CONDITIONING EXHAUST DOOR SHAFT SPACER INSPECTION			DISCRETIONARY	MTH		A/R			
MOC :										
SB 560-23-27 R04 23SB-27 : 560R4	COCKPIT SPEAKER MUTE SWITCH INSTALLATION	*CF		OPTIONAL	MTH		A/R			
MOC :										
SB 560-23-38	COMMUNICATIONS - RADIO MANAGEMENT UNIT (RM855) INSTALLATION (SUPERSEDED BY 560-23-38 R01)	LUK		OPTIONAL	MTH 31-Mar-2011 HRS 3431 LDG 2710		A/R			Complete
MOC : COMPLIED WITH - COMPLIED LIVITH CESSNA SERVICE BULLETIN 560-23-38, "COMMUNICATIONS - RADIO MANAGEMENT UNIT (RM855) INSTALLATION", IN ACCORDANCE WITH SERVICE BULLETIN DATED 'DEC 17/2010,										
SB 560-23-39	COMMUNICATIONS - ACP-4110 AUDIO PANEL LOCK-UP IMPROVEMENT			DISCRETIONARY			A/R			
MOC :										
SL 560-23-20	TRANSMITTAL OF HONEYWELL SIL D201005000001			INFORMATIONAL			A/R			
MOC :										
SL 560XL-23-08	TRANSMITTAL OF HONEYWELL SIL D201005000001			INFORMATIONAL			A/R			
MOC :										
SB 560-24-45	ELECTRICAL POWER - MAGNETIC CIRCUIT BREAKER REPLACEMENT			OPTIONAL			A/R			
MOC :										
SB 560-25-26 R03	ARTEX C406-2 THREE-FREQUENCY EMERGENCY LOCATORTRANSMITTER (ELT)			OPTIONAL			A/R			
MOC :										
SB 560-25-31 R02	ARTEX C406-2 THREE-FREQUENCY EMERGENCY LOCATORTRANSMITTER (ELT)			OPTIONAL			A/R			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 560-25-09 25SL-09	EQUIPMENT/FURNISHINGS - TRANSMITTAL OF PACIFIC SCIENTIFIC AEROSPACE SERVICE BULLETIN SB 25-1111432, INFORMATION REGARDING THE POTENTIAL FAILURE OF THE GUARDED ROTARYBUCKLE PLASTIC HANDLE	LUK	MANDATORY	MTH 11-Jul-2008 HRS 1584		A/R			Complete
MOC : COMPLIED WITH									
SL 560-25-10 25SL-10	EQUIPMENT/FURNISHINGS - TRANSMITTAL OF ROCKWELL COLLINS SERVICE BULLETIN 9200XX-44-4 AIRSHOW 400 DIGITAL INTERFACE UNIT (DIU) AND AIRSHOW GENESYS DATA COMMUNICATION UNIT (DCU)		DISCRETIONARY	MTH		A/R			
MOC :									
SL 560-25-12	EQUIPMENT/FURNISHINGS - TRANSMITTAL OF B/E AEROSPACE SERVICE BULLETIN 2524.518-25-02 REPLACEMENT OF SWIVEL ASSEMBLY	ICT	MANDATORY	MTH 20-Sep-2017 HRS 8329.5 LDG 6657		A/R			N/A
MOC : NOT APPLICABLE - SL560-25-12; TRANSMITTAL OF B/E AEROSPACE SB 2524.518-25-02 REPLACEMENT OF SWIVEL ASSEMBLY. DOES NOT APPLY DUE TO AIRCRAFT SERIAL NUMBER.									
ASL 560-26-01 26ASL-01	FIRE PROTECTION - TRANSMITTAL OF MEGGITT SAFETY SYSTEMS SERVICE BULLETIN 26-36 - THERMISTORS DETECTORS	LUK	MANDATORY	MTH 14-Jul-2007 HRS 609		A/R			Complete
MOC : COMPLIED WITH									
SL CIL-26-01 R01	FIRE PROTECTION - FIRE EXTINGUISHER BOTTLE CARTRIDGE GROUND STUD TORQUING	KICT	MANDATORY	MTH 28-Feb-2018 HRS 8329.5 LDG 6657		-			Complete
MOC : COMPLIED WITH - ACCOMPLISHED CIL-26-01 REV. 1. FIRE EXTINGUISHER BOTTLE CARTRIDGE STUD TORQUING, REV.1 DATED 6/16/2016.									
SB 560-27-21 27SB-21	FLIGHT CONTROLS - RUDDER SYSTEM GUARD TUBE IMPROVEMENT		DISCRETIONARY	MTH		A/R			
MOC :									
SB 560-27-22 27SB-22	FLIGHT CONTROLS - RUDDER PEDAL SUPPORT IMPROVEMENT		DISCRETIONARY	MTH 20-Nov-2009 HRS 2349.8 LDG 1879		A/R			Complete
MOC : COMPLIED WITH									
SB 560-27-23	FLIGHT CONTROLS - ELEVATOR BELLCRANK SUPPORT BRACKET INSPECTION AND REPAIR		MANDATORY	MTH 08-Jan-2011 HRS 3205.2 LDG 2542		A/R			Complete
MOC : COMPLIED WITH									
SL 560-27-13 27SL-13	RUDDER PEDAL SUPPORT INSPECTION	*CF	RECOMMENDED	MTH		-			
MOC :									
SL 560-27-14 27SL-14	FLIGHT CONTROLS - AILERON TRIM STOP BLOCK INSPECTION		MANDATORY	MTH 22-Jul-2009 HRS 2215.8 LDG 1753	2	A/R			Complete
MOC : COMPLIED WITH									



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 560-27-15	FLIGHT CONTROLS - AUTOPILOT WIRE HARNESS POSITION			MANDATORY	DAYS 07-Jan-2017 HRS 7959.7 LDG 6366		-			Complete
	MOC : COMPLIED WITH									
SB 560-28-13 28SB-13	FUEL - FUEL LINE SUPPORT INSTALLATION			RECOMMENDED	MTH		A/R			
	MOC :									
SB 560-28-14 R01	FUEL - FUEL CHECK VALVE MODIFICATION			RECOMMENDED	MTH		-			
	MOC :									
SB 560-28-16	FUEL TUBE STANDOFF/CLAMP INSTALLATION			RECOMMENDED	MTH 14-Dec-2015 HRS 7143.8 LDG 5715		-			Complete
	MOC : COMPLIED WITH									
SL 560-28-09	FUEL - FUEL LINE INSPECTION			MANDATORY	DAYS 27-Feb-2012 HRS 4146 LDG 3305		A/R			Complete
	MOC : COMPLIED WITH									
SB 560-29-08 R01	HYDRAULIC PRESSURE LINE ROUTING IMPROVEMENT	LUK		RECOMMENDED	MTH 15-Dec-2012 HRS 4724.2 LDG 3774		A/R			Complete
	MOC : COMPLIED WITH - ACCOMPLISHED SB560-29-08 R1 "HYDRAULIC POWER-HYDRAULIC PRESSURE LINE ROUTING IMPROVEMENT" IN ACCORDANCE WITH SB INSTRUCTIONS DATED 02/10/11									
SL 560-29-08 29SL-08	HYDRAULIC POWER - HYDRAULIC FIREWALL SHUT-OFF VALVE INSPECTION	LUK		MANDATORY	MTH 16-Sep-2007 HRS 773		A/R			Complete
	MOC : COMPLIED WITH									
SL CIL-30-01 R01	APPROVED DEICING PROGRAM UPDATES			INFORMATIONAL			-			
	MOC :									
SL 560-30-08 R16	ICE AND RAIN PROTECTION - APPROVED DEICING PROGRAM UPDATES (SUPERSEDED BY CIL-30-01)			INFORMATIONAL			-			
	MOC :									
SL 560-30-13	PICCOLO TUBE ASSEMBLY INSPECTION			MANDATORY	DAYS 29-May-2015 HRS 6723.9 LDG 5372		-			Complete
	MOC : COMPLIED WITH									
SL CIL-31-01	INDICATING/RECORDING SYSTEMS - CVR, FDR, AND CVDR 90-DAY BATTERY UNDERWATER LOCATOR BEACON (ULB) INSTALLATION			INFORMATIONAL			-			
	MOC :									
SL 560-31-01	INDICATING/RECORDING SYSTEMS - TRANSMITTAL OF L-3 COMMUNICATIONS ALERT BULLETIN NO. CESSNA SB 001			MANDATORY	MTH 17-Mar-2013 HRS 5133 LDG 4097		A/R			N/A
	MOC : NOT APPLICABLE - BY S/N INSTALLED 000596526									
SB 560-32-38 32SB-38	LANDING GEAR - HYDRAULIC PACK ASSEMBLY PLACARD INSTALLATION			RECOMMENDED	MTH	2	A/R			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 560-32-40 R01 <i>32SB-40 : 560R1</i>	LANDING GEAR - 250 POUND ZERO FUEL WEIGHT AND 200 POUND GROSS WEIGHT INCREASE			OPTIONAL	MTH		A/R			
MOC :										
SL CIL-32-01	IMPROVED NOSE WHEEL GREASE SEAL			INFORMATIONAL			-			
MOC :										
SL CIL-32-03	NLG UPLOCK ROLLER BRACKET INSPECTION			RECOMMENDED	MTH HRS		300			
MOC :										
SL CIL-32-04	WIRELESS TIRE PRESSURE MONITORING SYSTEM INSTALLATION			INFORMATIONAL			-			
MOC :										
SL 560-32-40 R01 <i>32SL-40 : 560R1</i>	NOSE LANDING GEAR ICE PROTECTION BOOT INSTALLATION	*CF		OPTIONAL	MTH		-			
MOC :										
SL 560-32-47 R01	TRAILING LINK FORWARD BORE CORROSION PROTECTION	ICT		RECOMMENDED	MTH 20-Sep-2017 HRS 8329.5 LDG 6657		-			Complete
MOC : COMPLIED WITH - SL560-32-47 REV. 1; TRAILING LINK FORWARD BORE CORROSION PROTECTION. WAS ACCOMPLISHED AT PRODUCTION.										
SL 560-32-48 <i>32SL-48</i>	LANDING GEAR - TRANSMITTAL OF GOODRICH SERVICE LETTER SL2060, LANDING GEAR - MAIN WHEEL ASSEMBLY - INTRODUCTION OF AN IMPROVED OPTIONAL THERMAL RELIEF PLUG ASSEMBLY			OPTIONAL	MTH		A/R			
MOC :										
SL 560-32-50 <i>32SL-50</i>	LANDING GEAR - EMERGENCY GEAR RELEASE INSPECTION			MANDATORY	MTH 20-Nov-2009 HRS 2349.8 LDG 1879		A/R			Complete
MOC : COMPLIED WITH										
SL 560-32-51	LANDING GEAR - UNAPPROVED NOSE LANDING GEAR TIRE INSPECTION	ICT		RECOMMENDED	MTH 20-Sep-2017 HRS 8329.5 LDG 6657		A/R			N/A
MOC : NOT APPLICABLE - SL560-32-51; UNAPPROVED NOSE LANDING GEAR TIRE INSPECTION. DOES NOT APPLY DUE TO AIRCRAFT SERIAL NUMBER.										
SB 560-33-27 <i>33SB-27</i>	LIGHTS - LED POSITION, TAIL POSITION, AND ANTI-COLLISION (PTA) LIGHT INSTALLATION	PVG		OPTIONAL	MTH 08-Mar-2019 HRS 8431 LDG 6737		A/R			Complete
MOC : COMPLIED WITH - REMOVED OLD NAV/STOBE LIGHTS REPLACED WITH SB560-33-27 (.WING) SEALED AND OPS CKED OK										
SB 560-33-28 <i>33SB-28</i>	LIGHTS - LED BEACON LIGHT INSTALLATION			OPTIONAL	MTH		A/R			
MOC :										
SB 560-33-31 <i>33SB-31</i>	LED TAIL FLOODLIGHT UPGRADE			OPTIONAL	MTH		A/R			
MOC :										
SB 560-33-32	LED REPLACEMENT LIGHT FOR THE BAGGAGE COMPARTMENT			OPTIONAL			A/R			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 560-33-33 R01	LED REPLACEMENT LIGHT FOR THE WING LANDING/TAXI LIGHT ASSEMBLY			OPTIONAL			-			
	MOC :									
SB 560-33-35	LED LANDING GEAR INDICATION LIGHT INSTALLATION			OPTIONAL			A/R			
	MOC :									
SL CIL-33-01	TRANSMITTAL OF RADIANT POWER CORP. SB-RPC-001, PROCEDURE TO REPLACE OBSOLETE CONNECTOR ASSEMBLY FOR CBS28 EMERGENCY BATTERY			INFORMATIONAL			-			
	MOC :									
SB 560-33-33	LED REPLACEMENT LIGHT FOR THE WING LANDING/TAXI LIGHT ASSEMBLY			OPTIONAL			O/C			
	MOC :									
SB 560-34-102 <i>34SB-102</i>	NAVIGATION - SECONDARY FLIGHT DISPLAY AIRSPEED INDICATION IMPROVEMENT			MANDATORY	MTH 20-Nov-2009 HRS 2349.8 LDG 1879		A/R			Complete
	MOC : COMPLIED WITH									
SB 560-34-124 R01 <i>34SB-124 : 560R1</i>	RUNWAY AWARENESS ADVISORY SYSTEM (RAAS) INSTALLATION	*CF		OPTIONAL	MTH		A/R			
	MOC :									
SB 560-34-128 R03 <i>34SB-128 : 560R3</i>	NAVIGATION - ENHANCED SURVEILLANCE TRANSPONDER INSTALLATION	*CF		OPTIONAL	MTH		A/R			
	MOC :									
SB 560-34-131 <i>34SB-131</i>	RUNWAY AWARENESS AND ADVISORY SYSTEM (RAAS) AUDIO INHIBIT SWITCH INSTALLATION			OPTIONAL	MTH		A/R			
	MOC :									
SB 560-34-137	NAVIGATION - GH-3000 MAGNETOMETER CIRCUIT BREAKER INSTALLATION (SUPERSEDED BY 560-34-137 R01)			OPTIONAL	MTH 20-Nov-2009 HRS 2349.8 LDG 1879		A/R			Complete
	MOC : COMPLIED WITH									
SB 560-34-138 R01 <i>34SB-138 : 560R1</i>	NAVIGATION - GNS-XDXLS FMS SOFTWARE UPGRADE TO MOD 8			OPTIONAL	MTH		A/R			
	MOC :									
SB 560-34-149 R01	NAVIGATION - DBU-5000 DATABASE UNIT (FLASH MEMORY) SOFTWARE DATABASE LOADER			OPTIONAL			A/R			
	MOC :									
SB 560-34-150 R02 <i>34SB-150 : 560R2</i>	COLLINS FMS-3000 SOFTWARE UPDATE (SUPERSEDED BY 560-34-150 R03)	ICT		RECOMMENDED	MTH 20-Sep-2017 HRS 8329.5 LDG 6657		A/R			N/A
	MOC : NOT APPLICABLE - SB560-34-150 REV. 2; COLLINS FMS-3000 SOFTWARE UPDATE. DOES NOT APPLY DUE TO AIRCRAFT SERIAL NUMBER.									
SB 560-34-154 R01	INSTALLATION OF SCN 802.8 FOR UNS-1 FMS			RECOMMENDED			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB 560-34-155 R01	UNIVERSAL FMS WAAS UPGRADE KICT	OPTIONAL	MTH 20-Apr-2018 HRS 8329.5 LDG 6657							Complete
MOC : COMPLIED WITH - ACCOMPLISHED SB560-34-155 REVISION 01 UNIVERSAL FMS WAAS UPGRADE										
SB 560-34-156 R01	NAVIGATION - UNIVERSAL SOLID STATE DATA TRANSFER UNIT (SSDTU) UPGRADE OPTIONAL									
MOC :										
SB 560-34-156	NAVIGATION - UNIVERSAL SOLID STATE DATA TRANSFER UNIT (SSDTU) UPGRADE KICT		MTH 20-Apr-2018 HRS 8329.5 LDG 6657							Complete
MOC : COMPLIED WITH - ACCOMPLISHED SB560-34-156 NAVIGATION, UNIVERSAL SOLID STATE DATA TRANSFER UNIT (SSDTU) UPGRADE.										
SB 560-34-157	ROCKWELL COLLINS IOC-3100 UPGRADE ICT	RECOMMENDED	MTH 20-Sep-2017 HRS 8329.5 LDG 6657			A/R				N/A
MOC : NOT APPLICABLE - SB560-34-157; ROCKWELL COLLINS IOC-3100 UPGRADE. DOES NOT APPLY DUE TO AIRCRAFT SERIAL NUMBER.										
SB 560-34-162	NAVIGATION - HONEYWELL TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM II (TCAS II) VERSION 7.1 SOFTWARE UPDATE OPTIONAL									
MOC :										
SB 560-34-164 R02	NAVIGATION - AUTOMATIC DEPENDENT SURVEILLANCE BROADCAST (ADS-B) OUT TRANSPONDER INSTALLATION KICT	OPTIONAL	MTH 20-Apr-2018 HRS 8329.5 LDG 6657							Complete
MOC : COMPLIED WITH - ACCOMPLISHED SB560-34-164 REVISION 02 NAVIGATION, AUTOMATIC DEPENDENT SURVEILLANCE BROADCAST (ADS-B) OUT TRANSPONDER INSTALLATION.										
SB 560-34-165	NAVIGATION - UNIVERSAL UNS-1ESPW FMS SOFTWARE UPGRADE 1000.8 KICT	OPTIONAL	MTH 20-Apr-2018 HRS 8329.5 LDG 6657							Complete
MOC : COMPLIED WITH - ACCOMPLISHED SB560-34-165 NAVIGATION, UNIVERSAL UNS-1ESPW FMS SOFTWARE UPGRADE 1000.8.										
ASL 560-34-21 34ASL21	TRANSMITTAL OF HONEYWELL TECHNICAL NEWSLETTER A23-3850-001 ICT	MANDATORY	MTH 19-Oct-2006 HRS 17			A/R				Complete
MOC : COMPLIED WITH										
SL CIL-34-01	TRANSMIT UNIVERSAL AVIONICS ALERT SERVICE BULLETIN 3XXX.(.)-34-3508 INFORMATIONAL									
MOC :										
SL CIL-34-02	TRANSMITTAL OF HONEYWELL SIL D201301000032, PRIMUS II INTEGRATED RADIO SYSTEM MANDATORY		MTH 14-Jun-2013 HRS 5133 LDG 4097							Complete
MOC : COMPLIED WITH										
SL CIL-34-03 R02	TRANSMITTAL OF HONEYWELL SERVICE BULLETIN 7014300-22-16, MODIFICATION (MOD) R TO DU-870 DISPLAY UNIT PN 7014300-901 AND -902; DECREASE FAILURE RATE OF HIGH VOLTAGE POWER SUPPLY (HVPS) BECAUSE OF HIGH HUMIDITY INFORMATIONAL									
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 560-34-23 <i>34SL-23</i>	GNS-XL FLIGHT MANAGEMENT SYSTEM (FMS) MOD 4 UPGRADE (SUPERSEDED BY SL560-34-23 R01)	ICT		RECOMMENDED	MTH 19-Oct-2006 HRS 17		-			N/A
MOC : NOT APPLICABLE										
SL 560-34-37	HONEYWELL SERVICE INFORMATION LETTER DU-870 DRY OUTPROCEDURES			INFORMATIONAL			A/R			
MOC :										
SL 560-34-38 R01	SERVICE INFORMATION FROM HONEYWELL			INFORMATIONAL			-			
MOC :										
SL 560-34-40	NAVIGATION - TRANSMITTAL OF ROCKWELL COLLINS SERVICE INFORMATION LETTER 16-1 FUNCTION OF RESET OVERRIDE MODE SWITCH ON XM WEATHER RECEIVER FOR PROLINE 21/PROLINE FUSION			INFORMATIONAL			-			
MOC :										
SB 560-35-09 R01 <i>35SB-09 : 560R1</i>	EROS MLD20-506 OXYGEN MASK INSTALLATION	*CF		OPTIONAL	MTH		-			
MOC :										
SB 560-35-12 <i>35SB-12</i>	EROS MLD20-510 OXYGEN MASK INSTALLATION	*CF		OPTIONAL	MTH		-			
MOC :										
SL CIL-35-05	OXYGEN - TRANSMITTAL OF ZODIAC AEROSPACE SB MCF-SBU-35-001	KICT		MANDATORY	DAYS 28-Feb-2018 HRS 8329.5 LDG 6657		-			N/A
MOC : NOT APPLICABLE - ACCOMPLISHED SERVICE LETTER CIL-35-05 OXYGEN-TRANSMITTAL OF ZODIAC AEROSPACE SB MCF-SBU -35-001 DATED 1/08/2016. THIS SERVICE LETTER IS NOT APPLICABLE DUE TO EQUIPMENT NOT INSTALLED.										
SL 560-35-06	OXYGEN - OXYGEN BOTTLE INSPECTION			INFORMATIONAL	MTH		A/R			
MOC :										
SL 560-35-07 R02	OXYGEN - TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240	LUK		MANDATORY	MTH 15-Dec-2012 HRS 4724.2 LDG 3774		-			Complete
MOC : COMPLIED WITH - ACCOMPLISHED CESSNA SL560-35-07R2 DATED 10/25/12 "OXYGEN-TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240".										
SB 560-52-13	DOORS-CXX WIDE DOOR KICK PLATE IMPR	ICT		RECOMMENDED	MTH 10-Oct-2018 HRS 8362.7 LDG 6690		-			N/A
MOC : NOT APPLICABLE - SB560-52-13; CXX WIDE DOOR KICK PLATE IMPROVEMENT. DOES NOT APPLY DUE TO WIDE DOOR NOT INSTALLED.										
SB 560-52-17 R01 <i>52SB-17 : 560R1</i>	DOORS - IMPROVEMENT FOR THE CABIN ENTRY STEPS			OPTIONAL	MTH		A/R			
MOC :										
SB 560-52-21	WIDE DOOR INSTALLATION MODIFICATION			OPTIONAL			-			
MOC :										
ASL 560-52-04 <i>52ASL-04</i>	DOORS - EMERGENCY DOOR INSPECTION	TOL		MANDATORY	MTH 27-Nov-2007 HRS 1000		A/R			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
ASL 560-52-05	DOORS - EMERGENCY EXIT INSPECTION	LUK		MANDATORY	DAYS 04-Jun-2011 HRS 3576.7 LDG 2819		A/R			Complete
MOC : COMPLIED WITH - COMPLIED WITH ASL560-52-05 "DOORS - EMERGENCY EXIT INSPECTION" IN ACCORDANCE WITH ALERT SERVICE LETTER INSTRUCTIONS DATED JAN 12/2011.										
SB 560-53-30 R01	FUSELAGE - FORWARD SHEAR TIE BOLT REPLACEMENT (SUPERSEDED BY 560-53-30 R02)			MANDATORY	MTH 02-Oct-2012 HRS 4565.6 LDG 3654		-			Complete
MOC : COMPLIED WITH										
SB 560-53-37 R01 53SB-37 : 560R1	FUSELAGE - MAIN CARRY-THRU SPAR FASTENER INSPECTION	KCMH		MANDATORY	MTH 06-Mar-2009 HRS 1999.3 LDG 1568		A/R			Complete
MOC : COMPLIED WITH										
SL 560-53-03	LIGHTNING DIVERTER STRIP INSTALLATION/REPAIR PROCEDURE CHANGE (RADOME)	LUK		INFORMATIONAL	MTH 13-Jun-2012 HRS 4363.3 LDG 3468		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH CESSNA 560 SL560-53-03, "FUSELAGE - LIGHTENING DIVERTER STRIP INST ALLATION/REPAIR PROCEDURE (RADOME) IAW SL INSTRUCTIONS DATED SEP 18,2001.										
SL 560-54-01 R01	NACELLES/ PYLONS - PYLON DRAIN HOLE INSPECTION			RECOMMENDED	MTH		-			
MOC :										
SL 560-55-03 R02	HORIZONTAL STABILIZER RIB BORESCOPE INSPECTION			MANDATORY	MTH 14-Dec-2015 HRS 7143.8 LDG 5715		-			Complete
MOC : COMPLIED WITH										
SB 560-71-08 71SB-08	POWER PLANT - ENGINE INLET FLANGE IMPROVEMENT			RECOMMENDED	MTH 20-Nov-2009 HRS 2349.8 LDG 1879		A/R			Complete
MOC : COMPLIED WITH										
SB 560-71-09 R01	ENGINE FUEL MANIFOLD DRAIN LINE INSTALLATION (SUPERSEDED BY 560-71-09 R02)			OPTIONAL	MTH 09-Dec-2014 HRS 6314.5 LDG 5067		-			Complete
MOC : COMPLIED WITH										
SL CIL-71-01	TRANSMITTAL OF PRATT & WHITNEY CANADA SERVICE BULLETIN 30463			OPTIONAL			-			
MOC :										
SL 560-72-22 72SL-22	ENGINE - TRANSMITTAL OF PRATT & WHITNEY CANADA SERVICE BULLETIN PW500-72-30252 NUMBER FOUR BEARING OIL PRESSURE AND OIL SCAVENGE TUBES - REPLACEMENT OF			RECOMMENDED	MTH		A/R			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 560-72-27 LEFT ENGINE <i>72SL-27 : E1**L</i>	TRANSMITTAL OF PRATT AND WHITNEY CANADA (P&WC) SERVICE BULLETIN PW500-72-30409, TURBOFAN ENGINE HYDROMECHANICAL FUEL CONTROL UNIT - REPLACEMENT,MODIFICATION OF	KICT	MANDATORY	MTH 28-Feb-2018 HRS 8329.5 LDG 6657		A/R			Complete
MOC : COMPLIED WITH - ACCOMPLISHED SL560-72-27 LEFT ENGINE TRANSMITTAL OF PRATT AND WHITNEY CANADA SERVICE BULLETIN PW500-72-30409, TURBOFAN ENGINE HYDROMECHANICAL FUEL CONTROL UNIT REPLACEMENT / MODIFICATION, DATED 2/09/2010. PREVIOUSLY COMPLIED WITH DUE TO PART INSTALLED ON ENGINE.									
SL 560-72-27 RIGHT ENGINE <i>72SL-27 : E2**R</i>	TRANSMITTAL OF PRATT AND WHITNEY CANADA (P&WC) SERVICE BULLETIN PW500-72-30409, TURBOFAN ENGINE HYDROMECHANICAL FUEL CONTROL UNIT - REPLACEMENT,MODIFICATION OF	KICT	MANDATORY	MTH 28-Feb-2018 HRS 8329.5 LDG 6657		A/R			Complete
MOC : COMPLIED WITH - ACCOMPLISHED SL560-72-27 RIGHT ENGINE TRANSMITTAL OF PRATT AND WHITNEY CANADA SERVICE BULLETIN PW500-72-30409, TURBOFAN ENGINE HYDROMECHANICAL FUEL CONTROL UNIT REPLACEMENT / MODIFICATION, DATED 2/09/2010. PREVIOUSLY COMPLIED WITH DUE TO PART INSTALLED ON ENGINE.									
SL 560-72-28 <i>72SL-28</i>	TRANSMITTAL OF PRATT AND WHITNEY CANADA SERVICE BULLETIN PW500-72-30382,MODIFICATION OF THE TURBINE EXHAUST CONE, INNER BY-PASS DUCT ASSEMBLY, FUEL MANIFOLD, FUEL SHUT-OFF CABLE GROMMETS AND COVER PLATE FAIRING	ICT	RECOMMENDED	MTH 10-Oct-2018 HRS 8362.7 LDG 6690		A/R			Complete
MOC : COMPLIED WITH - SL560-72-28; TRANSMITTAL OF P&W SB PW500-72-30382. IS C/W DUE TO SB PW500-72-30382 REV. 1 WAS ACCOMPLISHED ON 9-17-09.									
SB PW500-72-30121 E1	LIGHTWEIGHT SPACER FAN CASE AND NO. 1 & 2 BEARING HOUSING - INTRODUCTION OF		CATEGORY 7	MTH 10-Feb-2004		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW500-72-30121 E2	LIGHTWEIGHT SPACER FAN CASE AND NO. 1 & 2 BEARING HOUSING - INTRODUCTION OF		CATEGORY 7	MTH 10-Feb-2004		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW500-72-30129 E1	IGNITION EXCITER - REPLACEMENT OF		CATEGORY 3	MTH 10-Feb-2004		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW500-72-30129 E2	IGNITION EXCITER - REPLACEMENT OF		CATEGORY 3	MTH 10-Feb-2004		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW500-72-30131 R1 E1	COLD START VALVE ASSEMBLY - REPLACEMENT OF		CATEGORY 3	MTH 10-Feb-2004		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW500-72-30131 R1 E2	COLD START VALVE ASSEMBLY - REPLACEMENT OF		CATEGORY 3	MTH 10-Feb-2004		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW500-72-30133 R1 E1	DIFFUSER SET - REPLACEMENT OF		CATEGORY 7	MTH 10-Feb-2004		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW500-72-30133 R1 E2	DIFFUSER SET - REPLACEMENT OF		CATEGORY 7	MTH 10-Feb-2004		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE									



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30134 E1	IGNITION CABLE - REROUTING		CATEGORY 6	MTH 10-Feb-2004		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW500-72-30134 E2	IGNITION CABLE - REROUTING		CATEGORY 6	MTH 10-Feb-2004		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW500-72-30136 E1	LOW PRESSURE TURBINE DISC ASSEMBLY - REPLACEMENT OF		CATEGORY 7	MTH 10-Feb-2004		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW500-72-30136 E2	LOW PRESSURE TURBINE DISC ASSEMBLY - REPLACEMENT OF		CATEGORY 7	MTH 10-Feb-2004		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW500-72-30138 E1	ALTERNATOR BLANKING COVER - REPLACEMENT OF		CATEGORY 7	MTH 10-Feb-2004		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW500-72-30138 E2	ALTERNATOR BLANKING COVER - REPLACEMENT OF		CATEGORY 7	MTH 10-Feb-2004		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW500-72-30139 E1	ACCESSORY GEARBOX MANIFOLD ASSEMBLY - REPLACEMENT OF		CATEGORY 7	MTH 10-Feb-2004		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW500-72-30139 E2	ACCESSORY GEARBOX MANIFOLD ASSEMBLY - REPLACEMENT OF		CATEGORY 7	MTH 10-Feb-2004		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW500-72-30141 E1	COMPRESSOR STATOR ASSEMBLY - REPLACEMENT OF		CATEGORY 7	MTH 10-Feb-2004		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW500-72-30141 E2	COMPRESSOR STATOR ASSEMBLY - REPLACEMENT OF		CATEGORY 7	MTH 10-Feb-2004		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW500-72-30145 E1	LOW PRESSURE COMPRESSOR (LPC) FAN ROTOR - REPLACEMENT OF		CATEGORY 7	MTH 10-Feb-2004		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW500-72-30145 E2	LOW PRESSURE COMPRESSOR (LPC) FAN ROTOR - REPLACEMENT OF		CATEGORY 7	MTH 10-Feb-2004		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW500-72-30146 E1	TWO PART EPOXY TO INSPECTION LACQUER - REPLACEMENT OF		CATEGORY 8	MTH 10-Feb-2004		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW500-72-30146 E2	TWO PART EPOXY TO INSPECTION LACQUER - REPLACEMENT OF		CATEGORY 8	MTH 10-Feb-2004		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE									



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30148 R2 E1	ACCESSORY DRIVE GEARSHAFT AND LIP SEAL - REPLACEMENT OF		CATEGORY 7	MTH 10-Feb-2004		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW500-72-30148 R2 E2	ACCESSORY DRIVE GEARSHAFT AND LIP SEAL - REPLACEMENT OF		CATEGORY 7	MTH 10-Feb-2004		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW500-72-30149 E1	FAN EXIT VANE RING ASSEMBLY - REPLACEMENT OF		CATEGORY 7	MTH 10-Feb-2004		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW500-72-30149 E2	FAN EXIT VANE RING ASSEMBLY - REPLACEMENT OF		CATEGORY 7	MTH 10-Feb-2004		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW500-72-30151 R1 E1	GAS GENERATOR CASE - REPLACEMENT OF		CATEGORY 7	MTH 10-Feb-2004		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW500-72-30151 R1 E2	GAS GENERATOR CASE - REPLACEMENT OF		CATEGORY 7	MTH 10-Feb-2004		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW500-72-30152 E1	LOW PRESSURE TURBINE 2ND STAGE DISC ASSEMBLY - REPLACEMENT OF		CATEGORY 7	MTH 10-Feb-2004		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW500-72-30152 E2	LOW PRESSURE TURBINE 2ND STAGE DISC ASSEMBLY - REPLACEMENT OF		CATEGORY 7	MTH 10-Feb-2004		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW500-72-30153 E1	LOW PRESSURE TURBINE 2ND STAGE DISC ASSEMBLY - REPLACEMENT OF		CATEGORY 9	MTH 10-Feb-2004		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW500-72-30153 E2	LOW PRESSURE TURBINE 2ND STAGE DISC ASSEMBLY - REPLACEMENT OF		CATEGORY 9	MTH 10-Feb-2004		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW500-72-30154 R1 E1	GREEK ASCOLOY TO WASPALOY BOLTS - REPLACEMENT OF		CATEGORY 8	MTH 10-Feb-2004		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW500-72-30154 E2	GREEK ASCOLOY TO WASPALOY BOLTS - REPLACEMENT OF		CATEGORY 8	MTH 10-Feb-2004		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW500-72-30155 E1	NO. 4 BEARING OIL SCAVENGE TUBE ASSEMBLY - REPLACEMENT OF		CATEGORY 8	MTH 10-Feb-2004		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW500-72-30155 E2	NO. 4 BEARING OIL SCAVENGE TUBE ASSEMBLY - REPLACEMENT OF		CATEGORY 8	MTH 10-Feb-2004		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE									



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30156 E1	ANTI-ICING VALVE - REPLACEMENT OF		CATEGORY 7	MTH 10-Feb-2004		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW500-72-30156 E2	ANTI-ICING VALVE - REPLACEMENT OF		CATEGORY 7	MTH 10-Feb-2004		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW500-72-30158 E1	HIGH PRESSURE COMPRESSOR SHAFT - REPLACEMENT OF		CATEGORY 7	MTH 10-Feb-2004		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW500-72-30158 E2	HIGH PRESSURE COMPRESSOR SHAFT - REPLACEMENT OF		CATEGORY 7	MTH 10-Feb-2004		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW500-72-30163 E1	P3 BLEED AIR COVER ASSEMBLY - REPLACEMENT OF		CATEGORY 7	MTH 10-Feb-2004		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW500-72-30163 E2	P3 BLEED AIR COVER ASSEMBLY - REPLACEMENT OF		CATEGORY 7	MTH 10-Feb-2004		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW500-72-30164 E1	ACCESSORY DRIVE AND ALTERNATOR DRIVE GEARSHAFTS - REPLACEMENT OF			MTH 10-Feb-2004		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW500-72-30164 E2	ACCESSORY DRIVE AND ALTERNATOR DRIVE GEARSHAFTS - REPLACEMENT OF			MTH 10-Feb-2004		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW500-72-30168 E1	TURBINE EXHAUST CASE ASSEMBLY - REPLACEMENT OF		CATEGORY 7	MTH 10-Feb-2004		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW500-72-30168 E2	TURBINE EXHAUST CASE ASSEMBLY - REPLACEMENT OF		CATEGORY 7	MTH 10-Feb-2004		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW500-72-30170 R2 E1	BELLOWS SEAL FOR CABIN BLEED AIR TUBES - REPLACEMENT OF		CATEGORY 3	MTH 10-Feb-2004		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW500-72-30170 R2 E2	BELLOWS SEAL FOR CABIN BLEED AIR TUBES - REPLACEMENT OF		CATEGORY 3	MTH 10-Feb-2004		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW500-72-30174 R1 E1	IGNITION EXCITER BOX - REPLACEMENT OF		CATEGORY 5	MTH 10-Feb-2004		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW500-72-30174 R1 E2	IGNITION EXCITER BOX - REPLACEMENT OF		CATEGORY 5	MTH 10-Feb-2004		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE								



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30175 E1	FUEL PRESSURE TUBE - REPLACEMENT OF			CATEGORY 7	MTH 10-Feb-2004		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW500-72-30175 E2	FUEL PRESSURE TUBE - REPLACEMENT OF			CATEGORY 7	MTH 10-Feb-2004		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW500-72-30176 E1	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY				MTH 10-Feb-2004		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW500-72-30176 E2	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY				MTH 10-Feb-2004		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW500-72-30177 E1	REPLACEMENT OF HIGH PRESSURE (HPT) SEAL RING			CATEGORY 6	MTH 10-Feb-2004		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW500-72-30177 E2	REPLACEMENT OF HIGH PRESSURE (HPT) SEAL RING			CATEGORY 6	MTH 10-Feb-2004		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW500-72-30183 E1	REPLACEMENT OF ACCESSORY GEARBOX ANGLE BRACKET			CATEGORY 7	MTH 10-Feb-2004		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW500-72-30183 E2	REPLACEMENT OF ACCESSORY GEARBOX ANGLE BRACKET			CATEGORY 7	MTH 10-Feb-2004		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW500-72-30184 R1 E1	REPLACEMENT OF FUEL NOZZLE			CATEGORY 7	MTH 10-Feb-2004		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW500-72-30184 R1 E2	REPLACEMENT OF FUEL NOZZLE			CATEGORY 7	MTH 10-Feb-2004		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW500-72-30186 E1	REPLACEMENT OF DIFFUSER EXIT DUCT ASSEMBLY			CATEGORY 9	MTH 10-Feb-2004		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW500-72-30186 E2	REPLACEMENT OF DIFFUSER EXIT DUCT ASSEMBLY			CATEGORY 9	MTH 10-Feb-2004		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW500-72-30188 E1	INTRODUCTION OF OPTIONAL COMBUSTION CHAMBER LINER ASSEMBLY			CATEGORY 9	MTH 10-Feb-2004		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW500-72-30188 E2	INTRODUCTION OF OPTIONAL COMBUSTION CHAMBER LINER ASSEMBLY	UNK		CATEGORY 9	MTH 24-Dec-2017		-			Complete
					HRS 8329.5					
					LDG 6657					
	MOC : COMPLIED WITH									



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30191 E1	TURBINE EXHAUST CASE ASSEMBLY - REPLACEMENT CATEGORY 7			MTH	10-Feb-2004		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW500-72-30191 E2	TURBINE EXHAUST CASE ASSEMBLY - REPLACEMENT CATEGORY 7			MTH	10-Feb-2004		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW500-72-30194 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT CATEGORY 7			MTH	10-Feb-2004		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW500-72-30194 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT CATEGORY 7			MTH	10-Feb-2004		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW500-72-30197 E1	INTRODUCTION OF NEW FUEL MANIFOLD			MTH	10-Feb-2004		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW500-72-30197 E2	INTRODUCTION OF NEW FUEL MANIFOLD			MTH	10-Feb-2004		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW500-72-30202 E1	INTRODUCTION OF RE-PROFILED GRAFOIL GASKETS CATEGORY 5			MTH	10-Feb-2004		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW500-72-30202 E2	INTRODUCTION OF RE-PROFILED GRAFOIL GASKETS CATEGORY 5			MTH	10-Feb-2004		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW500-72-30206 E1	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY CATEGORY 7			MTH	10-Feb-2004		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW500-72-30206 E2	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY CATEGORY 7			MTH	10-Feb-2004		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW500-72-30210 E1	REMOVAL OF FUEL NOZZLE TO FUEL MANIFOLD WASHERS CATEGORY 8			MTH	10-Feb-2004		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW500-72-30210 E2	REMOVAL OF FUEL NOZZLE TO FUEL MANIFOLD WASHERS CATEGORY 8			MTH	10-Feb-2004		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW500-72-30212 R1 E1	INTERNAL VISUAL INSPECTION OF FUEL TUBE CATEGORY 3			MTH			-			
	MOC :									
SB PW500-72-30212 R1 E2	INTERNAL VISUAL INSPECTION OF FUEL TUBE CATEGORY 3			MTH			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30213 R1 E2	INSPECTION OF FUEL TUBE			CATEGORY 3	MTH		-			
MOC :										
SB PW500-72-30216 E1	INTRODUCTION OF IMPROVED COMBUSTION CHAMBER LINER ASSEMBLY			CATEGORY 7	MTH	10-Feb-2004	-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW500-72-30216 E2	INTRODUCTION OF IMPROVED COMBUSTION CHAMBER LINER ASSEMBLY	UNK		CATEGORY 7	MTH	24-Dec-2017	-			Complete
HRS 8329.5 LDG 6657										
MOC : COMPLIED WITH										
SB PW500-72-30217 R02 E1	INSPECTION OF FUEL TUBE (SUPERSEDED BY PW500-72-30217 R03)			CATEGORY 3	MTH	10-Feb-2004	-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW500-72-30217 E2	INSPECTION OF FUEL TUBE (SUPERSEDED BY PW500-72-30217 R01)				MTH	10-Feb-2004	-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW500-72-30218 R1 E1	REPLACEMENT/MODIFICATION OF FOKKER ELMO ENGINE HARNESS			CATEGORY 8	MTH	10-Feb-2004	-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW500-72-30218 E2	REPLACEMENT/MODIFICATION OF FOKKER ELMO ENGINE HARNESS			CATEGORY 8	MTH	10-Feb-2004	-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW500-72-30221 R1 E1	REPLACEMENT OF T1/FCU TEMPERATURE SENSOR			CATEGORY 8	MTH	10-Feb-2004	-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW500-72-30221 R1 E2	REPLACEMENT OF T1/FCU TEMPERATURE SENSOR			CATEGORY 8	MTH	10-Feb-2004	-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW500-72-30222 R1 E1	REPLACEMENT OF HIGH COMPRESSOR ROTOR			CATEGORY 7	MTH	10-Feb-2004	-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW500-72-30222 R1 E2	REPLACEMENT OF HIGH COMPRESSOR ROTOR			CATEGORY 7	MTH	10-Feb-2004	-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW500-72-30225 E1	REPLACEMENT OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 7	MTH	10-Feb-2004	-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW500-72-30225 E2	REPLACEMENT OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 7	MTH	10-Feb-2004	-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30228 R2 E1	INTRODUCTION OF CONVERSION OF PW535A BUILD SPECIFICATION 909 TO 1155 (PROGRESSIVE MAINTENANCE PROGRAM)		CATEGORY 3	MTH 15-Apr-2004 HRS -1420.1 LDG -1105		-			Complete
MOC : COMPLIED WITH									
SB PW500-72-30228 R2 E2	INTRODUCTION OF CONVERSION OF PW535A BUILD SPECIFICATION 909 TO 1155 (PROGRESSIVE MAINTENANCE PROGRAM)		CATEGORY 3	MTH 15-Apr-2004 HRS -1417.4 LDG -1094		-			Complete
MOC : COMPLIED WITH									
SB PW500-72-30233 E1	REPLACEMENT OF OIL FILLER CAP		CATEGORY 7	MTH 10-Feb-2004		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW500-72-30233 E2	REPLACEMENT OF OIL FILLER CAP		CATEGORY 7	MTH 10-Feb-2004		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW500-72-30235 E1	REPLACEMENT OF REAR BYPASS DUCT MOUNTING FLANGE FRONT AND REAR HEAT SHIELDS		CATEGORY 7	MTH 10-Feb-2004		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW500-72-30235 E2	REPLACEMENT OF REAR BYPASS DUCT MOUNTING FLANGE FRONT AND REAR HEAT SHIELDS		CATEGORY 7	MTH 10-Feb-2004		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW500-72-30239 E1	REPLACEMENT OF NO. 4 CYLINDRICAL ROLLER BEARING		CATEGORY 7	MTH 10-Feb-2004		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW500-72-30239 E2	REPLACEMENT OF NO. 4 CYLINDRICAL ROLLER BEARING		CATEGORY 7	MTH 10-Feb-2004		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW500-72-30241 E1	REPOSITIONING OF T1 THERMOCOUPLE WIRING HARNESS CLAMP		CATEGORY 8	MTH 10-Feb-2004		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW500-72-30241 E2	REPOSITIONING OF T1 THERMOCOUPLE WIRING HARNESS CLAMP		CATEGORY 8	MTH 10-Feb-2004		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW500-72-30247 E2	REPLACEMENT OF AC ALTERNATOR DRIVE GREASHAFT		CATEGORY 7			-			
MOC :									
SB PW500-72-30252 R2 E1	REPLACEMENT OF NO. 4 BRG OIL PRESSURE AND OIL SCAVENGE TUBES		CATEGORY 6	MTH		-			
MOC :									
SB PW500-72-30252 R2 E2	REPLACEMENT OF NO. 4 BRG OIL PRESSURE AND OIL SCAVENGE TUBES		CATEGORY 6	MTH		-			
MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30256 R1 E1	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY			CATEGORY 7			-			
MOC :										
SB PW500-72-30256 R1 E2	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY			CATEGORY 7			-			
MOC :										
SB PW500-72-30258 R2 E1	REPLACEMENT OF COMBUSTION CHAMBER LINER			CATEGORY 7			-			
MOC :										
SB PW500-72-30258 R2 E2	REPLACEMENT OF COMBUSTION CHAMBER LINER	UNK		CATEGORY 7	MTH 24-Dec-2017 HRS 8329.5 LDG 6657		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30264 R2 E1	REPLACEMENT OF STARTER-GENERATOR-DRIVE GEARSHAFT AND PLAIN SEAL	BTV		CATEGORY 8	MTH 09-Aug-2010 HRS 3464.9 LDG 2748		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30264 R2 E2	REPLACEMENT OF STARTER-GENERATOR-DRIVE GEARSHAFT AND PLAIN SEAL	BTV		CATEGORY 8	MTH 09-Aug-2010 HRS 3467.6 LDG 2759		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30266 R1 E1	REPLACEMENT/MODIFICATION OF IGNITION EXCITER	UNK		CATEGORY 7	MTH 31-Dec-2017 HRS 8329.5 LDG 6657		A/R			Complete
MOC : COMPLIED WITH										
SB PW500-72-30266 R1 E2	REPLACEMENT/MODIFICATION OF IGNITION EXCITER	ICT		CATEGORY 7	MTH 10-Oct-2018 HRS 8362.7 LDG 6690		A/R			Complete
MOC : COMPLIED WITH - SB PW500-72-30266 REV. 1; REPLACEMENT OF IGNITION EXCITER. IS C/W DUE TO PART NUMBER INSTALLED.										
SB PW500-72-30271 E1	MODIFICATION/REPLACEMENT OF FAN ROTOR BALANCING ASSEMBLY	UNK		CATEGORY 6	MTH 31-Dec-2017 HRS 8329.5 LDG 6657		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30271 E2	MODIFICATION/REPLACEMENT OF FAN ROTOR BALANCING ASSEMBLY	UNK		CATEGORY 6	MTH 24-Dec-2017 HRS 8329.5 LDG 6657		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30273 E1	INTRODUCTION OF FUEL PRESSURE TUBE REPLACEMENT AND ATTENUATOR			CATEGORY 3	MTH 20-Aug-2004 HRS -1182.3 LDG -920		-			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30273 E2	INTRODUCTION OF FUEL PRESSURE TUBE REPLACEMENT AND ATTENUATOR			CATEGORY 3	MTH 20-Aug-2004 HRS -1179.6 LDG -909		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30277 R1 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL			CATEGORY 8	MTH		-			
MOC :										
SB PW500-72-30277 R1 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL			CATEGORY 8	MTH		-			
MOC :										
SB PW500-72-30279 R2 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL	ICT		CATEGORY 6	MTH 10-Oct-2018 HRS 8362.7 LDG 6690		-			
MOC : DEFERRED - SB PW500-72-30279 REV. 2; REPLACEMENT OF HYDROMECHANICAL FUEL CONTROL. DOES NOT APPLY DUE TO PART NUMBER INSTALLED.										
SB PW500-72-30279 R2 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL	ICT		CATEGORY 6	MTH 10-Oct-2018 HRS 8362.7 LDG 6690		-			N/A
MOC : NOT APPLICABLE - SB PW500-72-30279 REV. 2; REPLACEMENT OF HYDROMECHANICAL FUEL CONTROL. DOES NOT APPLY DUE TO PART NUMBER INSTALLED.										
SB PW500-72-30282 E1	REPLACEMENT OF FUEL NOZZLE PREFORMED PACKINGS	BTV		CATEGORY 6	MTH 09-Aug-2010 HRS 3464.9 LDG 2748		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30282 E2	REPLACEMENT OF FUEL NOZZLE PREFORMED PACKINGS	BTV		CATEGORY 6	MTH 09-Aug-2010 HRS 3467.6 LDG 2759		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30291 R1 E1	REPLACEMENT OF FIRST-STAGE-HIGH-COMPRESSOR-ROTOR	UNK		CATEGORY 6	MTH 31-Dec-2017 HRS 8329.5 LDG 6657		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30291 R1 E2	REPLACEMENT OF FIRST-STAGE-HIGH-COMPRESSOR-ROTOR	UNK		CATEGORY 6	MTH 24-Dec-2017 HRS 8329.5 LDG 6657		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30294 R2 (PART A) E1	INSPECT INSPECTION OF OIL TANK FILLER CAP USING FINGER	ICT		CATEGORY 3	MTH 10-Oct-2018 HRS 8362.7 LDG 6690		A/R			Complete
MOC : COMPLIED WITH - SB PW500-72-30294 REV. 2 PART A; INSPECTION OF OIL FILLER CAP. IS C/W DUE TO REV. 2 PART B WAS ACCOMPLISHED.										



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30294 R2 (PART A) E2	INSPECT INSPECTION OF OIL TANK FILLER CAP USING FINGER	ICT		CATEGORY 3	MTH 10-Oct-2018 HRS 8362.7 LDG 6690		A/R			Complete
MOC : COMPLIED WITH - SB PW500-72-30294 REV. 2 PART A; INSPECTION OF OIL FILLER CAP. IS C/W DUE TO REV. 2 PART B WAS ACCOMPLISHED.										
SB PW500-72-30294 R2 (PART B) E1	INSPECT INSPECTION OF OIL TANK FILLER CAP USING TORQUE WRENCH	ICT		CATEGORY 3	MTH 10-Oct-2018 HRS 8362.7 LDG 6690		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30294 R2 (PART B) E2	INSPECT INSPECTION OF OIL TANK FILLER CAP USING TORQUE WRENCH	ICT		CATEGORY 3	MTH 10-Oct-2018 HRS 8362.7 LDG 6690		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30294 R2 E1	INSPECTION OF OIL TANK FILLER CAP	ICT		CATEGORY 3	MTH 10-Oct-2018 HRS 8362.7 LDG 6690		A/R			Complete
MOC : COMPLIED WITH - SB PW500-72-30294 REV. 2; INSPECTION OF OIL FILLER CAP. IS C/W DUE TO REV. 2 PART B WAS ACCOMPLISHED.										
SB PW500-72-30294 R2 E2	INSPECTION OF OIL TANK FILLER CAP	ICT		CATEGORY 3	MTH 10-Oct-2018 HRS 8362.7 LDG 6690		A/R			Complete
MOC : COMPLIED WITH - SB PW500-72-30294 REV. 2; INSPECTION OF OIL FILLER CAP. IS C/W DUE TO REV. 2 PART B WAS ACCOMPLISHED.										
SB PW500-72-30297 R1 E1	REPLACEMENT OF NO. 4 BEARING CARBON SEAL			CATEGORY 10	MTH		-			Complete
MOC :										
SB PW500-72-30297 R1 E2	REPLACEMENT OF NO. 4 BEARING CARBON SEAL			CATEGORY 10	MTH		-			Complete
MOC :										
SB PW500-72-30300 R3 E1	REPLACEMENT OF OIL PUMP PLAIN SEAL	UNK		CATEGORY 6	MTH 31-Dec-2017 HRS 8329.5 LDG 6657		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30300 R3 E2	REPLACEMENT OF OIL PUMP PLAIN SEAL			CATEGORY 6	MTH		-			Complete
MOC :										
SB PW500-72-30301 R1 E1	REPLACEMENT OF NO. 4 BEARING CARBON SEAL			CATEGORY 10	MTH		-			Complete
MOC :										
SB PW500-72-30301 R1 E2	REPLACEMENT OF NO. 4 BEARING CARBON SEAL			CATEGORY 10	MTH		-			Complete
MOC :										
SB PW500-72-30302 R2 E1	REPLACEMENT OF IGNITION IGNITERS AND CABLES				MTH		-			Complete
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30302 R2 E2	REPLACEMENT OF IGNITION IGNITERS AND CABLES		MTH			-			
MOC :									
SB PW500-72-30305 R01 E1	REPLACEMENT/MODIFICATION OF TURBINE CASE ASSEMBLY		CATEGORY 7			-			
MOC :									
SB PW500-72-30305 R01 E2	REPLACEMENT/MODIFICATION OF TURBINE CASE ASSEMBLY		CATEGORY 7			-			
MOC :									
SB PW500-72-30306 R3 E1	NEW TRANSFER TUBE WITH HEATSHIELD		CATEGORY 5	MTH 01-Mar-2007 HRS 917.4 LDG 705		-			Complete
MOC : COMPLIED WITH									
SB PW500-72-30306 R3 E2	NEW TRANSFER TUBE WITH HEATSHIELD		CATEGORY 5	MTH 01-Mar-2007 HRS 920.6 LDG 716		-			Complete
MOC : COMPLIED WITH									
SB PW500-72-30308 E1	REPLACEMENT OF COMPRESSOR RETAINING NUT	UNK	CATEGORY 6	MTH 31-Dec-2017 HRS 8329.5 LDG 6657		-			Complete
MOC : COMPLIED WITH									
SB PW500-72-30308 E2	REPLACEMENT OF COMPRESSOR RETAINING NUT	UNK	CATEGORY 6	MTH 24-Dec-2017 HRS 8329.5 LDG 6657		-			Complete
MOC : COMPLIED WITH									
SB PW500-72-30309 R4 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL		CATEGORY 8			-			
MOC :									
SB PW500-72-30309 R4 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL		CATEGORY 8			-			
MOC :									
SB PW500-72-30315 E1	REPLACEMENT OF VANE RINGS ASSEMBLY COMPRESSOR-INLET	BTV	CATEGORY 7	MTH 09-Aug-2010 HRS 3464.9 LDG 2748		-			Complete
MOC : COMPLIED WITH									
SB PW500-72-30315 E2	REPLACEMENT OF VANE RINGS ASSEMBLY COMPRESSOR-INLET	BTV	CATEGORY 7	MTH 09-Aug-2010 HRS 3467.6 LDG 2759		-			Complete
MOC : COMPLIED WITH									
SB PW500-72-30316 R1 E1	REPLACEMENT OF TRANSFER TUBE ASSEMBLY		CATEGORY 5	MTH 01-Mar-2007 HRS 917.4 LDG 705		-			Complete
MOC : COMPLIED WITH									



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30316 R1 E2	REPLACEMENT OF TRANSFER TUBE ASSEMBLY			CATEGORY 5	MTH 01-Mar-2007 HRS 920.6 LDG 716		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30318 R1 E2	REPLACEMENT OF COMBUSTION CHAMBER LINER	UNK		CATEGORY 7	MTH 24-Dec-2017 HRS 8329.5 LDG 6657		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30325 R03 E1	REPLACEMENT OF OIL-PUMP PLAIN SEAL	UNK		CATEGORY 6	MTH 31-Dec-2017 HRS 8329.5 LDG 6657		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30325 R03 E2	REPLACEMENT OF OIL-PUMP PLAIN SEAL	UNK		CATEGORY 6	MTH 24-Dec-2017 HRS 8329.5 LDG 6657		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30328 E1	FIELD REPLACEMENT OF SPARE FAN ROTOR BALANCING ASSEMBLY			CATEGORY 7			-			
MOC :										
SB PW500-72-30328 E2	FIELD REPLACEMENT OF SPARE FAN ROTOR BALANCING ASSEMBLY			CATEGORY 7			-			
MOC :										
SB PW500-72-30332 R03 E1	REPLACEMENT OF ACCESSORY GEARBOX DRIVE SHAFT ANNULAR BALL BEARING			CATEGORY 6			-			
MOC :										
SB PW500-72-30332 R03 E2	REPLACEMENT OF ACCESSORY GEARBOX DRIVE SHAFT ANNULAR BALL BEARING			CATEGORY 6			-			
MOC :										
SB PW500-72-30332 R04 E1	REPLACEMENT OF ACCESSORY GEARBOX DRIVE-SHAFT ANNULAR BALL-BEARING			CATEGORY 6			-			
MOC :										
SB PW500-72-30332 R04 E2	REPLACEMENT OF ACCESSORY GEARBOX DRIVE-SHAFT ANNULAR BALL-BEARING			CATEGORY 6			-			
MOC :										
SB PW500-72-30332 R1 E1	REPLACEMENT OF ACCESSORY GEARBOX DRIVE SHAFT ANNULAR BALL BEARING	BTV		CATEGORY 6	MTH 09-Aug-2010 HRS 3464.9 LDG 2748		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30332 R1 E2	REPLACEMENT OF ACCESSORY GEARBOX DRIVE SHAFT ANNULAR BALL BEARING	BTV		CATEGORY 6	MTH 09-Aug-2010 HRS 3467.6 LDG 2759		-			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30335 R1 E1	BORESCOPE INSPECTION OF GAS-GENERATOR-CASE TO INTERMEDIATE-CASE RETAINING-BOLTS			CATEGORY 3	MTH		-			
	MOC :									
SB PW500-72-30335 R1 E2	BORESCOPE INSPECTION OF GAS-GENERATOR-CASE TO INTERMEDIATE-CASE RETAINING-BOLTS			CATEGORY 3	MTH		-			
	MOC :									
SB PW500-72-30336 R1 E1	REPLACEMENT / MODIFICATION OF HYDROMECHANICAL FUEL CONTROL			CATEGORY 7			-			
	MOC :									
SB PW500-72-30336 R1 E2	REPLACEMENT / MODIFICATION OF HYDROMECHANICAL FUEL CONTROL			CATEGORY 7			-			
	MOC :									
SB PW500-72-30338 E1	REPLACEMENT OF T1.4 AND T2.5 TEMPERATURE SENSORS	UNK		CATEGORY 7	MTH	31-Dec-2017	-			Complete
					HRS	8329.5				
					LDG	6657				
	MOC : COMPLIED WITH									
SB PW500-72-30340 R2 E1	REPLACEMENT OF IGNITERS AND IGNITION CABLES			CATEGORY 7	MTH	17-Sep-2009	-			Complete
					HRS	2909.9				
					LDG	2295				
	MOC : COMPLIED WITH									
SB PW500-72-30340 R2 E2	REPLACEMENT OF IGNITERS AND IGNITION CABLES			CATEGORY 7	MTH	17-Sep-2009	-			Complete
					HRS	2912.6				
					LDG	2306				
	MOC : COMPLIED WITH									
SB PW500-72-30343 R6 E1	REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR-BLEED-VALVE			CATEGORY 7			-			
	MOC :									
SB PW500-72-30343 R6 E2	REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR-BLEED-VALVE			CATEGORY 7			-			
	MOC :									
SB PW500-72-30344 R1 E1	REPLACEMENT OF VARIOUS CADMIUM PLATED PARTS			CATEGORY 7			-			
	MOC :									
SB PW500-72-30344 R1 E2	REPLACEMENT OF VARIOUS CADMIUM PLATED PARTS			CATEGORY 7			-			
	MOC :									
SB PW500-72-30349 R1 E1	TURBOFAN ENGINE OIL FILLER CAP - REPLACEMENT OF						-			
	MOC :									
SB PW500-72-30349 R1 E2	TURBOFAN ENGINE OIL FILLER CAP - REPLACEMENT OF						-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30353 R1 E1	REPLACEMENT OF INTERSHAFT CARBON SEALS	BTV		CATEGORY 6	MTH 09-Aug-2010 HRS 3464.9 LDG 2748		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30353 R1 E2	REPLACEMENT OF INTERSHAFT CARBON SEALS	BTV		CATEGORY 6	MTH 09-Aug-2010 HRS 3467.6 LDG 2759		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30356 R2 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL WITH ADDITIONAL PROTECTIVE SCREENS			CATEGORY 6			-			
MOC :										
SB PW500-72-30356 R2 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL WITH ADDITIONAL PROTECTIVE SCREENS			CATEGORY 6			-			
MOC :										
SB PW500-72-30358 R1 E1	P3 AIR INERTIAL SEPARATOR WITH NO SILVER PLATING	UNK		CATEGORY 7	MTH 31-Dec-2017 HRS 8329.5 LDG 6657		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30359 R1 E1	REPLACEMENT OF AIR/OIL SEPARATOR	BTV		CATEGORY 7	MTH 09-Aug-2010 HRS 3464.9 LDG 2748		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30359 R1 E2	REPLACEMENT OF AIR/OIL SEPARATOR	BTV		CATEGORY 7	MTH 09-Aug-2010 HRS 3467.6 LDG 2759		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30364 R1 E1	REPLACEMENT ACCESSORY GEARBOX PLAIN SEALS			CATEGORY 7				A/R		
MOC :										
SB PW500-72-30364 R1 E2	REPLACEMENT ACCESSORY GEARBOX PLAIN SEALS			CATEGORY 7				A/R		
MOC :										
SB PW500-72-30374 E1	INSPECTION TURBINE EXHAUST CASE OUTER-WALL THICKNESS	UNK		CATEGORY 5	MTH 31-Dec-2017 HRS 8329.5 LDG 6657		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30374 E2	INSPECTION TURBINE EXHAUST CASE OUTER-WALL THICKNESS	UNK		CATEGORY 5	MTH 24-Dec-2017 HRS 8329.5 LDG 6657		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30376 R2 E1	REPLACEMENT/MODIFICATION OF OIL PUMP ASSEMBLY AND OIL-PUMP-DRIVE SPUR GEAR			CATEGORY 7			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30376 R2 E2	REPLACEMENT/MODIFICATION OF OIL PUMP ASSEMBLY AND OIL-PUMP-DRIVE SPUR GEAR		CATEGORY 7			-			
MOC :									
SB PW500-72-30382 R1 E1	TURBINE EXHAUST CONE, INNER BY-PASS DUCT ASSEMBLY, FUEL MANIFOLD, FUEL SHUT-OFF CABLE GROMMETS AND COVER PLATE FAIRING - REPLACEMENT /MODIFICATION OF		CATEGORY 3	MTH 17-Sep-2009 HRS 2909.9 LDG 2295		A/R			Complete
MOC : COMPLIED WITH									
SB PW500-72-30382 R1 E2	TURBINE EXHAUST CONE, INNER BY-PASS DUCT ASSEMBLY, FUEL MANIFOLD, FUEL SHUT-OFF CABLE GROMMETS AND COVER PLATE FAIRING - REPLACEMENT /MODIFICATION OF		CATEGORY 3	MTH 17-Sep-2009 HRS 2912.6 LDG 2306		A/R			Complete
MOC : COMPLIED WITH									
SB PW500-72-30386 R1 E1	FLIGHT COUNT FACTOR CRITICAL ROTATING COMPONENTS		CATEGORY 6			A/R			
MOC :									
SB PW500-72-30386 R1 E2	FLIGHT COUNT FACTOR CRITICAL ROTATING COMPONENTS		CATEGORY 6			A/R			
MOC :									
SB PW500-72-30387 E1	REPLACEMENT/MODIFICATION REAR BY-PASS DUCT ASSEMBLY	BTV	CATEGORY 6	MTH 09-Aug-2010 HRS 3464.9 LDG 2748		-			Complete
MOC : COMPLIED WITH									
SB PW500-72-30387 E2	REPLACEMENT/MODIFICATION REAR BY-PASS DUCT ASSEMBLY	BTV	CATEGORY 6	MTH 09-Aug-2010 HRS 3467.6 LDG 2759		-			Complete
MOC : COMPLIED WITH									
SB PW500-72-30389 E1	REPLACEMENT OF CARBON SEAL, NO. 4 BEARING	BTV	CATEGORY 7	MTH 09-Aug-2010 HRS 3464.9 LDG 2748		-			Complete
MOC : COMPLIED WITH									
SB PW500-72-30389 E2	REPLACEMENT OF CARBON SEAL, NO. 4 BEARING	BTV	CATEGORY 7	MTH 09-Aug-2010 HRS 3467.6 LDG 2759		-			Complete
MOC : COMPLIED WITH									
SB PW500-72-30390 R5 E1	CAVITATION REPAIR HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY SB PW500-72-30409 R8, DATED JUNE 20, 2012)		CATEGORY 10			-			
MOC :									
SB PW500-72-30390 R5 E2	CAVITATION REPAIR HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY SB PW500-72-30409 R8, DATED JUNE 20, 2012)		CATEGORY 10			-			
MOC :									
SB PW500-72-30396 R1 E1	REPLACEMENT OF BOLTS		CATEGORY 7			-			
MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30396 R1 E2	REPLACEMENT OF BOLTS			CATEGORY 7			-			
MOC :										
SB PW500-72-30400 R4 E1	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER	UNK		CATEGORY 6	MTH 31-Dec-2017 HRS 8329.5 LDG 6657		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30400 R4 E2	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER	UNK		CATEGORY 6	MTH 24-Dec-2017 HRS 8329.5 LDG 6657		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30403 R02 E1	REPLACEMENT OF TEE HEAD BOLT/1ST.- 2ND. STAGE HP COMPRESSOR ASSEMBLIES	UNK		CATEGORY 6	MTH 31-Dec-2017 HRS 8329.5 LDG 6657		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30403 R02 E2	REPLACEMENT OF TEE HEAD BOLT/1ST.- 2ND. STAGE HP COMPRESSOR ASSEMBLIES	UNK		CATEGORY 6	MTH 24-Dec-2017 HRS 8329.5 LDG 6657		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30403 R04 E1	REPLACEMENT OF TEE HEAD BOLT/1ST.- 2ND. STAGE HP COMPRESSOR ASSEMBLIES			CATEGORY 6			-			
MOC :										
SB PW500-72-30403 R04 E2	REPLACEMENT OF TEE HEAD BOLT/1ST.- 2ND. STAGE HP COMPRESSOR ASSEMBLIES			CATEGORY 6			-			
MOC :										
SB PW500-72-30404 R3 E1	REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR BLEED-VALVE			CATEGORY 7			A/R			
MOC :										
SB PW500-72-30404 R3 E2	REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR BLEED-VALVE			CATEGORY 7			A/R			
MOC :										
SB PW500-72-30405 R3 E1	REPLACEMENT OF - FUEL NOZZLE MANIFOLD	UNK		CATEGORY 6	MTH 31-Dec-2017 HRS 8329.5 LDG 6657		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30405 R3 E2	REPLACEMENT OF - FUEL NOZZLE MANIFOLD	UNK		CATEGORY 6	MTH 24-Dec-2017 HRS 8329.5 LDG 6657		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30408 E1	REPLACEMENT OF ENGINE GASKET	UNK		CATEGORY 6	MTH 31-Dec-2017 HRS 8329.5 LDG 6657		A/R			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30408 E2	REPLACEMENT OF ENGINE GASKET	UNK		CATEGORY 6	MTH 24-Dec-2017 HRS 8329.5 LDG 6657		A/R			Complete
MOC : COMPLIED WITH										
SB PW500-72-30409 R5 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT	MKE		CATEGORY 3	MTH 05-Dec-2010 HRS 3710.7 LDG 2941		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH PRATT & WHITNEY SERVICE BULLETIN PW500-72-30409R5 REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT DATED 09/28/2010 BY REPLACEMENT OF UNIT										
SB PW500-72-30409 E1	REPLACEMENT/MODIFICATION OF HYDROMACHANICAL FUEL CONTROL UNIT			CATEGORY 3	MTH 22-Jun-2011 HRS 4120.8 LDG 3241		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30414 E1	REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR BLEED-VALVE			CATEGORY 10			A/R			
MOC :										
SB PW500-72-30414 E2	REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR BLEED-VALVE			CATEGORY 10			A/R			
MOC :										
SB PW500-72-30415 R3 E1	REPLACEMENT OF NO. 4 ROLLER BEARING	UNK		CATEGORY 6	MTH 31-Dec-2017 HRS 8329.5 LDG 6657		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30415 R3 E2	REPLACEMENT OF NO. 4 ROLLER BEARING	UNK		CATEGORY 6	MTH 24-Dec-2017 HRS 8329.5 LDG 6657		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30420 R03 E1	REPLACEMENT/MODIFICATION OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE (SUPERSEDED BY PW500-72-30420 R04)	ICT		CATEGORY 3	MTH 10-Oct-2018 HRS 8362.7 LDG 6690		-			Complete
MOC : COMPLIED WITH - SB PW500-72-30420 REV. 3; REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE SERVO VALVE. IS C/W DUE TO ORIGINAL ISSUE WAS C/W ON 8-9-10.										
SB PW500-72-30420 R03 E2	REPLACEMENT/MODIFICATION OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE (SUPERSEDED BY PW500-72-30420 R04)	ICT		CATEGORY 3	MTH 10-Oct-2018 HRS 8362.7 LDG 6690		-			Complete
MOC : COMPLIED WITH - SB PW500-72-30420 REV. 3; REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE SERVO VALVE. IS C/W DUE TO ORIGINAL ISSUE WAS C/W ON 8-9-10.										
SB PW500-72-30423 R1 E1	REPLACEMENT/MODIFICATION INTERMEDIATE CASE ASSEMBLY	UNK		CATEGORY 6	MTH 31-Dec-2017 HRS 8329.5 LDG 6657		-			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30423 R1 E2	REPLACEMENT/MODIFICATION INTERMEDIATE CASE ASSEMBLY	UNK	CATEGORY 6	MTH 24-Dec-2017 HRS 8329.5 LDG 6657		-			Complete
MOC : COMPLIED WITH									
SB PW500-72-30428 R05 E1	REPLACEMENT OF FUEL MANIFOLD SYSTEM INTERFACE	UNK	CATEGORY 6	MTH 31-Dec-2017 HRS 8329.5 LDG 6657		-			Complete
MOC : COMPLIED WITH									
SB PW500-72-30428 R05 E2	REPLACEMENT OF FUEL MANIFOLD SYSTEM INTERFACE	UNK	CATEGORY 6	MTH 24-Dec-2017 HRS 8329.5 LDG 6657		-			Complete
MOC : COMPLIED WITH									
SB PW500-72-30428 R06 E1	REPLACEMENT OF FUEL MANIFOLD SYSTEM INTERFACE		CATEGORY 6			-			
MOC :									
SB PW500-72-30428 R06 E2	REPLACEMENT OF FUEL MANIFOLD SYSTEM INTERFACE		CATEGORY 6			-			
MOC :									
SB PW500-72-30430 R1 E1	REPLACEMENT OF HIGH PRESSURE TURBINE BLADE	UNK	CATEGORY 7	MTH 31-Dec-2017 HRS 8329.5 LDG 6657		A/R			Complete
MOC : COMPLIED WITH									
SB PW500-72-30430 R1 E2	REPLACEMENT OF HIGH PRESSURE TURBINE BLADE		CATEGORY 7	MTH 30-Sep-2016 HRS 7714.2 LDG 6181		A/R			Complete
MOC : COMPLIED WITH									
SB PW500-72-30431 E1	CARBON SEAL NO. 4 BEARING - REPLACEMENT OF		CATEGORY 7			A/R			
MOC :									
SB PW500-72-30431 E2	CARBON SEAL NO. 4 BEARING - REPLACEMENT OF		CATEGORY 7			A/R			
MOC :									
SB PW500-72-30432 R1 E1	PLAIN SEAL ACCESSORY GEARBOX - REPLACEMENT OF		CATEGORY 7			A/R			
MOC :									
SB PW500-72-30432 R1 E2	PLAIN SEAL ACCESSORY GEARBOX - REPLACEMENT OF		CATEGORY 7			A/R			
MOC :									
SB PW500-72-30442 R04 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT	ICT	CATEGORY 7	MTH 10-Oct-2018 HRS 8362.7 LDG 6690		-			Complete
MOC : COMPLIED WITH - SB PW500-72-30442 REV. 4; REPLACEMENT OF HYDROMECHANICAL FUEL CONTROL UNIT. IS C/W DUE TO REV. 3 WAS ACCOMPLISHED.									



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30442 R04 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 7			-			
MOC :										
SB PW500-72-30444 R1 E1	REPLACEMENT OF COMBUSTION CHAMBER LINER			CATEGORY 7			A/R			
MOC :										
SB PW500-72-30444 R1 E2	REPLACEMENT OF COMBUSTION CHAMBER LINER	UNK		CATEGORY 7	MTH 24-Dec-2017 HRS 8329.5 LDG 6657		A/R			Complete
MOC : COMPLIED WITH										
SB PW500-72-30446 R2 E1	REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT BALANCING ASSEMBLY			CATEGORY 7			-			
MOC :										
SB PW500-72-30446 R2 E2	REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT BALANCING ASSEMBLY			CATEGORY 7			-			
MOC :										
SB PW500-72-30447 R1 E1	NEW COATING MODIFICATION OF GAS GENERATOR CASE	UNK		CATEGORY 6	MTH 31-Dec-2017 HRS 8329.5 LDG 6657		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30447 R1 E2	NEW COATING MODIFICATION OF GAS GENERATOR CASE	UNK		CATEGORY 6	MTH 24-Dec-2017 HRS 8329.5 LDG 6657		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30453 R03 E1	REPLACEMENT OF NO. 4 CARBON SEAL			CATEGORY 7			-			
MOC :										
SB PW500-72-30453 R03 E2	REPLACEMENT OF NO. 4 CARBON SEAL			CATEGORY 7			-			
MOC :										
SB PW500-72-30455 R05 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 7			-			
MOC :										
SB PW500-72-30455 R05 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 7			-			
MOC :										
SB PW500-72-30455 R4 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT	UNK		CATEGORY 7	MTH 31-Dec-2017 HRS 8329.5 LDG 6657		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30455 R4 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 7			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30459 R1 E1	REPLACEMENT OF NUT OPTION (IC)	UNK		CATEGORY 6	MTH 31-Dec-2017 HRS 8329.5 LDG 6657		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30459 R1 E2	REPLACEMENT OF NUT OPTION (IC)	UNK		CATEGORY 6	MTH 24-Dec-2017 HRS 8329.5 LDG 6657		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30461 E1	CONVERSION OF PW535A BUILD SPECIFICATION 1155 TO 909	UNK		CATEGORY 8	MTH 31-Dec-2017 HRS 8329.5 LDG 6657		-	CONVERSION OF PW535B BUILT SPECIFICATION 1262 TO 1208		Complete
MOC : COMPLIED WITH										
SB PW500-72-30461 E2	CONVERSION OF PW535A BUILD SPECIFICATION 1155 TO 909	UNK		CATEGORY 8	MTH 24-Dec-2017 HRS 8329.5 LDG 6657		-	CONVERSION OF PW535B BUILT SPECIFICATION 1262 TO 1208		Complete
MOC : COMPLIED WITH										
SB PW500-72-30463 R2 E1	REPLACEMENT OF ACCESSORY DRIVE LIP SEAL			CATEGORY 7			-			
MOC :										
SB PW500-72-30463 R2 E2	REPLACEMENT OF ACCESSORY DRIVE LIP SEAL			CATEGORY 7			-			
MOC :										
SB PW500-72-30465 R2 E1	REPLACEMENT OF FUEL MANIFOLD TUBES	UNK		CATEGORY 7	MTH 31-Dec-2017 HRS 8329.5 LDG 6657		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30465 R2 E2	REPLACEMENT OF FUEL MANIFOLD TUBES	UNK		CATEGORY 7	MTH 24-Dec-2017 HRS 8329.5 LDG 6657		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30472 R02 E1	REPLACEMENT OF N1 AND N2 SPEED SENSORS			CATEGORY 7			-			
MOC :										
SB PW500-72-30472 R02 E2	REPLACEMENT OF N1 AND N2 SPEED SENSORS			CATEGORY 7			-			
MOC :										
SB PW500-72-30472 R1 E1	REPLACEMENT OF - N1 AND N2 SPEED SENSORS			CATEGORY 7			-			
MOC :										
SB PW500-72-30472 R1 E2	REPLACEMENT OF - N1 AND N2 SPEED SENSORS			CATEGORY 7			-			
MOC :										
SB PW500-72-30475 R3 PART A E1	ACCOMPLISH REMOVE AND INSTALL FUEL CONTROL DRIVE GEARSHAFT			CATEGORY 7			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30475 R3 PART A E2	ACCOMPLISH REMOVE AND INSTALL FUEL CONTROL DRIVE GEARSHAFT			CATEGORY 7			-			
MOC :										
SB PW500-72-30475 R3 PART B E1	ACCOMPLISH REMOVE AND INSTALL THE ACCESSORY DRIVE GEARSHAFT			CATEGORY 7			-			
MOC :										
SB PW500-72-30475 R3 PART B E2	ACCOMPLISH REMOVE AND INSTALL THE ACCESSORY DRIVE GEARSHAFT			CATEGORY 7			-			
MOC :										
SB PW500-72-30475 R3 E1	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY			CATEGORY 7			-			
MOC :										
SB PW500-72-30475 R3 E2	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY			CATEGORY 7			-			
MOC :										
SB PW500-72-30482 R3 E1	INSPECTION OF COMBUSTION CHAMBER LINER COOLING RING SEGMENTS SELF-LOCKING NUT (SUPERSEDED BY SB PW500-72-30492 R2)			CATEGORY 10			-			
MOC :										
SB PW500-72-30482 R3 E2	INSPECTION OF COMBUSTION CHAMBER LINER COOLING RING SEGMENTS SELF-LOCKING NUT (SUPERSEDED BY SB PW500-72-30492 R2)			CATEGORY 10			-			
MOC :										
SB PW500-72-30483 R3 E1	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY (SUPERSEDED BY SB PW500-72-30492 R2)			CATEGORY 10			-			
MOC :										
SB PW500-72-30483 R3 E2	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY (SUPERSEDED BY SB PW500-72-30492 R2)	UNK		CATEGORY 10	MTH 24-Dec-2017 HRS 8329.5 LDG 6657		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30485 R02 E1	REPLACEMENT OF REAR OUTER BY-PASS DUCT HARDWARE			CATEGORY 7			-			
MOC :										
SB PW500-72-30485 R02 E2	REPLACEMENT OF REAR OUTER BY-PASS DUCT HARDWARE			CATEGORY 7			-			
MOC :										
SB PW500-72-30487 R3 E1	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE LIP SEAL (SUPERSEDED BY SB PW500-72-30502)						-			
MOC :										
SB PW500-72-30487 R3 E2	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE LIP SEAL (SUPERSEDED BY SB PW500-72-30502)						-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30489 E1	INSPECTION/REPLACEMENT OF TURBINE EXHAUST CASE OIL PRESSURE TUBE BRACKET CONFIGURATION	UNK		CATEGORY 6	MTH 31-Dec-2017 HRS 8329.5 LDG 6657		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30489 E2	INSPECTION/REPLACEMENT OF TURBINE EXHAUST CASE OIL PRESSURE TUBE BRACKET CONFIGURATION	UNK		CATEGORY 6	MTH 24-Dec-2017 HRS 8329.5 LDG 6657		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30491 R2 E1	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY			CATEGORY 7			-			
MOC :										
SB PW500-72-30491 R2 E2	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY	UNK		CATEGORY 7	MTH 24-Dec-2017 HRS 8329.5 LDG 6657		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30492 R04 E1	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER			CATEGORY 6			-			
MOC :										
SB PW500-72-30492 R04 E2	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER	UNK		CATEGORY 6	MTH 24-Dec-2017 HRS 8329.5 LDG 6657		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30493 E1	REPLACEMENT OF TEMPERATURE SENSORS	UNK		CATEGORY 7	MTH 31-Dec-2017 HRS 8329.5 LDG 6657		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30493 E2	REPLACEMENT OF TEMPERATURE SENSORS			CATEGORY 7			-			
MOC :										
SB PW500-72-30495 R01 E1	MODIFICATION OF ACCESSORY GEARBOX COVER BOLT TORQUING PROCEDURE (SUPERSEDED BY PW500-72-30498)			CATEGORY 10			-			
MOC :										
SB PW500-72-30495 R01 E2	MODIFICATION OF ACCESSORY GEARBOX COVER BOLT TORQUING PROCEDURE (SUPERSEDED BY PW500-72-30498)			CATEGORY 10			-			
MOC :										
SB PW500-72-30498 R03 E1	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY			CATEGORY 7			-			
MOC :										
SB PW500-72-30498 R03 E2	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY			CATEGORY 7			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30500 E1	REPLACEMENT OF PREFORMED PACKING			CATEGORY 7			-			
MOC :										
SB PW500-72-30500 E2	REPLACEMENT OF PREFORMED PACKING			CATEGORY 7			-			
MOC :										
SB PW500-72-30501 E1	REPLACEMENT OF SHIPPING CAPS FOR SHIPPING CONTAINERS	UNK		CATEGORY 3	MTH 31-Dec-2017 HRS 8329.5 LDG 6657		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30501 E2	REPLACEMENT OF SHIPPING CAPS FOR SHIPPING CONTAINERS	UNK		CATEGORY 3	MTH 24-Dec-2017 HRS 8329.5 LDG 6657		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30502 R04 PART (A) E1	ACCOMPLISH REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL FUEL CONTROL GEARSHAFT SEAL			CATEGORY 7			-			
MOC :										
SB PW500-72-30502 R04 PART (A) E2	ACCOMPLISH REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL FUEL CONTROL GEARSHAFT SEAL			CATEGORY 7			-			
MOC :										
SB PW500-72-30502 R04 PART (B) E1	ACCOMPLISH REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL ACCESSORY GEARSHAFT SEAL			CATEGORY 7			-			
MOC :										
SB PW500-72-30502 R04 PART (B) E2	ACCOMPLISH REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL ACCESSORY GEARSHAFT SEAL			CATEGORY 7			-			
MOC :										
SB PW500-72-30502 R04 E1	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL			CATEGORY 7			-			
MOC :										
SB PW500-72-30502 R04 E2	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL			CATEGORY 7			-			
MOC :										
SB PW500-72-30504 R02 E1	REPLACEMENT OF FUEL/OIL HEAT EXCHANGER			CATEGORY 7			-			
MOC :										
SB PW500-72-30504 R02 E2	REPLACEMENT OF FUEL/OIL HEAT EXCHANGER			CATEGORY 7			-			
MOC :										
SB PW500-72-30504 R03 E1	REPLACEMENT OF FUEL/OIL HEAT EXCHANGER			CATEGORY 7			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30504 R03 E2	REPLACEMENT OF FUEL/OIL HEAT EXCHANGER		CATEGORY 7			-			
MOC :									
SB PW500-72-30505 R02 E1	REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS	UNK	CATEGORY 3	MTH 31-Dec-2017 HRS 8329.5 LDG 6657		-			Complete
MOC : COMPLIED WITH									
SB PW500-72-30505 R02 E2	REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS	UNK	CATEGORY 3	MTH 24-Dec-2017 HRS 8329.5 LDG 6657		-			Complete
MOC : COMPLIED WITH									
SB PW500-72-30506 R02 E1	REPLACEMENT OF FUEL MANIFOLD ADAPTERS	UNK	CATEGORY 7	MTH 31-Dec-2017 HRS 8329.5 LDG 6657		-			Complete
MOC : COMPLIED WITH									
SB PW500-72-30506 R02 E2	REPLACEMENT OF FUEL MANIFOLD ADAPTERS	UNK	CATEGORY 7	MTH 24-Dec-2017 HRS 8329.5 LDG 6657		-			Complete
MOC : COMPLIED WITH									
SB PW500-72-30511 R01 E1	RE-TORQUEING OF AGB COVER BOLTS OR NUTS	UNK	CATEGORY 6	MTH 31-Dec-2017 HRS 8329.5 LDG 6657		-			Complete
MOC : COMPLIED WITH									
SB PW500-72-30511 R01 E2	RE-TORQUEING OF AGB COVER BOLTS OR NUTS		CATEGORY 6			-			
MOC :									
SB PW500-72-30512 R02 E2	INSPECTION/ REPLACEMENT OF HYDROMECHANICAL FUEL CONTROL (SUPERSEDED BY PW500-72-30512 R03)	LUK	CATEGORY 3	MTH 09-Oct-2015 HRS 6928.1 LDG 5541		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH P&WC PW500-72-30512 R2, "TURBOFAN ENGINE HYDROMECHANICAL FUEL CONTROL - INSPECTION /REPLACEMENT OF" DATED APR 29/2015 IN ACCORDANCE WITH SERVICE BULLETIN INSTRUCTIONS.									
SB PW500-72-30512 R03 E1	INSPECTION/REPLACEMENT OF HYDROMECHANICAL FUEL CONTROL (SUPERSEDED BY PW500-72-30512 R04)	UNK	CATEGORY 3	MTH 31-Dec-2017 HRS 8329.5 LDG 6657		-			Complete
MOC : COMPLIED WITH									
SB PW500-72-30513 R01 E1	REPLACEMENT / MODIFICATION OF OIL LEVEL INDICATOR	ICT	CATEGORY 7	MTH 10-Oct-2018 HRS 8362.7 LDG 6690		-			N/A
MOC : NOT APPLICABLE - SB PW500-72-30513 REV. 1; REPLACEMENT OF OIL LEVEL INDICATOR. DOES NOT APPLY DUE TO ENGINE SERIAL NUMBER.									
SB PW500-72-30513 R01 E2	REPLACEMENT / MODIFICATION OF OIL LEVEL INDICATOR	ICT	CATEGORY 7	MTH 10-Oct-2018 HRS 8362.7 LDG 6690		-			N/A
MOC : NOT APPLICABLE - SB PW500-72-30513 REV. 1; REPLACEMENT OF OIL LEVEL INDICATOR. DOES NOT APPLY DUE TO ENGINE SERIAL NUMBER.									



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30514 R01 E2	REPLACEMENT / MODIFICATION OF INTERMEDIATE CASE ASSEMBLY			CATEGORY 7			-			
MOC :										
SB PW500-72-30514 R02 E1	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY			CATEGORY 7			-			
MOC :										
SB PW500-72-30514 R02 E2	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY			CATEGORY 7			-			
MOC :										
SB PW500-72-30514 E1	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30514 R01)	LUK		CATEGORY 7	MTH 09-Oct-2015 HRS 6925.4 LDG 5530		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH P&WC PW500-72-30514 INTERMEDIATE CASE ASSEMBLY - REPLACEMENT 1 MODIFICATION OF DATED MAR 03/2015, IN ACCORDANCE WITH SB INSTRUCTIONS										
SB PW500-72-30515 R01 E1	REPLACEMENT OF TURBINE SUPPORT CASE			CATEGORY 7			-			
MOC :										
SB PW500-72-30515 R01 E2	REPLACEMENT OF TURBINE SUPPORT CASE			CATEGORY 7			-			
MOC :										
SB PW500-72-30515 R02 E1	REPLACEMENT OF TURBINE SUPPORT CASE			CATEGORY 7			-			
MOC :										
SB PW500-72-30515 R02 E2	REPLACEMENT OF TURBINE SUPPORT CASE			CATEGORY 7			-			
MOC :										
SB PW500-72-30516 R02 E1	REPLACEMENT OF HP TURBINE SEAL RINGS			CATEGORY 7			-			
MOC :										
SB PW500-72-30516 R02 E2	REPLACEMENT OF HP TURBINE SEAL RINGS	UNK		CATEGORY 7	MTH 24-Dec-2017 HRS 8329.5 LDG 6657		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30517 R01 E1	DELETION OF IGNITER FLANGE GASKETS	UNK		CATEGORY 6	MTH 31-Dec-2017 HRS 8329.5 LDG 6657		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30517 R01 E2	DELETION OF IGNITER FLANGE GASKETS	UNK		CATEGORY 6	MTH 24-Dec-2017 HRS 8329.5 LDG 6657		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30519 R01 E1	INSPECTION OF IGNITION LEAD	LUK		CATEGORY 3	MTH 09-Oct-2015 HRS 6925.4 LDG 5530		-			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30519 R01 E2	INSPECTION OF IGNITION LEAD	KCMH		CATEGORY 3	MTH 17-Sep-2009 HRS 2912.6 LDG 2306		-			Complete
MOC : COMPLIED WITH - C/W SB 72-30340 LEAD REPLACEMENT										
SB PW500-72-30521 R01 E1	REPLACEMENT OF COMBUSTION CHAMBER LINER			CATEGORY 7			-			
MOC :										
SB PW500-72-30521 R01 E2	REPLACEMENT OF COMBUSTION CHAMBER LINER	UNK		CATEGORY 7	MTH 24-Dec-2017 HRS 8329.5 LDG 6657		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30522 E1	REPLACEMENT OF IGNITER CABLES (SUPERSEDED BY PW500-72-30522 R01)	LUK		SUPERSEDED	MTH 09-Oct-2015 HRS 6925.4 LDG 5530		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH P&WC PW500-72-30522," IGNITER CABLES - REPLACEMENT OF" DATED JU113/2015, IN ACCORDANCE WITH SERVICE BULLETIN INSTRUCTIONS.										
SB PW500-72-30522 E2	REPLACEMENT OF IGNITER CABLES (SUPERSEDED BY PW500-72-30522 R01)	LUK		SUPERSEDED	MTH 09-Oct-2015 HRS 6928.1 LDG 5541		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH P&WC PW500-72-30522," IGNITER CABLES - REPLACEMENT OF" DATED JU113/2015, IN ACCORDANCE WITH SERVICE BULLETIN INSTRUCTIONS.										
SB PW500-72-30523 R01 E1	REPLACEMENT OF ACCESSORY GEARBOX COVER GASKET			CATEGORY 7			-			
MOC :										
SB PW500-72-30523 R01 E2	REPLACEMENT OF ACCESSORY GEARBOX COVER GASKET			CATEGORY 7			-			
MOC :										
SB PW500-72-30527 E1	REPLACEMENT OF NO. 4 ROLLER BEARING			CATEGORY 9			-			
MOC :										
SB PW500-72-30527 E2	REPLACEMENT OF NO. 4 ROLLER BEARING			CATEGORY 9			-			
MOC :										
SB PW500-72-30529 R01 E1	REPLACEMENT OF IGNITER CABLES (SUPERSEDED BY PW500-72-30529 R02)	LUK		CATEGORY 3	MTH 20-Apr-2016 HRS 7322.6 LDG 5841		-			Complete
MOC : COMPLIED WITH - PW500-72-30529 REV 1 COMPLIANCE. INSTALLED A NEW UNIT LAW PRATT & WHITNEY 535A MM 74-10-01.										
SB PW500-72-30529 R01 E2	REPLACEMENT OF IGNITER CABLES (SUPERSEDED BY PW500-72-30529 R02)	LUK		CATEGORY 3	MTH 20-Apr-2016 HRS 7325.3 LDG 5852		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH PW500-72-30529 REV 1 DATED FEB. 15/2016. " TURBOFAN ENGINE IGNITOR CABLES - REPLACEMENT OF" IN ACCORDANCE WITH PW SB INSTRUCTIONS.										



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30532 E1	REPLACEMENT OF RETAINING RINGS			CATEGORY 9			-			
	MOC :									
SB PW500-72-30532 E2	REPLACEMENT OF RETAINING RINGS			CATEGORY 9			-			
	MOC :									
SB PW500-72-30533 R01 E1	REPLACEMENT OF P3 AIR SEPARATOR TUBE CLAMP			CATEGORY 6			-			
	MOC :									
SB PW500-72-30533 R01 E2	REPLACEMENT OF P3 AIR SEPARATOR TUBE CLAMP			CATEGORY 6			-			
	MOC :									
SB PW500-72-30533 E1	REPLACEMENT OF P3 AIR SEPARATOR TUBE CLAMP	UNK		CATEGORY 6	MTH 31-Dec-2017 HRS 8329.5 LDG 6657		-			Complete
	MOC :									
SB PW500-72-30533 E2	REPLACEMENT OF P3 AIR SEPARATOR TUBE CLAMP			CATEGORY 6			-			
	MOC :									
SB PW500-72-30535 R01 E1	REPLACEMENT OF ENGINE SHIPPING CONTAINER			CATEGORY 7			-			
	MOC :									
SB PW500-72-30535 R01 E2	REPLACEMENT OF ENGINE SHIPPING CONTAINER			CATEGORY 7			-			
	MOC :									
SB PW500-72-30541 R01 PART A E1	ACCOMPLISH FUEL CONTROL GEARSHAFT SEAL			CATEGORY 7			-			
	MOC :									
SB PW500-72-30541 R01 PART A E2	ACCOMPLISH FUEL CONTROL GEARSHAFT SEAL			CATEGORY 7			-			
	MOC :									
SB PW500-72-30541 R01 PART B E1	ACCOMPLISH ACCESSORY GEARSHAFT SEAL			CATEGORY 7			-			
	MOC :									
SB PW500-72-30541 R01 PART B E2	ACCOMPLISH ACCESSORY GEARSHAFT SEAL			CATEGORY 7			-			
	MOC :									
SB PW500-72-30541 R01 E1	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL			CATEGORY 7			-			
	MOC :									
SB PW500-72-30541 R01 E2	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL			CATEGORY 7			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30543 R01 E1	REPLACEMENT OF T1 THERMOCOUPLE HARNESS			CATEGORY 7						
	MOC :									
SB PW500-72-30543 R01 E2	REPLACEMENT OF T1 THERMOCOUPLE HARNESS			CATEGORY 7						
	MOC :									
SB PW500-72-30545 R01 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT				MTH 31-Dec-2017 HRS 8328.5 LDG 6648					
	MOC :									
SB PW500-72-30545 R01 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT				MTH 24-Dec-2017 HRS 8328.1					
	MOC :									
SB PW500-72-30545 R02 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 3						
	MOC :									
SB PW500-72-30545 R02 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 3						
	MOC :									
SB PW500-72-30545 R03 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 6						
	MOC :									
SB PW500-72-30545 R03 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 6						
	MOC :									
SB PW500-72-30545 R04 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 6						
	MOC :									
SB PW500-72-30545 R04 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 6						
	MOC :									
SB PW500-72-30545 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 3						
	MOC :									
SB PW500-72-30545 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 3						
	MOC :									
SB PW500-72-30548 R02 E1	REPLACEMENT/MODIFICATION OF ANTI-ICING VALVE			CATEGORY 7						
	MOC :									
SB PW500-72-30548 R02 E2	REPLACEMENT/MODIFICATION OF ANTI-ICING VALVE			CATEGORY 7						
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30553 E1	REPLACEMENT OF IC NUMBER INTERMEDIATE CASE			CATEGORY 9			-			
MOC :										
SB PW500-72-30553 E2	REPLACEMENT OF IC NUMBER INTERMEDIATE CASE			CATEGORY 9			-			
MOC :										
ASB PW500-72-A30257 R02 E1	INSPECTION OF HFC RATIO UNIT SETSCREW ADJUSTMENT			CATEGORY 3	MTH 28-Feb-2008 HRS 1870.7 LDG 1463		-			Complete
MOC : COMPLIED WITH										
ASB PW500-72-A30257 R02 E2	INSPECTION OF HFC RATIO UNIT SETSCREW ADJUSTMENT			CATEGORY 3	MTH 28-Feb-2008 HRS 1873.4 LDG 1474		-			Complete
MOC : COMPLIED WITH										
ASB PW500-72-A30314 R01 E1	INTRODUCTION OF NEW FUEL MANIFOLD			CATEGORY 10			-			
MOC :										
ASB PW500-72-A30314 R01 E2	INTRODUCTION OF NEW FUEL MANIFOLD			CATEGORY 10			-			
MOC :										
SL 560-73-08 73SL-08	ENGINE FUEL AND CONTROL - TRANSMITTAL OF P&WC ASB 30257 TURBOFAN ENGINE HFC UNIT RATIO SETSCREW ADJUSTMENT AND COMMERCIAL SUPPORT PROGRAM NOTIFICATION (CSPN) A03011			RECOMMENDED	MTH 29-Nov-2006 HRS 26 LDG 19		A/R			N/A
MOC : NOT APPLICABLE										
SL 560-76-02	ENGINE CONTROLS - TRANSMITTAL OF PRATT & WHITNEY CANADA SERVICE BULLETIN 30438 TURBOFAN ENGINE ELECTRONIC ENGINE CONTROL (EEC) - REPLACEMENT/MODIFICATIONS OF	ICT		RECOMMENDED	MTH 20-Sep-2017 HRS 8329.5 LDG 6657		A/R			N/A
MOC : NOT APPLICABLE - SL560-76-02; TRANSMITTAL OF PRATT & WHITNEY SB PW500-72-30438 ELECTRONIC ENGINE CONTROL REPLACEMENT. DOES NOT APPLY DUE TO AIRCRAFT SERIAL NUMBER.										
SL 560-77-01 77SL-01	P&W SIL PW500-018 *CF			INFORMATIONAL	MTH		-			
MOC :										
SL CIL-99-01 R03	MISCELLANEOUS - USE OF CORROSION INHIBITING COMPOUNDS			CANCELLED			-			
MOC :										
SL CIL-99-02 R01	MISCELLANEOUS - AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS			CANCELLED			-			
MOC :										
SL CIL-99-03 R02	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)			CANCELLED			-			
MOC :										
SL CIL-99-04 R01	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW			CANCELLED			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task # City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 1996-24-06	ICING COND ADDITION TO FM (SUPERSEDED BY 2006-22-05)	SUPERSEDED	MTH 03-Apr-2000		-			N/A
	MOC : NOT APPLICABLE - SUPERSEDED BY AD 2000-03-09							
FAA 1998-04-38 30AD-02	SEVERE ICING PROCEDURES ICT	MANDATORY	MTH 19-Oct-2006 HRS 17		-			N/A
	MOC : NOT APPLICABLE							
FAA 1998-25-10	APPLIANCE AD - AIRCRAFT BELTS, INC. (SUPERSEDED BY 1998-25-10 R01)	SUPERSEDED	MTH 19-Oct-2006 HRS 17.6 LDG 13		-			N/A
	MOC : NOT APPLICABLE							
FAA 1999-08-21	APPLIANCE AD - PURITAN-BENNETT AERO SYSTEM CO	MANDATORY	MTH 29-Nov-2006 HRS 26 LDG 19		-			N/A
	MOC : NOT APPLICABLE - AFFECTED PARTS NOT INSTALLED							
FAA 2000-03-09	ICING COND FM INFORMATION	MANDATORY	MTH 29-Nov-2006 HRS 26 LDG 19		-			N/A
	MOC : NOT APPLICABLE - AFFECTED PARTS NOT INSTALLED							
FAA 2006-04-10	THIS AD REQUIRES INSTALLING IDENTIFICATION SLEEVES ON THE WIRES FOR THE POSITIVE AND NEGATIVE STUDS OF THE ENGINE AND/ OR (APU) FIRE EXTINGUISHING BOTTLES, AS APPLICABLE, AND RECONNECTING THE WIRES TO THE CORRECT TERMINAL STUDS.	MANDATORY	DAYS 29-Nov-2006 HRS 26 LDG 19		-			N/A
	MOC : NOT APPLICABLE - AFFECTED PARTS NOT INSTALLED							
FAA 2006-06-03	PREVENT FUEL VAPOR IGNITION	MANDATORY	MTH 29-Nov-2006 HRS 26 LDG 19		-			N/A
	MOC : NOT APPLICABLE - AFFECTED PARTS NOT INSTALLED							
FAA 2006-16-18 34AD-16	APPLIANCE AD - SANDEL AVIONICS INCORPORATED MODEL ST3400 TERRAIN AWARENESS WARNING SYSTEM/RADIO MAGNETIC INDICATOR (TAWS/RMI)	MANDATORY	MTH 29-Nov-2006 HRS 26 LDG 19		A/R			N/A
	MOC : NOT APPLICABLE - AFFECTED PARTS NOT INSTALLED							
FAA 2006-19-04 PARA(F) 34AD-17	REVISE HONEYWELL RCZ-833J/K, -851J/K AND 854J COMMUNICATION (COM) UNITS, EQUIPPED WITH XS-852E/F MODE S TRANSPONDERS; AND HONEYWELL XS-856A/B AND -857A MODE S TRANSPONDERS AIRPLANE FLIGHT MANUAL (AFM)	MANDATORY	MTH 29-Nov-2006 HRS 26 LDG 19		A/R			N/A
	MOC : NOT APPLICABLE - AFFECTED PARTS NOT INSTALLED							
FAA 2006-19-04 PARA(G)	REPLACE HONEYWELL RCZ-833J/K, -851J/K AND 854J COMMUNICATION (COM) UNITS, EQUIPPED WITH XS-852E/F MODE S TRANSPONDERS; AND HONEYWELL XS-856A/B AND -857A MODE S TRANSPONDERS IDENTIFICATION PLATE	MANDATORY	MTH 29-Nov-2006 HRS 26 LDG 19		A/R			N/A
	MOC : NOT APPLICABLE - AFFECTED PARTS NOT INSTALLED							



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2006-19-04	APPLIANCE AD - HONEYWELL RCZ-833J/K, -851J/K AND 854J COMMUNICATION (COM) UNITS, EQUIPPED WITH XS-852E/F MODE S TRANSPONDERS; AND HONEYWELL XS-856A/B AND -857A MODE S TRANSPONDERS		MANDATORY	MTH 29-Nov-2006 HRS 26 LDG 19		A/R			N/A
MOC : NOT APPLICABLE - AFFECTED PARTS NOT INSTALLED									
FAA 1995-25-10	OUTFLOW AND SAFETY VALUES		MANDATORY	MTH 29-Nov-2006 HRS 26 LDG 19		-			N/A
MOC : NOT APPLICABLE - AFFECTED PARTS NOT INSTALLED									
FAA 2013-09-11 PARA (G)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM INSPECTION FOR PART NUMBER (P/N)	LUK	MANDATORY	DAYS 12-Jun-2014 HRS 5921 LDG 4721		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH AIRWORTHINESS DIRECTIVE 2013-09-11, "A/C COMPRESSOR MOTOR BRUSHES REPLACEMENT" IN ACCORDANCE WITH AD INSTRUCTIONS DATED 07/05/2013.									
FAA 2013-09-11 PARA (H)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM INSPECTION A/C COMPRESSOR HOUR METER AND MAINTENANCE RECORDS	LUK	MANDATORY	DAYS 12-Jun-2014 HRS 5921 LDG 4721		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH AIRWORTHINESS DIRECTIVE 2013-09-11, "A/C COMPRESSOR MOTOR BRUSHES REPLACEMENT" IN ACCORDANCE WITH AD INSTRUCTIONS DATED 07/05/2013.									
FAA 2013-09-11 PARA (I) & (J)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM REPLACEMENT OF A/C COMPRESSOR MOTOR BRUSHES AND RELATED MAINTENANCE MANUAL INFORMATION	KCMH	MANDATORY	MTH 21-Jul-2017 HRS 8327 LDG 6656 ACH 3111		500		3611	Complete 500
MOC : COMPLIED WITH									
FAA 2013-09-11 PARA (K)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM DEACTIVATION OF A/C SYSTEM		MANDATORY			A/R			
MOC :									
FAA 2013-09-11 PARA (L)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM REACTIVATION OF A/C SYSTEM		MANDATORY			A/R			
MOC :									
FAA 2013-09-11 PARA (M)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM PARTS RETURN AND REPORTING REQUIREMENTS		MANDATORY	DAYS		30			
MOC :									
FAA 2013-09-11	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM		MANDATORY	MTH 29-Jun-2016 HRS 7559.3 LDG 6026		-			Complete
MOC : COMPLIED WITH									
FAA 2015-17-12 PARA (G)	INSPECT THE A/C COMPRESSOR MOTOR TO DETERMINE WHETHER P/N FWA1134104-1 OR P/N FWA1134104-5 IS INSTALLED	KICT	MANDATORY	DAYS 28-Feb-2018 HRS 8329.5 LDG 6657		-			Complete
MOC : COMPLIED WITH - ACCOMPLISHED FAA AD2015-17-12 PARAGRAPH (G) INSPECT THE A/C COMPRESSOR MOTOR TO DETERMINE WHETHER P/N FWA1134104-1 OR P/N FWA1134104-5 IS INSTALLED.									



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2015-17-12 PARA (H)	DETERMINE THE HOUR READING ON THE A/C COMPRESSOR HOUR METER (IF, DURING THE INSPECTION REQUIRED BY PARA (G) OF THIS AD, ANY A/C COMPRESSOR MOTOR HAVING P/N FWA1134104-1 OR P/N FWA1134104-5 IS FOUND	KICT	MANDATORY	DAYS 28-Feb-2018 HRS 8329.5 LDG 6657		-			Complete
MOC : COMPLIED WITH - ACCOMPLISHED FAA AD2015-17-12 PARAGRAPH (H) DETERMINE THE HOUR READING ON THE A/C COMPRESSOR HOUR METER (IF, DURING THE INSPECTION REQUIRED BY PARA (G) OF THIS AD, ANY A/C COMPRESSOR MOTOR HAVING P/N FWA1134104-1 OR P/N FWA1134104-5 IS FOUND.									
FAA 2015-17-12 PARA (I)	REPLACE THE A/C COMPRESSOR MOTOR BRUSHES WITH NEW BRUSHES (USING THE HOUR READING ON THE A/C COMPRESSOR HOUR METER DETERMINED IN PARA (H) OF THIS AD)	KICT	MANDATORY	MTH 28-Feb-2018 HRS 8329.5 LDG 6657		-			N/A
MOC : NOT APPLICABLE - ACCOMPLISHED FAA AD2015-17-12 PARAGRAPH (I) REPLACE THE A/C COMPRESSOR MOTOR BRUSHES (USING THE HOUR READING ON THE A/C COMPRESSOR HOUR METER DETERMINED IN PARAGRAPH (H) OF THIS AD. PARA (I) OF THIS AIRWORTHINESS DIRECTIVE IS NOT APPLICABLE.									
FAA 2015-17-12 PARA (K)	DEACTIVATE THE A/C SYSTEM (IN LIEU OF REPLACING THE A/C COMPRESSOR MOTOR BRUSHES AS REQUIRED BY THIS AD)	KICT	MANDATORY	MTH 28-Feb-2018 HRS 8329.5 LDG 6657		-			N/A
MOC : NOT APPLICABLE - ACCOMPLISHED FAA AD2015-17-12, PARA (K) OF THIS AIRWORTHINESS DIRECTIVE IS NOT APPLICABLE.									
FAA 2015-17-12 PARA (L)	IF THE A/C SYSTEM IS DEACTIVATED, AS SPECIFIED IN PARA (K), PRIOR TO THE A/C SYSTEM BEING REACTIVATED: PERFORM THE INSPECTION SPECIFIED IN PARA (H), AND DO THE REPLACEMENTS SPECIFIED IN PARA (I), AT THE TIMES SPECIFIED IN PARA (I). RETURN THE A/C SYSTEM TO SERVICE	KICT	MANDATORY	MTH 28-Feb-2018 HRS 8329.5 LDG 6657		-			N/A
MOC : NOT APPLICABLE - ACCOMPLISHED FAA AD2015-17-12 PARAGRAPH (L), PARA (L) OF THIS AIRWORTHINESS DIRECTIVE IS NOT APPLICABLE.									
FAA 2015-17-12 PARA (M)	SEND THE REMOVED BRUSHES TO CESSNA AIRCRAFT COMPANY	KICT	MANDATORY	DAYS 28-Feb-2018 HRS 8329.5 LDG 6657		-			N/A
MOC : NOT APPLICABLE - ACCOMPLISHED FAA AD2015-17-12 PARAGRAPH (M), PARA (M) OF THIS AIRWORTHINESS DIRECTIVE IS NOT APPLICABLE.									
FAA 2015-17-12	AIR CONDITIONING - INSPECTIONS TO DETERMINE IF CERTAIN A/C COMPRESSOR MOTORS ARE INSTALLED AND TO DETERMINE THE ACCUMULATED HOURS ON CERTAIN A/C COMPRESSOR MOTOR ASSEMBLIES; AND REPETITIVE REPLACEMENT OF THE BRUSHES IN THE A/C COMPRESSOR MOTOR ASSEMBLY, OR, AS AN OPTION TO THE BRUSH REPLACEMENT, DEACTIVATION OF THE A/C SYSTEM AND PLACARD INSTALLATION; AND RETURN OF REPLACED BRUSHES TO CESSNA	KICT	MANDATORY	MTH 28-Feb-2018 HRS 8329.5 LDG 6657		-			Complete
MOC : COMPLIED WITH - ACCOMPLISHED FAA AD2015-17-12, INSPECTIONS TO DETERMINE IF CERTAIN A/C COMPRESSOR MOTORS ARE INSTALLED AND TO DETERMINE THE ACCUMULATED HOURS ON CERTAIN A/C COMPRESSOR MOTOR ASSEMBLIES; AND REPETITIVE REPLACEMENT OF THE BRUSHES IN THE A/C COMPRESSOR MOTOR ASSEMBLY, OR, AS AN OPTION TO BRUSH REPLACEMENT, DEACTIVATION OF THE A/C SYSTEM AND PLACARD INSTALLATION; AND RETURN OF THE REPLACEMENT BRUSHES TO CESSNA.									
FAA 1995-22-01	APPLIANCE AD - TO PREVENT SMOKE, FIRE, ELECTRICAL SHOCK AND POSSIBLE ELECTROMAGNETIC INTERFERENCE CAUSED BY HIGH VOLTAGE ARCING		MANDATORY	MTH 29-Nov-2006 HRS 26 LDG 19			A/R		N/A
MOC : NOT APPLICABLE - AFFECTED PARTS NOT INSTALLED									



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2003-23-02	THIS ACTION REQUIRES DISENGAGING AND TIE-STRAPPING THE PITCH TRIMAND AUTOPILOT SERVO (SERVO 1) CIRCUIT BREAKERS. THIS ACTION ALSO PROVIDES AN OPTIONAL INSPECTION AND FOLLOW-ON ACTIONS THAT, IF ACCOMPLISHED, TERMINATES THE REQUIREMENT TO DISENGAGE AND TIE-STRAP THOSE CIRCUIT BREAKERS								
			MANDATORY	DAYS 29-Nov-2006 HRS 26 LDG 19		A/R			N/A
MOC : NOT APPLICABLE - AFFECTED PARTS NOT INSTALLED									
FAA 1974-08-09 R03	LAVATORY PAPER OR LINEN WASTE RECEPTACLE FIRE PREVENTION	KCMH	MANDATORY	MTH 11-Aug-2017 HRS 8327 LDG 6656		1000		9327	Complete 785.4
MOC : COMPLIED WITH									
FAA 1998-25-10 R01	APPLIANCE AD - TO PREVENT FAILURE OF THE SEAT RESTRAINT SYSTEM DUE TO THE BUCKLE ASSEMBLY (BUCKLE) LOCKING MECHANISM NOT ENGAGING		MANDATORY	MTH 29-Nov-2006 HRS 26 LDG 19		A/R			N/A
MOC : NOT APPLICABLE - AFFECTED PARTS NOT INSTALLED									
FAA 2015-10-02 PARA (G)	GENERAL VISUAL INSPECTION FOR CRACKING OF SEAT BACKREST LINKS HAVING PART NUMBER (P/N) 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2								
	KICT		MANDATORY	MTH 28-Feb-2018 HRS 8329.5 LDG 6657		-			N/A
MOC : NOT APPLICABLE - ACCOMPLISHED FAA AD2015-10-02 PARAGRAPH (G) . THIS AIRWORTHINESS DIRECTIVE IS NOT APPLICABLE DUE TO EQUIPMENT NOT INSTALLED IN AIRCRAFT.									
FAA 2015-10-02 PARA (H)	CORRECTIVE ACTIONS - CRACKING IS FOUND ON THE LINK								
	KICT		MANDATORY	MTH 28-Feb-2018 HRS 8329.5 LDG 6657		-			N/A
MOC : NOT APPLICABLE - ACCOMPLISHED FAA AD2015-10-02 PARAGRAPH (H). THIS AIRWORTHINESS DIRECTIVE IS NOT APPLICABLE DUE TO EQUIPMENT NOT INSTALLED IN AIRCRAFT.									
FAA 2015-10-02 PARA (I)	REPLACE ALL SEAT BACKREST LINKS, HAVING P/N 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2, WITH NEW LINKS								
	KICT		MANDATORY	MTH 28-Feb-2018 HRS 8329.5 LDG 6657		-			N/A
MOC : NOT APPLICABLE - ACCOMPLISHED FAA AD2015-10-02 PARAGRAPH (I). THIS AIRWORTHINESS DIRECTIVE IS NOT APPLICABLE DUE TO EQUIPMENT NOT INSTALLED IN AIRCRAFT.									
FAA 2015-10-02	APPLIANCE AD - EQUIPMENT/FURNISHINGS - ZODIAC SEATS FRANCE - INSPECTION/REPLACEMENT								
	KICT		MANDATORY	MTH 28-Feb-2018 HRS 8329.5 LDG 6657		-			N/A
MOC : NOT APPLICABLE - ACCOMPLISHED FAA AD2015-10-02 APPLIANCE AD-EQUIPMENT / FURNISHINGS-ZODIAC SEATS FRANCE-INSPECTION REPLACEMENT. THIS AIRWORTHINESS DIRECTIVE IS NOT APPLICABLE DUE TO EQUIPMENT NOT INSTALLED IN AIRCRAFT.									
FAA 2017-16-01 PARA (G)	PERFORM GENERAL VISUAL INSPECTIONS OF THE ELT FOR DISCREPANCIES; CHECKS , TESTS AND VERIFICATIONS AS APPLICABLE, TO ENSURE THE ELT IS FUNCTIONING, AND ALL APPLICABLE CORRECTIVE ACTIONS								
	KICT			MTH 18-Oct-2018 HRS 8362.7 LDG 6690		-			N/A
MOC : NOT APPLICABLE									



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2017-16-01 PARA (J)	OPTIONAL TERMINATING ACTION: REPLACE ELT WITH A SERVICEABLE FAA-APPROVED ELT	KICT		MANDATORY	MTH 18-Oct-2018 HRS 8362.7 LDG 6690		-			N/A
MOC : NOT APPLICABLE										
FAA 2017-16-01	APPLIANCE AD - EQUIPMENT / FURNISHINGS - AMERI-KING CORPORATION MODEL AK-450() AND AK-451() SERIES EMERGENCY LOCATOR TRANSMITTERS - REPETITIVE INSPECTIONS, CHECKS, TESTS AND VERIFICATIONS	KICT		MANDATORY	MTH 18-Oct-2018 HRS 8362.7 LDG 6690		-			N/A
MOC : NOT APPLICABLE - ACCOMPLISHED FAA AD 2017-16-01 AMERI-KING CORPORATION MODEL AK-450() AND AK-451() SERIES EMERGENCY LOCATOR TRANSMITTERS - REPETITIVE INSPECTIONS, CHECKS, TESTS AND VERIFICATIONS, EFFECTIVE DATE 10/24/2017. THIS AD AND ALL SUBTASKS ARE NOT APPLICABLE DUE TO THIS ELT IS NOT INSTALLED.										
FAA 2003-26-14	APPLIANCE AD - THIS AD REQUIRES YOU TO REMOVE CERTAIN KIDDE AEROSPACE P/N 898052 HAND-HELD HALON FIRE EXTINGUISHERS FROM SERVICE.			MANDATORY	MTH 29-Nov-2006 HRS 26 LDG 19		A/R			N/A
MOC : NOT APPLICABLE - AFFECTED PARTS NOT INSTALLED										
FAA 2007-11-17 26AD-03	IDENTIFY WIRES FOR FIRE EXTINGUISHING BOTTLES			MANDATORY	DAYS 02-Jul-2007		A/R			Complete
MOC : COMPLIED WITH - AFFECTED PARTS NOT INSTALLED										
FAA 2010-01-03	APPLIANCE AD - IDENTIFY AND REMOVE FROM SERVICE ALL AFFECTED FIRE EXTINGUISHERS AND REPLACE WITH SERVICABLE UNITS			MANDATORY	MTH 29-Nov-2006 HRS 26 LDG 19		A/R			N/A
MOC : NOT APPLICABLE - AFFECTED PARTS NOT INSTALLED										
FAA 2010-04-16 PARA (G) 26AD-07	REPLACE TYPE H1-10 AIR HALON 1211 (BCF) PORTABLE FIRE EXTINGUISHERS MANUFACTURED BY SICLI WITH SERVICABLE UNIT			MANDATORY	DAYS 29-Nov-2006 HRS 26 LDG 19		A/R			N/A
MOC : NOT APPLICABLE - AFFECTED PARTS NOT INSTALLED										
FAA 2010-04-16 PARA (H)	RETURN TYPE H1-10 AIR HALON 1211 (BCF) PORTABLE FIRE EXTINGUISHERS MANUFACTURED BY SICLI THE AFFECTED FIRE EXTINGUISHER TO MANUFACTURER			MANDATORY	DAYS 29-Nov-2006 HRS 26 LDG 19		A/R			N/A
MOC : NOT APPLICABLE - AFFECTED PARTS NOT INSTALLED										
FAA 2010-04-16 26AD-07	APPLIANCE AD - TYPE H1-10 AIR HALON 1211 (BCF) PORTABLE FIRE EXTINGUISHERS MANUFACTURED BY SICLI			MANDATORY	DAYS 29-Nov-2006 HRS 26 LDG 19		A/R			N/A
MOC : NOT APPLICABLE - AFFECTED PARTS NOT INSTALLED										
FAA 1990-06-13	APPLIANCE AD - TO PREVENT ERRONEOUS ATTITUDE DISPLAY			MANDATORY	MTH 29-Nov-2006 HRS 26 LDG 19		A/R			N/A
MOC : NOT APPLICABLE - AFFECTED PARTS NOT INSTALLED										
FAA 1999-01-14	APPLIANCE AD - TO PREVENT A "RANDOM RESET" CONDITION OF THE ELECTRONIC FLIGHT INSTRUMENT SYSTEM			MANDATORY	MTH 29-Nov-2006 HRS 26 LDG 19		A/R			N/A
MOC : NOT APPLICABLE - AFFECTED PARTS NOT INSTALLED										



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2007-23-13	INSPECT - ADJUSTMENT OF STALL WARNING SYSTEM (SUPERSEDED BY FAA 2008-26-04)			SUPERSEDED	MTH 29-Nov-2006 HRS 26 LDG 19		A/R			N/A
MOC : NOT APPLICABLE - AFFECTED PARTS NOT INSTALLED										
FAA 2008-26-04 AFM	REMOVE AND DISCARD INSTALL WARNING PLACARDS, PERFORM FUNCTIONAL TEST OF ANGLE OF ATTACK SYSTEM AND ADJUST CALIBRATION SETTINGS OF AOA SYSTEM AS REQUIRED. AFM WARNING STATEMENT REGARDING STICK SHAKER			AIRWORTHINESS	DAYS 29-Nov-2006 HRS 26 LDG 19		-			N/A
MOC : NOT APPLICABLE - AFFECTED PARTS NOT INSTALLED										
FAA 2008-26-04 TEST	PERFORM CHECK INSTALL WARNING PLACARDS, PERFORM FUNCTIONAL TEST OF ANGLE OF ATTACK SYSTEM AND ADJUST CALIBRATION SETTINGS OF AOA SYSTEM AS REQUIRED. ANGLE OF ATTACK SYSTEM			AIRWORTHINESS	MTH 29-Nov-2006 HRS 26 LDG 19		-			N/A
MOC : NOT APPLICABLE - AFFECTED PARTS NOT INSTALLED										
FAA 2008-26-04	INSTALL WARNING PLACARDS, PERFORM FUNCTIONAL TEST OF ANGLE OF ATTACK SYSTEM AND ADJUST CALIBRATION SETTINGS OF AOA SYSTEM AS REQUIRED.			AIRWORTHINESS	MTH 29-Nov-2006 HRS 26 LDG 19		A/R			N/A
MOC : NOT APPLICABLE - AFFECTED PARTS NOT INSTALLED										
FAA 1990-07-08	APPLIANCE AD - TO PREVENT SMOKE, FIRE, AND POSSIBLE ELECTRICAL SHOCK, OR ELECTROMAGNETIC INTERERENCE			SUPERSEDED	MTH 29-Nov-2006 HRS 26 LDG 19		A/R			N/A
MOC : NOT APPLICABLE - AFFECTED PARTS NOT INSTALLED										
FAA 1994-01-04	APPLIANCE AD - TO PREVENT COLLISIONS OR NEAR MISSES			MANDATORY	MTH 29-Nov-2006 HRS 26 LDG 19		A/R			N/A
MOC : NOT APPLICABLE - AFFECTED PARTS NOT INSTALLED										
FAA 1994-01-05	APPLIANCE AD - TO PREVENT COLLISIONS OR NEAR MISSES			MANDATORY	MTH 29-Nov-2006 HRS 26 LDG 19		A/R			N/A
MOC : NOT APPLICABLE - AFFECTED PARTS NOT INSTALLED										
FAA 1994-01-06	APPLIANCE AD - TO PREVENT COLLISIONS OR NEAR MISSES			MANDATORY	MTH 29-Nov-2006 HRS 26 LDG 19		A/R			N/A
MOC : NOT APPLICABLE - AFFECTED PARTS NOT INSTALLED										
FAA 1995-26-15 R01	APPLIANCE AD - ENSURE THAT THE FLIGHTCREW IS ADVISED OF THE POTENTIAL HAZARD ASSOCIATED WITH FAILURE OF THE AUDIO OUTPUT OF THE CAS-81 TCAS			MANDATORY	MTH 29-Nov-2006 HRS 26 LDG 19		A/R			N/A
MOC : NOT APPLICABLE - AFFECTED PARTS NOT INSTALLED										



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 1997-05-03 R01 <i>34AD-07 : 560R1</i>	APPLIANCE AD - TO PREVENT DEVIATION FROM AN INTENDED FLIGHT PATH CAUSED BY INACCURATE INFORMATION FROM THE GPS			MANDATORY	MTH 29-Nov-2006 HRS 26 LDG 19		A/R			N/A
MOC : NOT APPLICABLE - AFFECTED PARTS NOT INSTALLED										
FAA 1998-25-02	APPLIANCE AD - TO PREVENT THE DISPLAY OF TARGET INDICATORS ON THE WRONG SIDE OF THE AIRCRAFT CAUSED BY AN INTERNAL COMPONENT FAILURE IN THE SKY497 INSTALLATIONS			MANDATORY	MTH 29-Nov-2006 HRS 26 LDG 19		A/R			N/A
MOC : NOT APPLICABLE - AFFECTED PARTS NOT INSTALLED										
FAA 2001-23-17 <i>34AD-10</i>	APPLIANCE AD - TO PREVENT INACCURATE COURSE DEVIATION DISPLAYS IN THE GNS 430 UNIT			MANDATORY	MTH 29-Nov-2006 HRS 26 LDG 19		A/R			N/A
MOC : NOT APPLICABLE - AFFECTED PARTS NOT INSTALLED										
FAA 2002-06-06	APPLIANCE AD - ROCKWELL COLLINS TDR-94 AND TDR-94D MODE S TRANSPONDERS			MANDATORY	MTH 29-Nov-2006 HRS 26 LDG 19		A/R			N/A
MOC : NOT APPLICABLE - AFFECTED PARTS NOT INSTALLED										
FAA 2002-13-07	APPLIANCE AD - INSPECT THE AFFECTED IRU'S FOR PROPER FUNCTION AND REMOVE THE IRU EITHER IMMEDIATELY OR AT A CERTAIN TIME DEPENDING ON THE RESULT OF THE INSPECTION			MANDATORY	MTH 29-Nov-2006 HRS 26 LDG 19		A/R			N/A
MOC : NOT APPLICABLE - AFFECTED PARTS NOT INSTALLED										
FAA 2002-14-19	APPLIANCE AD - REMOVE ANY AFFECTED ADC FROM THE AIRPLANE AND, AS APPLICABLE, REPLACE OR REPROGRAM PARTS OR CIRCUIT CARD ASSEMBLIES ON CENTRAL PROCESSING UNIT (CPU) CIRCUIT CARDS			MANDATORY	MTH 29-Nov-2006 HRS 26 LDG 19		A/R			N/A
MOC : NOT APPLICABLE - AFFECTED PARTS NOT INSTALLED										
FAA 2003-04-06 <i>34AD-13</i>	APPLIANCE AD - HONEYWELL PRIMUS RNZ-850/851 NM (SUPERSEDED BY FAA 2006-22-05)			SUPERSEDED	MTH 29-Nov-2006 HRS 26 LDG 19		A/R			N/A
MOC : NOT APPLICABLE - AFFECTED PARTS NOT INSTALLED										
FAA 2003-13-08	APPLIANCE AD - THIS AD REQUIRES YOU TO INSPECT THE TAWS8000 TAWS INSTALLATION AND REMOVE ANY TAWS WHERE BOTH THE TAWS AND ANY OTHER DEVICE ARE CONNECTED TO THE SAME BARO SET POTENTIOMETER. THIS AD ALSO PROHIBITS FUTURE INSTALLATION OF ANY TAWS8000 TAWS THAT INCORPORATES HARDWARE "MOD NONE", "MOD A", OR "MOD B"			MANDATORY	MTH 29-Nov-2006 HRS 26 LDG 19		A/R			N/A
MOC : NOT APPLICABLE - AFFECTED PARTS NOT INSTALLED										
FAA 2006-16-18 R01	APPLIANCE AD - SANDEL ST3400 TAWS/RMI PLACARD			AIRWORTHINESS	MTH 29-Nov-2006 HRS 26 LDG 19		A/R			N/A
MOC : NOT APPLICABLE - AFFECTED PARTS NOT INSTALLED										



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2006-22-05 <i>34AD-18</i>	APPLIANCE AD - HONEYWELL PRIMUS RNZ-850/851 NM (SUPERSEDED BY FAA 2010-07-02)		MANDATORY	MTH 26-Dec-2006 HRS 89.1 LDG 72		A/R			N/A
MOC : NOT APPLICABLE - PN NOT INSTALLED									
FAA 2007-07-12	APPLIANCE AD - THIS AD IS ISSUED TO PREVENT A SHIFT IN THE FMS COMPUTED POSITION, WHICH COULD RESULT IN UNCOMMANDED DEVIATIONS FROM THE INTENDED FLIGHT PATH OF THE AIRPLANE.		MANDATORY	DAYS 20-Apr-2007 HRS 418.8 LDG 308		A/R			N/A
MOC : NOT APPLICABLE - PN NOT INSTALLED									
FAA 2009-08-01	APPLIANCE AD - THIS AD IS ISSUED TO PREVENT A SHIFT IN THE FMS COMPUTED POSITION AND TO UPGRADE SOFTWARE TO TERMINATE THE REQUIREMENTS OF AD 2007-07-12		MANDATORY	MTH 29-Nov-2006 HRS 26 LDG 19		A/R			N/A
MOC : NOT APPLICABLE - AFFECTED PARTS NOT INSTALLED									
FAA 2010-07-02	APPLIANCE AD - PERFORM A ONE-TIME GENERAL VISUAL INSPECTION OF THE MODIFICATION PLATE FOR THE HONEYWELL PRIMUS II NV-850 NAVIGATION RECEIVER MODULE (NRM)	LUK	MANDATORY	MTH 18-Oct-2010 HRS 2993.9 LDG 2384		A/R			Complete
MOC : COMPLIED WITH - COMPLIED WITH AIRWORTHINESS DIRECTIVE 2010-07-02, HONEYWELL NAV UNITS MOD STATUS. FOUND INSTALLED UNITS AS FOLLOWS									
FAA 2012-02-08	APPLIANCE AD - AVIATION COMMUNICATION AND SURVEILLANCE SYSTEMS (ACSS) TRAFFICALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) UNITS	KICT	MANDATORY	MTH 28-Feb-2018 HRS 8329.5 LDG 6657		-			N/A
MOC : NOT APPLICABLE - ACCOMPLISHED FAA AD2012-02-08 AVIATION COMMUNICATION AND SURVEILLANCE SYSTEMS(ACSS) TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM(TCAS) SYSTEM UNIT. THIS AIRWORTHINESS DIRECTIVE IS NOT APPLICABLE DUE TO THE SYSTEM AFFECTED IS NOT INSTALLED IN THE AIRCRAFT.									
FAA 2014-18-01	APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS - INSPECTION / MODIFICATION	KICT	MANDATORY	MTH 28-Feb-2018 HRS 8329.5 LDG 6657		-			N/A
MOC : NOT APPLICABLE - ACCOMPLISHED FAA AD2014-18-01 NAVIGATION, ROCKWELL COLLINS, INC. MODE S TRANSPONDERS, INSPECTION / MODIFICATION. THIS AIRWORTHINESS DIRECTIVE IS NOT APPLICABLE DUE TO EQUIPMENT NOT INSTALLED IN THE AIRCRAFT.									
FAA 2015-10-51-E	APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS.	KICT	MANDATORY	MTH 28-Feb-2018 HRS 8329.5 LDG 6657		-			N/A
MOC : NOT APPLICABLE - ACCOMPLISHED FAA AD2015-10-51_E AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD) INCORPORATE OPERATIONAL LIMITATIONS SECTION OF AFM OR AFMS. THIS AIRWORTHINESS DIRECTIVE IS NOT APPLICABLE DUE TO EQUIPMENT NOT INSTALLED IN THE AIRCRAFT.									
FAA 2015-10-51	APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS	KICT	MANDATORY	MTH 28-Feb-2018 HRS 8329.5 LDG 6657		-			N/A
MOC : NOT APPLICABLE - ACCOMPLISHED FAA AS2015-10-51 AVIDYNE INTREGRATED FLIGHT DISPLAY (IFD) INCORPORATE OPERATIONAL LIMITATIONS SECTION OF AFM OR AFMS. THIS AIRWORTHINESS DIRECTIVE IS NOT APPLICABLE DUE TO EQUIPMENT NOT INSTALL IN THE AIRCRAFT.									



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 1991-10-05	APPLIANCE AD - TO PREVENT MALFUNCTIONING OF THE LANYARD RELEASE PIN			MANDATORY	MTH 29-Nov-2006 HRS 26 LDG 19		A/R			N/A
MOC : NOT APPLICABLE - AFFECTED PARTS NOT INSTALLED										
FAA 1994-19-06	APPLIANCE AD - TO PREVENT THE FLIGHT CREW FROM EXPERIENCING DIFFICULTY IN EXHALING			MANDATORY	MTH 29-Nov-2006 HRS 26 LDG 19		A/R			N/A
MOC : NOT APPLICABLE - AFFECTED PARTS NOT INSTALLED										
FAA 2009-21-10 R01	APPLIANCE AD - INSPECT TO DETERMINE THE SERIAL NUMBER OF THE OXYGEN CYLINDER ASSEMBLIES INSTALLED IN THE AIRPLANE			MANDATORY	DAYS 29-Nov-2006 HRS 26 LDG 19		A/R			N/A
MOC : NOT APPLICABLE - AFFECTED PARTS NOT INSTALLED										
FAA 2010-11-05	APPLIANCE AD - INSPECT FOR AND REMOVE SUBSTANDARD OXYGEN CYLINDERS FROM AIRPLANE			MANDATORY	DAYS 29-Nov-2006 HRS 26 LDG 19		A/R			N/A
MOC : NOT APPLICABLE - AFFECTED PARTS NOT INSTALLED										
FAA 2011-01-09	APPLIANCE AD - B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE) PART NUMBER 119003-11 INSTALLED ON VARIOUS TRANSPORT AIRPLANES			MANDATORY	MTH 29-Nov-2006 HRS 26 LDG 19		-			N/A
MOC : NOT APPLICABLE - AFFECTED PARTS NOT INSTALLED										
FAA 2011-14-08	APPLIANCE AD - B/E AEROSPACE CONTINUOUS FLOW PASSENGER OXYGEN MASK ASSEMBLY			MANDATORY	MTH 29-Nov-2006 HRS 26 LDG 19		A/R			N/A
MOC : NOT APPLICABLE - AFFECTED PARTS NOT INSTALLED										
FAA 2015-08-07 PARA (G)	INSPECT THE INFLATABLE HARNESS FITTED TO EACH FLIGHTCREW OXYGEN MASK REGULATOR TO DETERMINE IF THE INFLATABLE HARNESS IS INSTALLED WITH A PART NUMBER AND A BATCH NUMBER IDENTIFIED IN APPENDIX I OF ZODIAC AEROSPACE SERVICE BULLETIN MXH-35-240, REVISION 7, DATED SEPTEMBER 1, 2011			KICT	MANDATORY	MTH 28-Feb-2018 HRS 8329.5 LDG 6657		-		N/A
MOC : NOT APPLICABLE - ACCOMPLISHED FAA 2015-08-07 PARAGRAPH (G) INSPECT THE INFLATABLE HARNESS FITTED TO EACH FLIGHT CREW OXYGEN MASK REGULATOR TO DETERMINE IF THE INFLATABLE HARNESS IS INSTALLED WITH A PART NUMBER AND BATCH NUMBER IDENTIFIED IN APPENDIX I OF ZODIAC AEROSPACE SERVICE BULLETIN MXH-35-240, REVISION 7, DATE SEPTEMBER 1, 2011. THIS AIRWORTHINESS DIRECTIVE IS NOT APPLICABLE DUE TO AFFECTED EQUIPMENT SERIAL NUMBER NOT INSTALLED.										
FAA 2015-08-07 PARA (H)	REPLACE THE INFLATABLE HARNESS IDENTIFIED IN PAPERGRAPH G WITH A NEW OR RE-IDENTIFIED HARNESSSES			KICT	MANDATORY	MTH 28-Feb-2018 HRS 8329.5 LDG 6657		-		N/A
MOC : NOT APPLICABLE - ACCOMPLISHED FAA AD2015-08-07 PARAGRAPH (H) REPLACE THE INFLATABLE HARNESS IDENTIFIED IN PARAGRAPH G WITH A NEW OF RE-IDENTIFIED HARNESS. THIS AIRWORTHINESS DIRECTIVE IS NOT APPLICABLE DUE TO AFFECTED EQUIPMENT SERIAL NUMBER NOT INSTALLED IN AIRCRAFT.										



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2015-08-07	APPLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHTCREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF INFLATABLE HARNESES	KICT	MANDATORY	MTH 28-Feb-2018 HRS 8329.5 LDG 6657		-			N/A
MOC : NOT APPLICABLE - ACCOMPLISHED FAA AD2015-08-07, APPLIANCE AD, OXYGEN, ZODIAC AEROTECHNICS(FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHT CREW OXYGEN MASK REGULATORS, INSPECTION / REPLACEMENT OF INFLATABLE HARNESS. THIS AIRWORTHINESS DIRECTIVE IN NOT APPLICABLE DUE TO AFFECTED EQUIPMENT SERIAL NUMBER IS NOT INSTALLED IN THE AIRCRAFT.									
FAA 2015-23-09 PARA (G)	INSPECT EACH FLIGHTCREW OXYGEN MASK REGULATOR TO IDENTIFY THE PART NUMBER AND SERIAL NUMBER	KICT	MANDATORY	DAYS 28-Feb-2018 HRS 8329.5 LDG 6657		-			N/A
MOC : NOT APPLICABLE - ACCOMPLISHED FAA AD2015-23-09 PARAGRAPH (G), INSPECT EACH FLIGHT CREW OXYGEN MASK REGULATOR TO IDENTIFY THE PART NUMBER AND SERIAL NUMBER. THIS AIRWORTHINESS DIRECTIVE IS NOT APPLICABLE DUE TO EQUIPMENT NOT INSTALLED.									
FAA 2015-23-09 PARA (H.1)	REPLACE EACH AFFECTED FLIGHTCREW OXYGEN MASK WITH A PART IDENTIFIED IN PARAGRAPH (H)(1)(I) OR (H)(1)(II).	KICT	MANDATORY	DAYS 28-Feb-2018 HRS 8329.5 LDG 6657		-			N/A
MOC : NOT APPLICABLE - ACCOMPLISHED FAA AD2015-23-09 PARAGRAPH (H)(I), REPLACE EACH AFFECTED FLIGHT CREW MASK WITH A PART IDENTIFIED IN PARAGRAPH(H)(1)(I) OR (H)(1)(II). THIS AIRWORTHINESS DIRECTIVE IS NOT APPLICABLE DUE TO EQUIPMENT NOT INSTALLED.									
FAA 2015-23-09 PARA (H.2.I)	REVISE THE EMERGENCY PROCEDURES SECTION OF THE AIRPLANE FLIGHT MANUAL (AFM) BY INSERTING THE STATEMENT PROVIDED IN FIGURE 1	KICT	MANDATORY	DAYS 28-Feb-2018 HRS 8329.5 LDG 6657		-			N/A
MOC : NOT APPLICABLE - ACCOMPLISHED FAA AD2015-23-09 PARAGRAPH (H)(2)(I), REVISE THE EMERGENCY PROCEDURES SECTION OF THE AIRPLANE FLIGHT MANUAL (AFM) BY INSERTING THE STATEMENT PROVIDED IN FIGURE 1. THIS AIRWORTHINESS DIRECTIVE IS NOT APPLICABLE DUE TO EQUIPMENT NOT INSTALLED.									
FAA 2015-23-09 PARA (H.2.II)	FABRICATE AND INSTALL A PLACARD ON THE FLIGHTCREW OXYGEN MASK CONTAINER THAT STATES: "USE SELECTOR ON 100% OR EMERGENCY ONLY."	KICT	MANDATORY	DAYS 28-Feb-2018 HRS 8329.5 LDG 6657		-			N/A
MOC : NOT APPLICABLE - ACCOMPLISHED FAA AD2015-23-09 PARAGRAPH (H)(2)(II), FABRICATE AND INSTALL A PLACARD ON THE FLIGHT CREW OXYGEN MASK CONTAINER THAT STATES : "USE SELECTOR ON 100% OR EMERGENCY ONLY". THIS AIRWORTHINESS DIRECTIVE IS NOT APPLICABLE DUE TO EQUIPMENT NOT INSTALLED.									
FAA 2015-23-09 PARA (I)	REGULATOR REPLACEMENT	KICT	MANDATORY	MTH 28-Feb-2018 HRS 8329.5 LDG 6657		-			N/A
MOC : NOT APPLICABLE - ACCOMPLISHED FAA AD2015-23-09 PARAGRAPH (I) REGULATOR REPLACEMENT. THIS AIRWORTHINESS DIRECTIVE IS NOT APPLICABLE DUE TO EQUIPMENT NOT INSTALLED.									
FAA 2015-23-09	APPLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHT CREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF OXYGEN MASK REGULATORS	KICT	MANDATORY	MTH 28-Feb-2018 HRS 8329.5 LDG 6657		-			N/A
MOC : NOT APPLICABLE - ACCOMPLISHED FAA AD2015-23-09, APPLIANCE AD, OXYGEN, ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FIGHT CREW OXYGEN MASK REGULATORS, INSPECTION / REPLACEMENT OF OXYGEN MASK REGULATORS. THIS AIRWORTHINESS DIRECTIVE IS NOT APPLICABLE, EQUIPMENT NOT INSTALLED.									



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2016-11-20 PARA (G)	PHYSICALLY INSPECT THE PBE POUCH TO DETERMINE IF IT HAS AN INTACT VACUUM SEAL IN ACCORDANCE WITH B/E AEROSPACE SERVICE BULLETIN NO. 119003-35-011, REV .000, DATED FEBRUARY 4, 2015, PARA III.A.1 SUPERSEDED BY FAA AD 2017-18-12		MANDATORY MTH			-			
MOC :									
FAA 2016-11-20 PARA (H.1)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, THAT DOES NOT HAVE AN INTACT VACUUM SEAL. SUPERSEDED BY FAA AD 2017-18-12		MANDATORY			-			
MOC :									
FAA 2016-11-20 PARA (H.2)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, WHERE THE VACUUM SEAL IS INTACT. SUPERSEDED BY FAA AD 2017-18-12		MANDATORY MTH			-			
MOC :									
FAA 2016-11-20	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 THAT ARE INSTALLED ON AIRPLANES. SUPERSEDED BY FAA AD 2017-18-12		MANDATORY			-			
MOC :									
FAA 2017-18-12 PARA (G)	INSPECTION RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED	KICT	MANDATORY MTH	28-Feb-2018		-			N/A
HRS 8329.5 LDG 6657									
MOC : NOT APPLICABLE - ACCOMPLISHED FAA AD2017-18-12 PARAGRAPH (G). THIS AIRWORTHINESS DIRECTIVE IS NOT APPLICABLE DUE TO EQUIPMENT NOT INSTALLED IN THE AIRCRAFT.									
FAA 2017-18-12 PARA (H)	REPLACEMENT RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED	KICT	MANDATORY MTH	28-Feb-2018		-			N/A
HRS 8329.5 LDG 6657									
MOC : NOT APPLICABLE - ACCOMPLISHED FAA AD2017-18-12 PARAGRAPH (H). THIS AIRWORTHINESS DIRECTIVE IS NOT APPLICABLE DUE TO EQUIPMENT NOT INSTALLED IN THE AIRCRAFT.									
FAA 2017-18-12 PARA (I) & (J)	INSPECT TO DETERMINE IF THE S/N OF THE INSTALLED PBE, P/N 119003-21, IS WITHIN THE RANGE OF 004-14768M THROUGH 004-21093M OR 004-02393M THROUGH 004-03033M AND IF FOUND WITHIN THE S/N RANGE REPLACE IT.	KICT	MANDATORY MTH	28-Feb-2018		-			N/A
HRS 8329.5 LDG 6657									
MOC : NOT APPLICABLE - ACCOMPLISHED FAA AD2017-18-12 PARAGRAPH (I) AND (J). THIS AIRWORTHINESS DIRECTIVE IS NOT APPLICABLE DUE TO EQUIPMENT NOT INSTALLED IN THE AIRCRAFT.									
FAA 2017-18-12	OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 AND 119003-21 THAT ARE INSTALLED ON AIRPLANES	KICT	MANDATORY MTH	28-Feb-2018		-			N/A
HRS 8329.5 LDG 6657									
MOC : NOT APPLICABLE - ACCOMPLISHED FAA AD2017-18-12. THIS AIRWORTHINESS DIRECTIVE IS NOT APPLICABLE DUE TO EQUIPMENT NOT INSTALLED IN THE AIRCRAFT.									
FAA 2006-08-13 E1	TO PREVENT LACK OF ENGINE RESPONSE TO POWER LEVER INPUT	UNK	MANDATORY MTH	31-Dec-2017		-			Complete
HRS 8329.5 LDG 6657									
MOC : COMPLIED WITH									
FAA 2006-08-13 E2	TO PREVENT LACK OF ENGINE RESPONSE TO POWER LEVER INPUT	UNK	MANDATORY MTH	24-Dec-2017		-			Complete
HRS 8329.5 LDG 6657									
MOC : COMPLIED WITH									



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
AD 73-04	HFC RATIO UNIT SETSCREW ICT			MTH 19-Oct-2006 HRS 17		-			N/A
MOC : NOT APPLICABLE									
FAA 2003-03-21 LEFT ENGINE 73AD-03 : E1**L	THIS ACTION REQUIRES A ONE-TIME VISUAL INSPECTION AND RE-MARKING, OR IN LIEU OF INSPECTION, REPLACEMENT OF CERTAIN PART NUMBERS (P/N'S) OF THE FLEXIBLE FUEL TUBE LOCATED BETWEEN THE FUEL/OIL HEAT EXCHANGER AND THE INTEGRAL FUEL CONTROL UNIT-FUEL PUMP	ICT	MANDATORY	MTH 19-Oct-2006 HRS 17		A/R			Complete
MOC : COMPLIED WITH									
FAA 2003-03-21 RIGHT ENGINE 73AD-03 : E2**R	THIS ACTION REQUIRES A ONE-TIME VISUAL INSPECTION AND RE-MARKING, OR IN LIEU OF INSPECTION, REPLACEMENT OF CERTAIN PART NUMBERS (P/N'S) OF THE FLEXIBLE FUEL TUBE LOCATED BETWEEN THE FUEL/OIL HEAT EXCHANGER AND THE INTEGRAL FUEL CONTROL UNIT-FUEL PUMP		MANDATORY	MTH 17-Nov-2008 HRS 2910.2 LDG 2329		A/R			Complete
MOC : COMPLIED WITH									
FAA 2003-03-21 E1	ENGINE FUEL AND CONTROL - ONE-TIME VISUAL INSPECTION AND RE-MARKING, OR IN LIEU OF INSPECTION, REPLACEMENT OF CERTAIN PART NUMBERS (P/N'S) OF THE FLEXIBLE FUEL TUBE LOCATED BETWEEN THE FUEL/OIL HEAT EXCHANGER AND THE INTEGRAL FUEL CONTROL UNIT-FUEL PUMP	UNK	MANDATORY	MTH 31-Dec-2017 HRS 8329.5 LDG 6657		-			Complete
MOC : COMPLIED WITH									
FAA 2003-03-21 E2	ENGINE FUEL AND CONTROL - ONE-TIME VISUAL INSPECTION AND RE-MARKING, OR IN LIEU OF INSPECTION, REPLACEMENT OF CERTAIN PART NUMBERS (P/N'S) OF THE FLEXIBLE FUEL TUBE LOCATED BETWEEN THE FUEL/OIL HEAT EXCHANGER AND THE INTEGRAL FUEL CONTROL UNIT-FUEL PUMP	UNK	MANDATORY	MTH 24-Dec-2017 HRS 8329.5 LDG 6657		-			Complete
MOC : COMPLIED WITH									
FAA 2006-24-08 E1 73AD-05 : E1**L	ENGINE FUEL AND CONTROL - REPLACE FUEL MANIFOLD P/N 3052627-01	UNK	MANDATORY	DAYS 31-Dec-2017 HRS 8329.5 LDG 6657		-			Complete
MOC : COMPLIED WITH									
FAA 2006-24-08 E2 73AD-05 : E2**R	ENGINE FUEL AND CONTROL - REPLACE FUEL MANIFOLD P/N 3052627-01	UNK	MANDATORY	DAYS 24-Dec-2017 HRS 8329.5 LDG 6657		-			Complete
MOC : COMPLIED WITH									
TCCA CF-2002-42 E1	PRATT & WHITNEY CANADA (P&WC) PW530A, PW535A AND PW545A ENGINES - INSPECTION OF FLEXIBLE FUEL TUBES	UNK	MANDATORY	MTH 31-Dec-2017 HRS 8329.5 LDG 6657		-			Complete
MOC : COMPLIED WITH									
TCCA CF-2002-42 E2	PRATT & WHITNEY CANADA (P&WC) PW530A, PW535A AND PW545A ENGINES - INSPECTION OF FLEXIBLE FUEL TUBES	UNK	MANDATORY	MTH 24-Dec-2017 HRS 8329.5 LDG 6657		-			Complete
MOC : COMPLIED WITH									



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
TCCA CF-2004-28 E1	PRATT & WHITNEY CANADA PW535A ENGINES - HFC RATIO UNIT	UNK	MANDATORY	SETSCREW ADJUST MTH 31-Dec-2017 HRS 8329.5 LDG 6657		A/R			Complete
MOC : COMPLIED WITH									
TCCA CF-2004-28 E2	PRATT & WHITNEY CANADA PW535A ENGINES - HFC RATIO UNIT	UNK	MANDATORY	SETSCREW ADJUST MTH 24-Dec-2017 HRS 8329.5 LDG 6657		A/R			Complete
MOC : COMPLIED WITH									
TCCA CF-2006-22 E1	FUEL MANIFOLD LEAKAGE - REPLACE FUEL MANIFOLD	UNK	MANDATORY	MTH 31-Dec-2017 HRS 8329.5 LDG 6657		-			Complete
MOC : COMPLIED WITH									
TCCA CF-2006-22 E2	FUEL MANIFOLD LEAKAGE - REPLACE FUEL MANIFOLD	UNK	MANDATORY	MTH 24-Dec-2017 HRS 8329.5 LDG 6657		-			Complete
MOC : COMPLIED WITH									
FAA 1993-05-15	THRUST REVERSERS		MANDATORY	MTH 29-Nov-2006 HRS 26 LDG 19		-			N/A
MOC : NOT APPLICABLE - AFFECTED PARTS NOT INSTALLED									



CESCOM 10 - Aircraft Status Report

Owner: **ETG AVIATION LLC**
 Aircraft Model: **560 - CITATION ENCORE**
 Aircraft Serial: **560-0706**
 Unit: **0706** Reg No: **N777HW**
 Airworthiness: **19-Oct-2006**
 Print Date: **09-Dec-2019 11:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8541.6	6818	07-Nov-2019	.37
ENG 1	10089.2	8015	07-Nov-2019	.37
ENG 2	10086.5	8004	07-Nov-2019	.37
AIR COND	3111		07-Nov-2019	.9

Factory Installed

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
23FO-04 560/N <i>23FO-04 : 560/N</i>	HF KHF-950 FACTORY OPTION	*CF		631N FO	MTH 19-Oct-2006		-			
23FO-06 XL/M <i>23FO-06 : XL/M</i>	MAGNASTAR AIRBORNE TELEPHONE FACTORY OPTION	*CF		674M FO	MTH 19-Oct-2006		-			
25FO-07 560 <i>25FO-07 : 560</i>	EXTENDED BAGGAGE TUBE FACTORY OPTION	*CF		132B FO	MTH 19-Oct-2006		-			
34FO-05 560/E <i>34FO-05 : 560/E</i>	ADF-2 ONLY W/HONEYWELL PRIMUS II FACTORY OPTION	*CF		659E FO	MTH 19-Oct-2006		-			
34FO-06 560 <i>34FO-06 : 560</i>	AIRBORN FLT INFO SYS (GLOGAL AFIS) FACTORY OPTION	*CF		695 FO	MTH 19-Oct-2006		-			
34FO-08 560/F <i>34FO-08 : 560/F</i>	TCAS II-CAS-67A FACTORY OPTION	*CF		635F FO	MTH 19-Oct-2006		-			
34FO-15 560/B <i>34FO-15 : 560/B</i>	EGPWS-WINDSHEAR COMPUTER FACTORY OPTION	*CF		691B FO	MTH 19-Oct-2006		-			